

3-21-24

552(B)(6)

National Highway
Traffic Safety Admin.

Attn: Administrator

I received a Safety Recall
on my Ford - 2019. EcoSport
Safety Recall 23V905.

Issue:

It may be possible for the
engine oil pump drive belt
tensioner arm to fracture,
separate from the tensioner
bracketing plate, and/or
the oil pump drive belt
material may degrade and
lose teeth, resulting in a loss
of engine oil pressure.

2

I can't believe this company could be so negligent about my safety, as well as others. A complaint against Ford was filed on March 15, 2024.

Office defects investigation #1577541



I have no computer to check any instructions or status, so this lack of compliance is overwhelming.

I want this fixed now!! before something happens. Waiting until the fall is crazy; to live with this fear is unacceptable.

If this car seizes up
or worse, what am I
to do?

I expect some sort of
compliance from a
company that should
know better.

Sincerely,





Port Jefferson Station, NY

MID-ISLAND NY 117

22 MAR 2024 PM 6 L

2/22/24

National Highway Traffic
Safety Administration
1200 New Gray Ave. S.E.
Washington, D.C. 20590

Att: Administration

20590-