

Dec. 3, 2025

National Highway  
Traffic Safety Administration

11/10/25

Ref: [REDACTED]

11/24/25 2022 Kia Soul LX

VIN: [REDACTED]

miles 51689

invoice no. [REDACTED]

Ph: [REDACTED]

Problem Fixed  
Engine Light

cause: p0017, p0014 active found <sup>viewing</sup> ~~viewing~~  
live data exhaust timing was not  
reading in spec. removed valve cover  
found cam is moving separate from  
gear, due to sheared dowel pin

Correction: removed and replaced exhaust  
cam and cvt assembly.

recall B & C

warranty

[REDACTED]

22

JACKSONVILLE RPDC 320

5 DEC 2025 PM 4 L

1775 \* 2025



National Highway Traffic Safety  
Administration  
1200 New Jersey Avenue  
Washington, DC 20590  
S.E.

NEF



