

18,984

VEHICLE OWNER'S QUESTIONNAIRE

FOR AGENCY USE ONLY

DATE RECEIVED
 od.or _____
 rt.dt _____
 od.rt _____
 up.ltr _____

OWNER INFORMATION (TYPE OR PRINT)

NAME & ADDRESS



REFERENCE NO.

609172

DAY TIME TELEPHONE NO. (AREA CODE)

Do you authorize NHTSA to provide a copy of this report to the manufacturer of your vehicle? YES NO
 In the absence of an authorization, NHTSA WILL NOT provide your name or address to the vehicle manufacturer.

SIGNATURE OF OWNER _____ DATE 12/23/98

VEHICLE INFORMATION

VEHICLE IDENTIFICATION NO. 4S2CK58W0W4369895 VEHICLE MAKE ISUZU VEHICLE MODEL Rodeo LS MODEL YEAR 1998

LOCATED AT BOTTOM OF WINDSHIELD ON DRIVER'S SIDE

CURRENT ODOMETER READING: 4323 DATE PURCHASED 8/8/98 DEALER'S NAME, CITY, & STATE Don Kott Carson, CA ENGINE SIZE (CID/CO/L) 3.165 TURBO DIESEL GAS FUEL INJECTION
 NEW USED NO. CYLINDERS 6

TRANSMISSION TYPE: MANUAL AUTOMATIC
 ANTILOCK BRAKES: YES NO
 RESTRAINT SYSTEM: DRIVER SIDE AIRBAG MOTOR BELT PASSENGER SIDE AIRBAG 2-POINT BELT 3-POINT BELT
 CRUISE CONTROL: YES NO
 DRIVETRAIN: FRONT REAR 4-WHEEL
 BODY STYLE: STAWAG HATCH BK 2 DOOR VAN 4 DOOR PK UP TRK OTHER

FAILED COMPONENT(S)/PART(S) INFORMATION

COMPONENT PART NAME(S) LOCATION FAILED PART(S)
 ① Isuzu trailer harness kit LEFT RIGHT ORIGINAL
 ② SRS Coil Assembly ③ Antenna FRONT REAR REPLACEMENT

NO. OF FAILURES: 0
 DATE(S) OF FAILURE(S) _____
 MILEAGE AT FAILURE(S) _____
 VEHICLE SPEED AT FAILURE(S) _____
 MANUFACTURER CONTACTED: YES NO
 NHTSA PREVIOUSLY CONTACTED: YES NO

APPLICABLE ACCIDENT INFORMATION

ACCIDENT: Yes No
 FIRE: Yes No
 NUMBER OF PERSONS INJURED: _____
 NUMBER OF FATALITIES: _____
 PROPERTY DAMAGE EST \$: _____
 POLICE REPORT FILED: YES NO

FAILED TIRE INFORMATION ONLY

TIRE IDENTIFICATION NO.* _____ MANUFACTURER TIRE NAME _____ SIZE _____
 DOT _____

* The identification number consists of 7 to 10 letters and numerals following the letters DOT. It is usually located near the rim flange on the side opposite the whitewall or on either side of a blackwall tire.

NARRATIVE DESCRIPTION OF FAILURE(S), ACCIDENT(S), INJURY(IES) ON THE BACK

The Privacy Act of 1974
 Public Law 93-579

This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to

assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

Component "Failures"

Actually, all 3 parts were defective or installed poorly during manufacture. All replaced under warranty.

① Trailer Hitch Harness kit (wiring)

- Isuzu notified us of defect via mail
- had kit replaced during regular service

② SRS Coil Assembly (Steering Column) made a rubbing or grinding noise when turning.

- reported noise to Isuzu service personnel at a regular service visit
- Service personnel replaced part under warranty

③ Antenna was severely bent and not tightly attached to vehicle when purchased.

- ^{Isuzu} service personnel unable to straighten antenna, so they replaced it under warranty.

NUMBER

609172

CHANGED

TO

6901257