

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

16-JAN-2000

 Od_or _____
 Rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

717417

 Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (located at front of windshield or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
2FMDA5143TBA48443	FORD TRUCK	WINDSTAR	1996	

Purchase Date 01-APR-1998	Dealer's Name _____	Engine Size (CID/CC/L) <u>3.8L</u>	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☐ New ☒ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☒ 3-Point Belt ☐ Motorbell ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Ult ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____
--	---	--	--	---	--	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 01243000 15300000	Part Name(s) STEERING:4 WHEEL STEERING:REAR ACTUATOR EQUIPMENT:SPEED CONTROL	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures 1	Date(s) of Failure(s) <u>01-DEC-1998</u> Mileage at Failure(s) <u>57000</u> Vehicle Speed at Failure(s) <u>20</u>	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	---------------------------	----------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE RIGHT REAR SPEED SENSOR QUIT WORKING AND WAS DETERMINED AS NEEDING REPLACEMENT BY JOE MAHAN FORD IN PARIS, TN. THE COST IS APPROXIMATELY \$100, BUT I FEEL THIS IS A SAFETY CONCERN BECAUSE WITHOUT IT WORKING, THE ANTI-LOCK BRAKES WILL NOT WORK. ALSO, THE SPEEDOMETER IS BROKEN. WHILE DRIVING OVER 30MPH, THE NEEDLE JUMPS AROUND TO 80 OR MORE AND THE CORRECT SPEED CANNOT BE DETERMINED. AGAIN, THIS SHOULD BE A SAFETY CONCERN BECAUSE SPEED SHOULD BE KNOWN AT ALL TIMES. I CONTACTED FORD CUSTOMER RELATIONS DEPARTMENT, BUT THEY STATED THAT THEY COULD BE OF NO ASSISTANCE. I REALLY NEED THESE ITEMS FIXED, BUT THE COMBINED COST IS GREATER THAN \$400 AND I FEEL FORD SHOULD AT LEAST SHARE IN THE COST. *AK

CONTINUED ON BACK (REVERSE)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

16-JAN-2000

 Od_or _____
 Rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

717417

 Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Listed at front of windshield or drivers side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
2FMDA5143TBA48443	FORD TRUCK	WINDSTAR	1996	

Purchase Date 01-APR-1998	Dealer's Name _____	Engine Size (CID/CC/L) 3.8L	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☐ New ☒ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☒ 3-Point Belt ☐ Motorbell ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Ult ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____
--	---	--	--	---	--	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 01243000 15300000	Part Name(s) STEERING:4 WHEEL STEERING:REAR ACTUATOR EQUIPMENT:SPEED CONTROL	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures 1	Date(s) of Failure(s) 01-DEC-1998 Mileage at Failure(s) 57000 Vehicle Speed at Failure(s) 20	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	---------------------------	----------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE RIGHT REAR SPEED SENSOR QUIT WORKING AND WAS DETERMINED AS NEEDING REPLACEMENT BY JOE MAHAN FORD IN PARIS, TN. THE COST IS APPROXIMATELY \$100, BUT I FEEL THIS IS A SAFETY CONCERN BECAUSE WITHOUT IT WORKING, THE ANTI-LOCK BRAKES WILL NOT WORK. ALSO, THE SPEEDOMETER IS BROKEN. WHILE DRIVING OVER 30MPH, THE NEEDLE JUMPS AROUND TO 80 OR MORE AND THE CORRECT SPEED CANNOT BE DETERMINED. AGAIN, THIS SHOULD BE A SAFETY CONCERN BECAUSE SPEED SHOULD BE KNOWN AT ALL TIMES. I CONTACTED FORD CUSTOMER RELATIONS DEPARTMENT, BUT THEY STATED THAT THEY COULD BE OF NO ASSISTANCE. I REALLY NEED THESE ITEMS FIXED, BUT THE COMBINED COST IS GREATER THAN \$400 AND I FEEL FORD SHOULD AT LEAST SHARE IN THE COST. *AK

CONTINUED ON BACK (REVERSE)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.