

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

21-APR-2000

 Od_or _____
 Rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

721759

 Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (located at front of windshield on driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
J81RF2362L7506132	GEO	STORM	1990	

Purchase Date 01-NOV-1996	Dealer's Name _____	Engine Size (CID/CC/L) 1.6 L	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☐ New ☒ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☒ 3-Point Belt ☐ Motorbell ☒ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☐ Yes ☒ No	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Ult ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☒ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____
--	---	---	--	---	--	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 08540000 06600000	Part Name(s) ELECTRICAL SYSTEM:IGNITION:ELECTRONIC CONTROL UNIT EXHAUST SYSTEM	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures 2	Date(s) of Failure(s) 20-SEP-1998 Mileage at Failure(s) 120000 Vehicle Speed at Failure(s) 35	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

PROBLEM WITH THE ECU IS A GMC MANUFACTURING DEFECT. DEALER WILL NOT REPLACE ECU. ECU HAS PROBLEM WITH BOARD LAMINATE EXPANDING AND CONTRACTING WITH TEMPERATURE CHANGE WHICH CAUSES DAMAGE TO THE CIRCUIT BOARD AND CHIP CONNECTIONS. SHOULD BE RECALLED AND REPLACED BY GM FREE OF CHARGE FOR ALL GEO STORMS. EXHAUST HEADER IS MADE OF IRON AND RUSTS IMMEDIATELY AFTER INSTALLATION. A FEW YEARS AFTERWARDS, EXHAUST HEADER WILL CRACK AND MUST BE REPLACED AT OWNER'S COST. THIS PART SHOULD BE REPLACED BY DEALER WITH SAME PART, FREE OF CHARGE, EVERY TIME IT BREAKS, OR REPLACED WITH A COMPONENT THAT WILL NOT RUST AND CRACK. *AK

CONTINUED ON BACK (SEE)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.