

U.S. Department  
of TransportationNational Highway  
Traffic Safety  
Administration

DOT Auto Safety Hotline

## Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT  
1-888-327-4236  
www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

30-MAY-2000

Oid\_or \_\_\_\_\_  
rt\_dt \_\_\_\_\_  
od\_rt \_\_\_\_\_  
up\_ltr \_\_\_\_\_

Reference No.

723360

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?  YES  NO  
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner \_\_\_\_\_ Date \_\_\_\_/\_\_\_\_/\_\_\_\_

## VEHICLE INFORMATION

Vehicle Ident. No. (VIN) <small>(Listed at front of windshield or drivers side)</small>	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1GNCS13W0T2242705	CHEVROLET TRU	BLAZER	1996	

Purchase Date <b>01-JUL-1997</b>	Dealer's Name _____	Engine Size (CID/CC/L) _____	<input type="checkbox"/> Turbo <input type="checkbox"/> Diesel <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Fuel Injection
<input type="checkbox"/> New <input checked="" type="checkbox"/> Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type <input type="checkbox"/> Manual <input type="checkbox"/> Automatic	Antilock Brakes <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Restraint System <input checked="" type="checkbox"/> 3-Point Belt <input checked="" type="checkbox"/> Driverside Airbag <input type="checkbox"/> Passengerside Airbag <input type="checkbox"/> Motorbell <input type="checkbox"/> 2-Point Belt	Cruise Control <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Drive Train <input type="checkbox"/> Front <input checked="" type="checkbox"/> Rear <input type="checkbox"/> 4-Wheel	Vehicle Type <input type="checkbox"/> Car <input type="checkbox"/> Van <input type="checkbox"/> Minivan <input type="checkbox"/> Other _____ <input type="checkbox"/> Sport Ult <input type="checkbox"/> Truck <input type="checkbox"/> Motorcycle	Body Style <input type="checkbox"/> 2-Door <input type="checkbox"/> 4-Door <input type="checkbox"/> Stationwagon <input type="checkbox"/> Pick Up Truck <input checked="" type="checkbox"/> Other _____
--	---	---	--	---	---	--

## FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06410000	Part Name(s) FUEL-THROTTLE LINKAGES AND CONTROL-PEDAL	Location <input type="checkbox"/> Left <input type="checkbox"/> Front <input type="checkbox"/> Right <input type="checkbox"/> Rear	Failed Part(s) <input type="checkbox"/> Original <input type="checkbox"/> Replacement
-----------------------	--	--	---

No. of Failures 1	Date(s) of Failure(s) 08-JAN-2000 Mileage at Failure(s) 49666 Vehicle Speed at Failure(s) 0	Failed Part(s) Available? <input type="checkbox"/> Yes <input type="checkbox"/> No	NHTSA Previously Contacted? <input type="checkbox"/> Yes <input type="checkbox"/> No
----------------------	---	---	---

## APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form.)

Crash <input type="checkbox"/> Yes <input type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
---	---	--------------------------------	---------------------------	---------------------------	---

## NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

ACCELERATOR PEDAL STICKS IN IDLE POSITION. IT SEEMS TO BE WORSE THE FIRST TIME THE PEDAL IS PRESSED AFTER THE ENGINE IS FIRST STARTED. HOWEVER, SINCE 5 MONTHS HAVE ELAPSED SINCE THE PROBLEM WAS FIRST NOTICED, IT SEEMS TO STICK NOW ALMOST EVERY TIME THE PEDAL GOES BACK TO THE IDLE POSITION. IT FEELS AS THOUGH SOMETHING IS HOLDING THE ACCELERATOR IN THE IDLE POSITION, AS IF IT IS SNAGGED ON SOMETHING. AFTER YOU APPLY EXTRA FORCE TO OVERCOME THE STICKING, IT TRAVELS SMOOTHLY WITH NO OTHER SNAGGING. A CO-WORKER OWNS A 1997 BLAZER AND IS HAVING THE SAME PROBLEM. I HAVE DRIVEN AT LEAST 2 DIFFERENT COMPANY VEHICLES WHICH WERE 1998 AND 1999 MODEL GM MINIVANS WITH A SIMILAR STICKING ACCELERATOR. ALL OF THESE VEHICLES, INCLUDING MINE, STICK ONLY IN THE IDLE POSITIO

CONTINUED ON BACK (REVERSE)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.