

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

258

Date Received

12-JUL-2000

Od_or

rt_dt

od_rt

up_ltr

Reference No.

725350

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner

Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) (located at front of vehicle or on driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1VWDC0173JV027635	VOLKSWAGEN	GOLF	1988	

Purchase Date

01-JUN-1988

Dealer's Name _____

Engine Size

(CID/CC) 1800CC

☐ Turbo☐ Diesel☐ Gas☒ Fuel Injection☒ New ☐ Used

City _____ State _____ Zip Code _____

No. Cylinders _____

Transmission Type

☐ Manual☐ Automatic

Antilock Brakes

☐ Yes☒ No

Restraint System

☒ 3-Point Belt☐ Driverside Airbag☐ Passengerside Airbag☐ Motorbelt☐ 2-Point Belt

Cruise Control

☒ Yes☐ No

Drive Train

☒ Front☐ Rear☐ 4-Wheel

Vehicle Type

☐ Car☐ Van☐ Minivan☐ Other☐ Sport Vlt☐ Truck☐ Motorcycle

Body Style

☐ 2-Door☐ 4-Door☐ Stationwagon☐ Pick Up Truck☒ Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 09530000	Part Name(s) COMMUNICATIONS:HORN ASSEMBLY:HORN	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures 5	Date(s) of Failure(s) 06-JUL-2000 Mileage at Failure(s) 150000 Vehicle Speed at Failure(s) 25	Failed Part(s) Available? Yes No	NHTSA Previously Contacted? Yes No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	--------------------------------	---------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE HORN ASSEMBLY IS PLACED IN THE FRONT LEFT PORTION OF THE AUTOMOBILE CLOSE TO THE ROAD SURFACE. WHEN WATER SPLASHES UP FROM THE FRONT LEFT TIRE, IT CAUSES ONE OR BOTH OF THE DUAL HORN SYSTEM TO FAIL, CREATING A POTENTIALLY DANGEROUS SITUATION OF NOT BEING ABLE TO USE HORN IN AN EMERGENCY. *AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.