

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Data Received

15-SEP-2000

 Od_or _____
 Rt_dt _____
 Od_rt _____
 Up_ltr _____

Reference No.

731552

Work Number

Home Number 913 236 8072

OWNER INFORMATION (Type or Print)

 MICHAEL LEWIS 641057
 5291 FOXRIDGE DR APT 303
 MISSION KS 66202

 Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Listed at front of windshield or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
JT2VV22E8K0070854	TOYOTA	CAMRY	1989	

Purchase Date 01-FEB-1996	Dealer's Name _____	Engine Size (CID/CC/L) <u>2.5L</u>	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☐ New ☒ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☐ 3-Point Belt ☐ Motorbell ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Ult ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____
--	---	---	--	---	--	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 15130000	Part Name(s) EQUIPMENT:ELECTRIC POWER ACCESSORIES:LOCKS:DOOR	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures 1	Date(s) of Failure(s) <u>07-JUL-2000</u> Mileage at Failure(s) <u>118518</u> Vehicle Speed at Failure(s) <u>2</u>	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	--------------------------------	---------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

PASSENGER FRONT DOOR POWER LOCK FUSED SHUT. DEALER IN SHAWNEE, KS CLAIMED THAT CAMPAGIN NUMBER 92V135000 WAS PERFORMED AT ROCHESTER NY DEALER IN 1994. TOYOTA AUTHORIZED DEALER TO CHECK RELAY TO SEE IF CAMPAIGN WAS PERFORMED. INSPECTION AT DEALER CONFIRMS RELAY INSTALLED, BUT DOOR IS STILL FUSED SHUT AND DEALER WILL NOT REPAIR AS PART OF THE ORIGNAL CAMPAIGN (THEY ALSO WON'T OFFER TO DISABLE THE DOOR LOCK SOLENOID). FROM LOOKING AT CONSUMER COMMENTS AT NHTSA THIS HAS HAPPENED TO MANY PEOPLE EVEN THOUGH CAPAING WAS PROBABLY PERFORMED! *AK

CONTINUED ON BACK (REVERSE)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response or a statistical summary thereof, may be used in support of the agency's action.