

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

258

Date Received

22-SEP-2000

Od_or

rt_dt

od_rt

up_ltr

Reference No.

732205

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner

Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (located at front of vehicle or on driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1GNEC16R1VJ367555	CHEVROLET TRU	SUBURBAN	1997	

Purchase Date 01-SEP-2000	Dealer's Name _____	Engine Size (CID/CCL) 5.7L	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☐ New ☒ Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☐ Motorbelt ☐ 2-Point Belt	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☒ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Van ☐ Minivan ☐ Other ☐ Sport Utl ☐ Truck ☐ Motorcycle	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other
--	---	---	--	---	---	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06351000	Part Name(s) FUEL:FUEL INJECTION/IDLE SPEED CONTROL UNIT	Location ☐ Left ☐ Front ☐ Right ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures 1	Date(s) of Failure(s) 16-SEP-2000 Mileage at Failure(s) 80500 Vehicle Speed at Failure(s) 45	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form.)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WHILE DRIVING ON A FLAT, EVEN ROAD AT ABOUT 45 MPH, THE STEERING RESISTANCE JUST DISAPPEARED FOR A FEW SECONDS. THIS WAS FRIGHTENING BECAUSE THERE WAS ABSOLUTELY NO CONTROL OF THE STEERING FOR THOSE FEW SECONDS AND I DRIFTED A LITTLE INTO THE OTHER LANE. MY HUSBAND AND I EXPERIENCED THIS SAME PROBLEM INTERMITTENTLY OVER THE NEXT DAY AND ALMOST EXCLUSIVELY WHEN TURNING TO THE RIGHT. WE WERE TEST DRIVING THE CAR AND BROUGHT THE PROBLEM UP TO THE CHEVY DEALER ON RETURN. THEY WOULD NOT FIX IT BUT AGREED TO LOWER THE PURCHASE PRICE BY THE ESTIMATED REPAIR COST. WE HAD IT FIXED THE NEXT DAY AT THE SAME CHEVY PLACE (I FELT IT WAS UNSAFE TO DRIVE IN THAT CONDITION). THEY REPLACED THE SPEED SENSOR AND CHARGED US \$260. THE REPAIR APPEARS T

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.