



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

25-MAR-2001

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

743030

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
JS1GR7HA9Y2103616	SUZUKI MOTORCY	SUZUKI MOTORCY	2000	

Purchase Date 01-SEP-2000	Dealer's Name _____	Engine Size (CID/CC/L 750 CC)	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☐ Yes ☒ No	Drive Train ☐ Front ☒ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Utl ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____
--	---	--	--	---	--	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06470000	Part Name(s) FUEL THROTTLE LINKAGES AND CONTROL/MOTORCYCLE	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
------------------------------	--	--	---

No of Failure 2	Date(s) of Failure(s) 20-JAN-2001 2300 Mileage at Failure(s) 50	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
---------------------------	---	--	--

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
---	---	---------------------------	----------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WHEN UNDER ACCELERATION IN SECOND GEAR, AND THE ENGINE REVS APPROACH 9000 RPM, THE BIKE "SKIPS" AS IF THE CHAIN IS SKIPPING ON THE SPROCKET. UPON TIGHTENING CHAIN PROBLEM STILL PERSISTS. TOOK IT TO THE DEALER AND SUZUKI CLAIMS TO DO A "GOOD WILL ONE TIME FIX". I KNOW OF MANY OTHERS WHO HAVE BEEN GIVEN THIS SAME LINE BY SUZUKI FOR THE EXACT SAME PROBLEM. THE PARTS THEY REPLACE ARE NEW REVISED PARTS, NOT THE ONES THAT CAME IN THE MOTORCYCLE OEM, YET SUZUKI STILL STANDS BY THEIR PRODUCT AND INSISTS IT IS "RIDER ERROR" AND NO FAULT OF THE PRODUCT.

COPIES OF THIS FORM ARE:

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.