



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

16-APR-2001

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

744111

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield or driver's side door)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1FMDU34X1TUC46109	FORD TRUCK	EXPLORER	1996	
Purchase Date 01-MAR-1996	Dealer's Name _____		Engine Size (CID/CC/L) 4.0 L	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____		No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☐ Rear ☒ 4-Wheel
Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____		Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____		

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06410000	Part Name(s) FUEL THROTTLE LINKAGES AND CONTROL PEDAL	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) 04-APR-2001 Mileage at Failure(s) 80000 Mileage at Failure(s) 0	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
---	---	---------------------------	----------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

STICKING THROTTLE BODY, CAUSES GAS PEDAL TO STICK AFTER PARK. IDENTICAL TO FORD RECALL OF SOHC ENGINE, HOWEVER FORD RECALL DOES NOT COVER THIS ENGINE (4.0L PUSH ROD V6). STICKING PEDAL CURED BY REPLACING DEFECTIVE THROTTLE BODY. FORD WILL NOT RECALL THROTTLE BODY FOR THIS ENGINE. STICKING PEDAL CAUSED "SUDDEN ACCELERATION" FROM STOP, RESULTING IN CLOSE CALL BACKING INTO SHOPPING CENTER STORE FRONT. FORD SHOULD RECALL THIS DEFECTIVE THROTTLE BODY, ALL SERVICES HAVE BEEN PERFORMED SINCE NEW AT FORD DEALER. THROTTLE BODY WAS CLEANED BY DEALER IN DECEMBER 2000.*AK

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.