

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393

DC METRO AREA (202) 366-0123

INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

23-APR-2001

Od. or

rt. dt

od. rt

ip. ltr

Reference No.

744409

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date _____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield or driver's side door)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
2FMDA5145TBB90809	FORD TRUCK	WINDSTAR	1996	

Purchase Date 01-OCT-1998	Dealer's Name _____	Engine Size (CID/CC/L) 3.8L	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☐ New ☒ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type	Antilock Brakes	Restraint System	Cruise Control	Drive Train	Vehicle Type	Body Style
☐ Manual ☐ Automatic	☒ Yes ☐ No	☐ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☐ Motorbelt ☐ 2-Point Bel	☒ Yes ☐ No	☒ Front ☐ Rear ☐ 4-Wheel	☐ Car ☒ Van ☐ Minivan ☐ Other	☐ Sport Util ☐ Truck ☐ Motorcycle ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05150021	Part Name(s) ENGINE:GASKETS:VALVE COVER	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) 06-APR-2001 Mileage at Failure(s) 62000 65	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag 0	Reported to Police ☐ Yes ☒ No
---	---	--------------------------------	---------------------------	-------------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE HEAD GASKET WAS REPLACED BY THE DEALER ON 3-16-01, DUE TO A CRACK AND LEAKING COOLANT. THE CAR HAD NEVER OVERHEATED OR SHOWN OBVIOUS SIGNS OF THIS, ALTHOUGH THE ENGINE CHECK LIGHT CAME ON AFTER LONG TRIPS AND THE DEALER SAID THIS WAS O2 SENSORS. 3 WEEKS AFTER THE HEADGASKET REPLACEMENT, THE WHOLE ENGINE BLEW WHILE ON I-81 AT 65MPH. WE LOST ALL POWER AND HAD TO COAST TO A NARROW SHOULDER. THIS SOUNDS EXACTLY LIKE THE 1995 WINDSTAR HEAD GASKET PROBLEM, BUT THEY HAVE NOT ACKNOWLEDGED THE 96 AS A MANUFACTURING DEFECT AND DID NOT RECALL THE 95 EITHER.*AK

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.