



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

08-MAY-2001

Ord. or
rt. dt
pd. rt
up. ltr

Reference No.

745081

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield or driver's side door)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1LNLM91V7VY633907	LINCOLN	MARK VIII	1997	

Purchase Date 01-OCT-2000	Dealer's Name _____	Engine Size (CID/CC/L) _____	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☐ New ☒ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☒ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☒ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____
--	---	--	--	---	---	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 09202000	Part Name(s) LIGHTING:LAMP OR SOCKET:HEAD LIGHTS	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
-----------------------	---	--	---

No of Failure 1	Date(s) of Failure(s) 01-NOV-2000 76000 Mileage at Failure(s) 0	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
--------------------	--	--	--

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
---	---	---------------------------	----------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE DRIVERS SIDE, LOW BEAM HEADLIGHT BURNT OUT ABOUT 6 MONTHS AGO. UPON TRYING TO REPLACE THE BULB, I LEARNED THAT THE BULB WAS ONLY AVAILABLE THROUGH THE DEALER. I CONTACTED 2 AUTHORIZED LINCOLN DEALERS & RECEIVED ESTIMATES VARYING IN THE RANGES OF \$79-\$835. AFTER MUCH RESEARCH, I DISCOVERED THAT THE \$835 ESTIMATE WAS CORRECT. IN MID PRODUCTION OF THE 97 LINCOLN MARK VIII THE FORD MOTOR COMPANY CHANGED VENDORS ON THE HEADLIGHT & THE FIRST SYSTEM UTILIZED IS NOT COMPATIBLE W/THE SECOND SYSTEM. HENCE, I NEED TO PAY TO CONVERT MY CAR TO THE ALTERNATE SYSTEM AS THEY DO NOT STOCK AFTER MARKET PARTS FOR THE CARS PRODUCED DURING THE FIRST HALF OF THE YEAR. I DO NOT HAVE A PROBLEM W/PAYING \$79 TO REPLACE THE BULB THAT NEEDS TO BE REPLACED. I FEEL IT IS LUDICROUS

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.