



U.S. Department  
of Transportation  
**National Highway  
Traffic Safety  
Administration**

**Auto Safety Hotline**

## Vehicle Owner's Questionnaire

**NATIONWIDE 1-800-424-9393  
DC METRO AREA (202) 366-0123  
INTERNET: <http://www.nhtsa.dot.gov>**

**FOR AGENCY USE ONLY 258**

Date Received

17-MAY-2001

Od\_or \_\_\_\_\_  
rt\_dt \_\_\_\_\_  
pd\_rt \_\_\_\_\_  
rp\_lr \_\_\_\_\_

Reference No.

745472

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?  YES  NO  
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner \_\_\_\_\_ Date \_\_\_\_/\_\_\_\_/\_\_\_\_

### VEHICLE INFORMATION

Vehicle Ident. No. (VIN) <small>(Locate at bottom of windshield or driver's side)</small>	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading		
4T1BF12B6VU140786	TOYOTA	AVALON	1997			
Purchase Date 01-OCT-1996	Dealer's Name _____	Engine Size (CID/CC/L) 3.0 L	<input type="checkbox"/> Turbo <input type="checkbox"/> Diesel <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Fuel Injectio			
<input checked="" type="checkbox"/> New <input type="checkbox"/> Used	City _____ State _____ Zip Code _____	No Cylinders _____				
Transmission Type <input type="checkbox"/> Manual <input type="checkbox"/> Automatic	Antilock Brakes <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Restraint System <input checked="" type="checkbox"/> 3-Point Belt <input type="checkbox"/> Motorbelt <input type="checkbox"/> Driverside Airbag <input type="checkbox"/> 2-Point Bel <input type="checkbox"/> Passengerside Airbag	Cruise Control <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Drive Train <input checked="" type="checkbox"/> Front <input type="checkbox"/> Rear <input type="checkbox"/> 4-Wheel	Vehicle Type <input type="checkbox"/> Car <input type="checkbox"/> Sport Util <input type="checkbox"/> Van <input type="checkbox"/> Truck <input type="checkbox"/> Minivan <input type="checkbox"/> Motorcycle <input type="checkbox"/> Other _____	Body Style <input type="checkbox"/> 2-Door <input checked="" type="checkbox"/> 4-Door <input type="checkbox"/> Stationwagon <input type="checkbox"/> Pick Up Truck <input type="checkbox"/> Other _____

### FAILED COMPONENT(S)/PART(S) INFORMATION

Component 10310000	Part Name(s) VISUAL SYSTEMS:WINDSHIELD WIPER	Location <input type="checkbox"/> Left <input type="checkbox"/> Right <input type="checkbox"/> Front <input type="checkbox"/> Rear	Failed Part's <input type="checkbox"/> Original <input type="checkbox"/> Replacement
No of Failure 1	Date(s) of Failure(s) C3-JAN-2000 56821	Failed Part(s) <input type="checkbox"/> Yes <input type="checkbox"/> No	NHTSA Previously <input type="checkbox"/> Yes <input type="checkbox"/> No
	Mileage at Failure(s) 50		

### APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash <input type="checkbox"/> Yes <input type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag	Reported to Police <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
---	---	--------------------------------	---------------------------	--------------------------	---

### NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WINDSHIELD WIPERS STOPPED WORKING IN A RAIN STORM WHILE ON THE HIGHWAY. THE AUTO WAS TAKEN TO TOYOTA DIRECT, THE CLOSEST TOYOTA DEALERSHIP. THE PROBLEM WAS DIAGNOSED AS WIPER TRANSMISSION BROKEN AND THE SOLUTION WAS TO REPLACE THE WIPER TRANSMISSION. THIS WAS EXPLAINED TO ACTUALLY BE A LINKAGE ASSEMBLY. THE REPAIR COST (INCLUDING TWO NEW WIPER INSERTS) WAS \$295.05. THIS WAS \$182.65 FOR PARTS (LINKAGE \$171.77, WIPER INSERTS @ \$5.44 EACH), LABOR-MECHANICAL - \$88.04, HAZARDOUS MATERIALS - \$4.40, SHOP SUPPLIES - \$4.40, AND SALES TAX OF \$15.56. THE SERVICE MANAGER SAID THIS WAS NOT COVERED BY THE MANUFACTURER BECAUSE OF THE MILEAGE AND NOT COVERED BY THE ADDITIONAL COVERAGE PURCHASED AT TIME AUTO WAS PURCHASED BECAUSE IT WAS NOT ELECTRICAL. THIS IS A VERY DANGEROUS SITUATION AND

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.