



U.S. Department  
of Transportation  
**National Highway  
Traffic Safety  
Administration**

## Auto Safety Hotline

**Vehicle Owner's Questionnaire**

NATIONWIDE 1-800-424-9393  
DC METRO AREA (202) 366-0123  
INTERNET: <http://www.nhtsa.dot.gov>

**FOR AGENCY USE ONLY 258**

Date Received

12-AUG-2001

Od\_or \_\_\_\_\_  
rt\_dt \_\_\_\_\_  
pd\_rt \_\_\_\_\_  
rp\_lr \_\_\_\_\_

Reference No.

750277

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?  YES  NO  
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner \_\_\_\_\_ Date \_\_\_\_/\_\_\_\_/\_\_\_\_

**VEHICLE INFORMATION**

Vehicle Ident. No. (VIN) <small>(Location at bottom of and/or above driver's side)</small>	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading		
1G6DW52P9SR704268	CADILLAC	FLEETWOOD	1995			
Purchase Date 01-MAR-1995	Dealer's Name _____	Engine Size (CID/CC/L 5.7L	<input type="checkbox"/> Turbo <input type="checkbox"/> Diesel <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Fuel Injectio			
<input checked="" type="checkbox"/> New <input type="checkbox"/> Used	City _____ State _____ Zip Code _____	No Cylinders _____				
Transmission Type <input type="checkbox"/> Manual <input type="checkbox"/> Automatic	Antilock Brakes <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Restraint System <input checked="" type="checkbox"/> 3-Point Belt <input type="checkbox"/> Motorbelt <input type="checkbox"/> Driverside Airbag <input type="checkbox"/> 2-Point Bel <input type="checkbox"/> Passengerside Airbag	Cruise Control <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Drive Train <input type="checkbox"/> Front <input checked="" type="checkbox"/> Rear <input type="checkbox"/> 4-Wheel	Vehicle Type <input type="checkbox"/> Car <input type="checkbox"/> Sport Util <input type="checkbox"/> Van <input type="checkbox"/> Truck <input type="checkbox"/> Minivan <input type="checkbox"/> Motorcycle <input type="checkbox"/> Other _____	Body Style <input type="checkbox"/> 2-Door <input checked="" type="checkbox"/> 4-Door <input type="checkbox"/> Stationwagon <input type="checkbox"/> Pick Up Truck <input type="checkbox"/> Other _____

**FAILED COMPONENT(S)/PART(S) INFORMATION**

Component 02815000	Part Name(s) WHEELS:LUGS:NUTS:BOLTS	Location <input type="checkbox"/> Left <input type="checkbox"/> Right <input type="checkbox"/> Front <input type="checkbox"/> Rear	Failed Part's <input type="checkbox"/> Original <input type="checkbox"/> Replacement
No of Failure 1	Date(s) of Failure(s) 04-AUG-2001 64171	Failed Part(s) <input type="checkbox"/> Yes <input type="checkbox"/> No	NHTSA Previously <input type="checkbox"/> Yes <input type="checkbox"/> No
	Mileage at Failure(s) 68		

**APPLICATION INCIDENT INFORMATION**

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash <input type="checkbox"/> Yes <input type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag	Reported to Police <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
---	---	--------------------------------	---------------------------	--------------------------	---

**NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)**

WHILE DRIVING AT 68 MPH ON ROUTE 35E 40 MILES SOUTH OF DALLAS, TEXAS, THE RIGHT FRONT WHEEL CAME OFF THE CAR. ALL FIVE OF THE LUG STUDS SHEARED OFF AT THE FACE OF THE ROTOR ASSEMBLY. THE TIRE WEDGED AGAINST THE LOWEST REAR PART OF THE FENDER WELL WHICH RESULTED IN A CLEAN CUT THROUGH THE TIRE SIDEWALL. I WAS TRAVELLING IN THE RIGHT HAND LANE AND WAS ABLE TO BRING THE CAR TO A SAFE STOP ON THE RIGHT SHOULDER OF THE ROAD. THE TIRE TRAVELED ABOUT 350 YARDS ACROSS THE RIGHT HAND DRAINAGE AREA AND STOPPED IN A CULTIVATED FIELD ABOUT 100 YARDS FROM WHERE I STOPPED THE CAR. THE TIRE HAD BEEN PUT ON THE CAR ABOUT THREE WEEKS PRIOR TO THIS INCIDENT AND HAD BEEN TORQUED TO THE MANUFACTURERS SPECIFICATIONS OF 100 FT/LBS. THE ROTOR REQUIRED REPLACEMENT ALONG WITH 1

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.