



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

01-OCT-2001

Od_or _____
rt_dt _____
od_rt _____
ip_lr _____

Reference No.

752772

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield or driver's side door)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1HFSC47431A000995	HONDA	GL1500	2001	

Purchase Date 01-APR-2001	Dealer's Name _____	Engine Size (CID/CC/L <u>1800CC</u>)	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No
		Drive Train ☐ Front ☒ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____
			Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 12430000	Part Name(s) INTERIOR SYSTEMS:INSTRUMENT PANEL:SPEEDOMETER:ODOM	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure	Date(s) of Failure(s) _____ Mileage at Failure(s) _____	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
---	---	---------------------------	----------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

SPEEDOMETER IS 6% TO 7% FAST THIS MEANS THAT THE DRIVER HAS TO COMPUTE HIS/HER ACTUAL SPEED, WHEN RIDING ON A TWO LANE ROAD AND YOU ARE TRAVELING AT THE SPEED LIMIT ACCORDING TO THE SPEEDOMETER CARS ARE RIDING YOUR ON YOUR BACK FENDER OR TRYING TO PASS BECAUSE YOU ARE TRAVELING WELL BELOW THE SPEED LIMIT. THIS CAN CAUSE A VERY SERIOUS ACCIDENT. AT AN INDICATED 65 MPH THE ACTUAL SPEED IS 60/61 MPH, THE FASTER YOU GO THE LARGER THE DIFFERENCE. IN THIS AGE OF ELECTRONICS THERE IS NO REASON THE SPEEDOMETER SHOULD BE 6% TO 7% FAST OR SLOW, AND THE DRIVER HAS TO COMPUTE THE ACTUAL SPEED. DRIVERS HAVE ENOUGH TO DO TO STAY SAFE. THIS IS A PROBLEM ON ALL GL1800'S.

COPIES OF THIS FORM ARE:

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.