



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

03-OCT-2001

Od_or _____
rt_dt _____
od_rt _____
ip_lr _____

Reference No.

752850

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield or driver's side door)		Vehicle Make ISUZU TRUCK	Vehicle Model AMIGO	Vehicle Year 1990	Current Odometer Reading
Purchase Date ☐ New ☒ Used	Dealer's Name _____ City _____ State _____ Zip Code _____		Engine Size (CID/CC/L) _____ No Cylinders _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☐ Yes ☒ No	Drive Train ☐ Front ☒ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____ Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06420000	Part Name(s) FUEL THROTTLE LINKAGES ACCELERATOR RIGID	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) 24-SEP-2001 Mileage at Failure(s) 45	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag 0	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	--------------------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE RUBBER SLEEVE THAT PROTECTS THE EXPOSED THROTTLE CABLE FROM DIRT HAD STARTED TO MELT (FROM ENGINE HEAT). THE RUBBER HAD MELTED AROUND THE THROTTLE CABLE CAUSING THE CABLE TO BE HELD IN THE OPEN POSITION. WHEN I TOOK MY FOOT OFF THE ACCELERATOR AND DISCOVERED THE THROTTLE WAS STICKING I STARTED BANGING ON THE SIDE OF THE PEDAL WITH MY FOOT THINKING THAT THE PROBLEM WAS WITH THE PEDAL ITSELF CAUSING THE THROTTLE TO BE PRESSED MORE. THIS HAPPEND WHILE TRAVELING SOUTH ON US 301 APPROACHING THE US 70 INTERSECTION IN SELMA, NORTH CAROLINA. AFTER I DID GET THE VEHICLE SHUT OFF, I CHECKED AROUND THE THROTTLE AREA UNDER THE HOOD AND FOUND THE RUBBER MELTING ONTO THE CABLE. I TOOK OFF WHAT WAS LEFT AND CLEANED THE CABLE AND HAVE NOT HAD A PROBLEM SINCE.*AK

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.