



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

19-DEC-2001

Od_or _____
rt_dt _____
od_rt _____
ip_lr _____

Reference No.

755830

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side) JT4VN36H9S0021132	Vehicle Make TOYOTA TRUCK	Vehicle Model 4 RUNNER	Vehicle Year 1995	Current Odometer Reading
Purchase Date 01-MAR-2001	Dealer's Name _____		Engine Size (CID/CC/L) 3L	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☐ New ☒ Used	City _____ State _____ Zip Code _____		No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☒ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☐ Rear ☒ 4-Wheel
Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____		Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____		

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05150021	Part Name(s) ENGINE:GASKETS:VALVE COVER	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) 02-DEC-2001	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
	Mileage at Failure(s) 130000		
	Vehicle Speed at Failure(s) 50		

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag 0	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	--------------------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

HEAD GASKET FAILURE: DULL BANG OCCURS IN ENGINE, EXCESSIVE WHITE SMOKE BILLOWS FROM EXHAUST. EXHAUST SMELLS SWEET FROM ANTI-FREEZE. ENGINE RAN ROUGH FROM ONE CYLINDER MISFIRING. COOLANT IS BEING BLOWN FROM RADIATOR CAP. HAD TO PULL OVER IMMEDIATELY IN HEAVY TRAFFIC. VEHICLE TOWED TO HOME. TEST ON ENGINE OIL FINDS THAT COOLANT HAS MIXED WITH ENGINE LUBRICATING OIL. DISCUSSION WITH TOYOTA CERTIFIED MECHANIC RESULT: THIS IS A COMMON PROBLEM WITH THE NEW HEAD GASKETS AND IS USUALLY CATASTROPHIC NEEDING ENGINE REBULD/REPLACEMENT AS THE ENGINE BLOCK USUALLY NEEDS RE-DECKING(MILLING) BEYOND MAXIMUM ALLOWABLE TOLERANCES; COOLANT GALLERY COMES TOO CLOSE TO CYLINDER WALL AT HE

COPIES OF THIS FORM ARE:

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.