



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

19-JAN-2002

Od_or _____
rt_dt _____
od_rt _____
ip_lr _____

Reference No.

757081

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Located at bottom of windshield and driver's side door) 1FTWW32F32EA35522	Vehicle Make FORD TRUCK	Vehicle Model F350	Vehicle Year 2001	Current Odometer Reading
---	-----------------------------------	------------------------------	-----------------------------	--------------------------

Purchase Date 01-SEP-2001	Dealer's Name _____	Engine Size (CID/CC/L) V-8	☒ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No
		Drive Train ☐ Front ☒ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____
			Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☒ Pick Up Truck ☐ Other _____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 02100000	Part Name(s) SUSPENSION:INDEPENDENT FRONT	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) 19-NOV-2001 Mileage at Failure(s) 3000 Vehicle Speed at Failure(s) _____	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag 0	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	--------------------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WITHIN FIRST 60 DAYS AFTER PURCHASE, VEHICLE BEGAN TO MAKE THUMPING NOISE IN FLOORBOARD AFTER START OF ENGINE, AFTER CONTINUED OPERATION OF VEHICLE OUT OF NECESSITY IT BEGAN TO HAVE FRONT END VIBRATIONS AT 70 MPH AS WELL AS A VIBRATION DURING SLOW SPEED SHARP TURNS. I AM CURRENTLY UNABLE TO TAKE VEHICLE TO BE SERVICED DUE TO LACK OF A SECOND VEHICLE (SEE ODI# 757078). ASKED FOR ASSISTANCE FROM DEALERSHIP (JACK ROACH FORD HOUSTON TX) WHO CONTACTED REGIONAL REP. WAS TOLD BY DEALERSHIP THAT THE REP WOULD NOT PROVIDE ANY ASSISTANCE BECAUSE I HAVE A VEHICLE (ODI# 757078) THAT IS AVAILABLE TO ME. PROBLEM IS UNRESOLVED DUE TO MY REQUIREMENT FOR TRANSPORTATION AND FORD MOTOR COMPANY REGIONAL

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.