



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

02-MAR-2002

Od_or _____
rt_dt _____
pd_rt _____
ip_lr _____

Reference No.

758849

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield or driver's side door)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1G6KY5294RU834484	CADILLAC	SEVILLE	1994	

Purchase Date 01-AUG-1994	Dealer's Name _____	Engine Size (CID/CC/L) 4.6L	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No
		Drive Train ☒ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____
			Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05100000 05150021	Part Name(s) ENGINE ENGINE:GASKETS:VALVE COVER	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) 20-JAN-2002	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
	Mileage at Failure(s) 105000		
	Vehicle Speed at Failure(s) 40		

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag 0	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	--------------------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

ENGINE SHUT DOWN WHILE DRIVING UP MOUNTAIN ROAD DUE TO OVERHEATING. PROBLEM DIAGNOSED BY DEALER AS BLOWN HEAD GASKETS DUE TO LOOSENING OF HEAD BOLTS. PROBLEM IS USE OF STEEL BOLTS DIRECTLY IN ALUMINUM BLOCK WHICH VIBRATE LOOSE OVER TIME, CAUSING LOSS OF ENGINE COOLANT. WIDELY RECOGNIZED PROBLEM BY REPAIR SHOPS AND THERE IS A TECHNICAL SERVICE BULLETIN ADDRESSING THIS REPAIR; NEVERTHELESS CADILLAC CLAIMS IT IS NOT AWARE OF ANY DESIGN DEFECT AND REFUSES TO ASSIST WITH REPAIR. REPAIR COST \$4,600 TO REBUILD ENGINE OR \$7,800 TO REPLACE ENGINE. PROBLEM DEVELOPED WITH NO WARNING AND CAUSED OCCUPANT AND FAMILY TO BE STRANDED.*AK

COPIES OF THIS FORM ARE:

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

02-MAR-2002

Ord. or
rt. dt
pd. rt
rp. ltr

Reference No.

758849

Work Number

Home Number 703 768 3477

OWNER INFORMATION (Type or Print)

TED STONE 741654
8024 EAST BOULEVARD DR.
ALEXANDRIA VA 22308

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side door) 1G6KY5294RU834484	Vehicle Make CADILLAC	Vehicle Model SEVILLE	Vehicle Year 1994	Current Odometer Reading
---	--------------------------	--------------------------	----------------------	--------------------------

Purchase Date 01-AUG-1994	Dealer's Name _____	Engine Size (CID/CC/L) 4.6L	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____
--	---	--	--	---	---	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05100000 05150021	Part Name(s) ENGINE ENGINE:GASKETS:VALVE COVER	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) 20-JAN-2002	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
	Mileage at Failure(s) 105000		
	Vehicle Speed at Failure(s) 40		

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag ☐ Yes ☒ No	Reported to Police ☐ Yes ☒ No
---	---	--------------------------------	---------------------------	---	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

ENGINE SHUT DOWN WHILE DRIVING UP MOUNTAIN ROAD DUE TO OVERHEATING. PROBLEM DIAGNOSED BY DEALER AS BLOWN HEAD GASKETS DUE TO LOOSENING OF HEAD BOLTS. PROBLEM IS USE OF STEEL BOLTS DIRECTLY IN ALUMINUM BLOCK WHICH VIBRATE LOOSE OVER TIME, CAUSING LOSS OF ENGINE COOLANT. WIDELY RECOGNIZED PROBLEM BY REPAIR SHOPS AND THERE IS A TECHNICAL SERVICE BULLETIN ADDRESSING THIS REPAIR; NEVERTHELESS CADILLAC CLAIMS IT IS NOT AWARE OF ANY DESIGN DEFECT AND REFUSES TO ASSIST WITH REPAIR. REPAIR COST \$4,600 TO REBUILD ENGINE OR \$7,800 TO REPLACE ENGINE. PROBLEM DEVELOPED WITH NO WARNING AND CAUSED OCCUPANT AND FAMILY TO BE STRANDED.*AK

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.