



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

10-JUN-2002

Od_or _____
rt_dt _____
od_rt _____
ip_lr _____

Reference No.

762877

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield and door side) 1N6DD26S1WC331510	Vehicle Make NISSAN TRUCK	Vehicle Model PICKUP	Vehicle Year 1998	Current Odometer Reading
Purchase Date 01-MAR-2098	Dealer's Name _____		Engine Size (CID/CC/L) _____	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____		No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☐ Yes ☒ No	Drive Train ☐ Front ☒ Rear ☐ 4-Wheel
Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____		Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☒ Pick Up Truck ☐ Other _____		

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 02261000	Part Name(s) SUSPENSION: I-BEAM: SOLID: FRONT HUB 1	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 2	Date(s) of Failure(s) 10-JUN-2002	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
	Mileage at Failure(s) 48537		
	Vehicle Speed at Failure(s) 0		

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
---	---	---------------------------	----------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THIS COMPONENT HAS FAILED ON BOTH THE RIGHT AND LEFT SIDE. IN BOTH CASES THE WASHER WAS MISSING THAT HOLDS THE BUSHING IN PLACE. THE FIRST OCCURRENCE HAPPENED AT 20,000 MILES AND THE SECONAND WAS DISCOVERED AT 48,000. THE DEALER WAS ASKED THE FIRST TIME TO CHECK THE LEFT SIDE BUT THEY STATED THAT IT WAS NISSAN POLICY TO FIX ONLY WHAT WAS BROKEN. IN BOTH CASES THE WASHER WAS MISSING AND I WONDER HOW MANY OTHER TRUCKS HAVE THIS SAME PROBLEM. THIS DEFECT CAUSES CAUSES EXCESSIVE SWAY WHILE DRIVING THE TRUCK AND THE DRIVER COULD LOOSE CONTROL. THANK YOU, DENNIS NICHOLS*AK

COPIES OF THIS FORM ARE:

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.