



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

20-JUN-2002

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

763270

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date _____/_____/_____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side door)		Vehicle Make HARLEY DAVIDSO	Vehicle Model FLHTCI	Vehicle Year 2000	Current Odometer Reading
Purchase Date	Dealer's Name _____		Engine Size (CID/CC/L 1340/C)	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection	
☒ New ☐ Used	City _____ State _____ Zip Code _____		No Cylinders _____		
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☐ Yes ☒ No	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Utl ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____ Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 09302000 09303000	Part Name(s) LIGHTING:FUSE:HEAD LIGHTS LIGHTING:FUSE:SIDE MARKER LIGHTS	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part's ☐ Original ☐ Replacement
No of Failure 2	Date(s) of Failure(s) 12-JUN-2002 Mileage at Failure(s) 18000 Vehicle Speed at Failure(s)	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
---	---	---------------------------	----------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE FRONT FENDER TIP MARKER LIGHT HAS WIRING THAT RUNS UNDER THE FRONT FENDER, IT RUBS ON THE TIRE WHICH WEARS THE INSULATION OFF THE WIRES , THIS CAUSES A SHORT AND BLOWS THE FUSE, THIS FUSE IS ALSO FOR THE HEADLIGHT SO WHEN THIS HAPPENS THE MOTORCYCLE LOSES HEADLIGHT AND RUNNING LIGHT, THIS IS A VERY DANGEROUS SITUATION WHEN DRIVING THE MOTORCYCLE AT NIGHT ON A DARK UNLIT ROAD, MY UNDERSTANDING FROM THE DEALER IS THAT THIS IS A COMMON PROBLEM FOR A COUPLE OF YEARS OF THIS MODEL.*AK

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.