



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

01-JUL-2002

Od_or _____
rt_dt _____
pd_rt _____
up_lr _____

Reference No.

763689

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side door)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1HFSC47062A100393	HONDA MOTORCY	GL1800	2002	

Purchase Date 01-SEP-2001	Dealer's Name _____	Engine Size (CID/CC/L) 1800	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No
		Drive Train ☐ Front ☒ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Utl ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____
			Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05200000	Part Name(s) ENGINE COOLING SYSTEM	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 3	Date(s) of Failure(s) 30-JUN-2002	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
	Mileage at Failure(s) 2175		
	Vehicle Speed at Failure(s) 20		

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
---	---	---------------------------	----------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THIS NEW GENERATION HONDA GOLDWING MOTORCYCLE RELEASED FOR MODEL YEAR 2001 HAS A COOLING DESIGN DEFECT THAT CAUSES THE ENGINE TO DANGEROUSLY OVERHEAT WHEN CAUGHT IN STOP AND GO TRAFFIC CONDITIONS. YESTERDAY, (JUNE 30, 2002) MYSELF AND TWO OTHERS ALSO HAVING 2002 GOLDWINGS WERE RETURNING FROM A TRIP AND FOUND OURSELVES IN A MAJOR TRAFFIC BACKUP IN A ROAD CONSTRUCTION AREA ON US INTERSTATE 35 SOUTH OF MINNEAPOLIS, MINNESOTA. ALL 3 GOLDWINGS OVERHEATED IN THE STOP AND GO, SINGLE LANE CONDITIONS. THERE WAS NOWHERE FOR ANY OF US TO SAFELY PULL OVER TO SHUT THE MOTORCYCLES OFF TO COOL. WE WERE ULTIMATELY FORCED TO DRIVE ON THE NARROE TEMPORARY RIGHT SHOULDER AT HIGH ENOUGH

COPIES OF THIS FORM ARE:

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.