

NO REPLY FROM FORD

Form Approved O.M.B. No. 2127-0005

 U.S. Department of Transportation National Highway Traffic Safety Administration		DOT Auto Safety Hotline Vehicle Owner's Questionnaire (VOQ) NATIONWIDE 1-888-DASH-2-DOT 1-888-327-4236 www.nhtsa.dot.gov/hotline		FOR AGENCY USE ONLY 1398 Date Received: 26 NOV 2002 Office: DEFECTS INVESTIGATION Reference No.: 8023395 Work Number: Home Number:	
OWNER INFORMATION (Type or Print) [Redacted] HENDERSON NC [Redacted]				Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? In the absence of an authorized address to the vehicle manufacturer. Signature of Owner: [Redacted] Date: 12/18/02	
Vehicle Ident. No. (VIN) (17 characters of which 8 are on driver's side) 1FMDU32X3TUA64141		Vehicle Make FORD TRUCK		Vehicle Model EXPLORER	
Purchase Date OCT 1995		Dealer's Name SIMMONS FORD		Engine Size (CID/CC/L) No Cylinders: 6	
☒ New ☐ Used		City: HENDERSON State: NC Zip Code: 27536		☐ Turbo Diesel Gas Fuel Injection	
Transmission Type ☐ Manual ☒ Automatic		Antilock Brakes ☒ Yes ☐ No		Restraint System ☒ 3-Point Belt ☐ Motorbelt ☒ Driverside Airbag ☐ 2-Point Belt ☒ Passengerside Airbag	
Cruise Control ☒ Yes ☐ No		Drive Train ☐ Front ☒ Rear ☐ 4-Wheel		Vehicle Type ☐ Car ☒ Sport Lift Truck ☐ Minivan ☐ Motorcycle ☐ Other	
Body Style ☒ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other		FAILED COMPONENT(S)/PART(S) INFORMATION			
Component 02182000		Part Name(s) SUSPENSION: INDEPENDENT FRONT CONTROL ARM: UNKNOWN T NON GREASEABLE BALL JOINTS		Location ☒ Left ☒ Right ☐ Front ☐ Rear	
Failed Part(s) ☒ Original ☐ Replacement		No of Failures		Date(s) of Failure(s) Mileage at Failure(s): 50000 Vehicle Speed at Failure(s):	
Failed Part(s) Available? ☐ Yes ☐ No		NHTSA Previously ☐ Yes ☐ No			
APPLICATION INCIDENT INFORMATION (Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)					
Crash ☐ Yes ☐ No		Fire ☐ Yes ☐ No		Number of Persons Injured	
Number of Fatalities		Estimated Property Damage		Reported to Police ☐ Yes ☐ No	
NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES) CONSUMER CALLED COMPLAINING ABOUT HAVING PROBLEMS WITH THE BALL JOINTS. ALSO STATED THAT HE HEARD RUMMORS ABOUT THE BALL JOINTS. MANUFACTURE WAS CONTACTED AND STATED THAT THEY WILL PASS THE INFORMATION TO THE ENGINEERS BUT IS BEEN 8 DAYS AND HE HAS NOT HEARD ABOUT THEM. TS THE RUBBER BOOTS ARE FALLING APART, CAUSING DIRT & WATER TO GET IN BALL JOINTS. THIS VEH. HAS NEVER BEEN ON A GRAVEL ROAD, PLUS NC HAS A MILD CLIMATE.					
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.					

ON THE INTERNET PEOPLE HAD JOINTS COME APART & LOST STEERING — AND MANY AT 40K MILES, HAD THEM REPLACED AT \$400.00 A JOB. FORD MUST BE USING BAD RUBBER ON THE JOINTS.

ITS BEEN A MONTH NOW. FORD DEFENSE SEEN TO BE CONCERNED ABOUT THIS PROBLEM