

DAIMLERCHRYSLER

853855

DaimlerChrysler
Motors Corporation

September 7, 1999

[Redacted]
Stone Mountain, GA [Redacted]


Reference No.: 6160236
V.I.N.: 2C3HE66G5XH625418

Dear [Redacted]:

This letter is in response to your latest contact to DaimlerChrysler Motors Corporation, regarding your 1999 Chrysler 300M.

Naturally, we were sorry to learn of the accident described to us during the initial contact. However, we have had the opportunity to review the inspection report and I must inform you that I have been unable to associate this incident with any manufacturing responsibility. Our inspection revealed that the throttle linkage, and all associated parts, were operating properly. Also, during electronic testing, no fault codes appeared that would have indicated a malfunction at the time of this incident.

Based on this information, we can only suggest that you refer this matter to your insurance carrier. Should they feel a manufacturing responsibility exists, they have full subrogation rights under the terms of your policy.

Sincerely,


M. R. Porterfield
Special Investigations
(248) 944-7134

MRP/lis

2003 OCT -1 AM 10:50

State Farm Insurance Companies



November 13, 1999

[Handwritten scribble]

Auto Claim Central
11380 Johns Creek Parkway
Post Office Box 10003
Duluth, Ga 30096-9403

[Redacted]
Stone Mountain, GA [Redacted]

RE: Claim Number: [Redacted]
Date of Loss: August 17, 1999
Our Insured: [Redacted]

Dear [Redacted]:

Enclosed is a copy of a supplemental estimate which was written on your vehicle.

The payment of the supplemental amount is being made directly to the shop for your convenience.

If you have any questions, please call us at the number below between the hours of 7:00 A.M. and 9:00 P.M. Monday through Friday, 9:00 A.M. to 5:00 P.M. on Saturday or 11:00 A.M. to 5:00 P.M. on Sunday. Whenever you call, anyone on our team will be available to assist you.

Sincerely,

[Handwritten signature: Sharon Keahey]
Sharon Keahey, Team 05
Claim Representative
(800) 578-8001

State Farm Fire and Casualty Company

State Farm Insurance

Damage Assessed By: CLAYTON DINN

Appraised For: Team 5 Processor
 (800) 578-8001

Supplemented By: CLAYTON DINN

Condition Code: Good
 Date of Loss: 08/17/99
 Deductible: 250.00
 Claim Number: 11-3332-30501

Type of Loss: Collision

Insured: [REDACTED]
 Address: [REDACTED] STONE MOUNTAIN, GA [REDACTED]
 Telephone: [REDACTED]

Mitchell Service: 912529

Description: 1999 Chrysler 300M
 Body Style: 4D Sed
 VIN: 2C3HE66G5KN625418
 Mileage: 10,405
 OEM/ALT: A
 Color: Gold

Drive Train: 3.5L Inj 4 Cyl AD
 License: [REDACTED] GA

Search Code: 3005

Line Entry	Labor	Line Item	Part Type/	Dollar	Labor
Item Number	Type	Operation	Part Number	Amount	Units
1	900500	BDY* ADD'L LABOR OP	600		
2		600 BODY PULL WITH SETUP			
3	900500	REF* REFINISH/REPAIR			
4	200003	BDY REMOVE/REPLACE	Sublet	8.00*	0.0*
5	200005	BDY REMOVE/REPLACE	4792545AA	2.25	
6	200006	BDY REMOVE/REPLACE	4591208	2.35	
7	AUTO	BDY OVERHAUL	4592114	2.70	
8	200014	BDY REMOVE/REPLACE			2.2
9	AUTO	REF REFINISH	4574820	335.00	INCL
10	200019	BDY REMOVE/REPLACE			C 2.3
11	200021	BDY REMOVE/REPLACE	4574819	86.00	INCL
12	200023	BDY REMOVE/REPLACE	4805052	22.50	INCL #
13	200025	BDY REMOVE/REPLACE	4574812	145.00	INCL
14	200029	BDY REMOVE/REPLACE	4805106	11.25	INCL
5	200030	BDY REMOVE/REPLACE	4805107	190.00	INCL #
6	200039	BDY REMOVE/REPLACE	4574822	89.50	INCL #
7	AUTO	BDY CHECK/ADJUST	4780013AA	315.00	INCL
8	200054	BDY REMOVE/REPLACE			0.3
9	200065	BDY REMOVE/REPLACE	4805039	21.25	INCL #
0	AUTO	REF REFINISH	500310QAB	435.00	1.5
1	AUTO	REF REFINISH			C 2.8
2	200073	BDY REMOVE/REPLACE			1.4
		R HOOD HINGE	4580136AD	27.50	0.3 #

ESTIMATE RECALL NUMBER: 08/24/99 11:33:57 11-3332-30501

Mitchell Data Version: OCT_99_B

UltraMate is a Trademark of Mitchell International
 Copyright (C) 1994, 1995 Mitchell International
 All Rights Reserved

23	AUTO	REF	REFINISH	R HINGE			0.3
24	200074	BDY	REMOVE/REPLACE	L HOOD HINGE	4580139AG	27.50	0.3 #
25	AUTO	REF	REFINISH	L HINGE			0.3
S2 26	200090	BDY	REMOVE/REPLACE	COOLING RADIATOR	5010359AA	310.00	2.0
27	200116	BDY	REMOVE/REPLACE	COOLING DRIVE BELT	4663950	8.85	0.8
28	900500	BDY*	ALIGN	ALIGN FRONT SUSPENSION	Sublet	49.95*	0.0*
S2 29	200118	BDY	REMOVE/REPLACE	TRANS OIL COOLER BRACKET	4796282AB	2.85	
S2 30	900500	BDY*	REMOVE/INSTALL	CARPET	Existing		1.0*
S2 31	201562	MCH	REMOVE/REPLACE	EVAQUATE & RECHARGE A/C			1.4
S2 32	201563	MCH	REMOVE/REPLACE	A/C REFRIGERANT RECOVERY			0.3
S2 33	200123	MCH	REMOVE/REPLACE	AIR COND CONDENSER			0.4 #
34	200159	BDY	REMOVE/REPLACE	R FENDER PANEL	5003066AC	210.00	1.6 #
35	AUTO	REF	REFINISH	R FENDER OUTSIDE			C 1.6
36	AUTO	REF	REFINISH	R FENDER EDGE			0.5
37	200160	BDY	REMOVE/REPLACE	L FENDER PANEL	5003067AC	210.00	1.6 #
38	AUTO	REF	REFINISH	L FENDER OUTSIDE			C 1.6
39	AUTO	REF	REFINISH	L FENDER EDGE			0.5
40	200165	BDY	REMOVE/REPLACE	R FENDER LINER	4580486AC	69.00	0.3 #
41	200166	BDY	REMOVE/REPLACE	L FENDER LINER	4580487AC	53.50	0.3 #
S2 42	201567	BDY	REMOVE/REPLACE	L FENDER LINER EXT		24.25	2.0
43	AUTO	REF	REFINISH	RADIATOR SUPPORT COMPLETE			1.5
44	200177	BDY	REMOVE/REPLACE	UPR FRONT BODY TIE BAR		64.50	1.0
S2 45	200178	BDY	REMOVE/REPLACE	LWR FRONT BODY TIE BAR		56.00	1.0
46	200180	BDY	REMOVE/REPLACE	L FRONT BODY SUPPORT		13.25	1.0
47	200182	BDY	REMOVE/REPLACE	L FRONT BODY HEADLAMP MOUNTING PANEL		N.A.	2.0
48				PAY PER INVOICE			
49	200199	BDY	REPAIR	L FRONT BODY STRUT MTG TOWER		Existing	4.0*#
50	AUTO	REF	REFINISH	L STRUT MOUNTING TOWER			1.0
51				AFTER PULL			
52	200201	BDY	REPAIR	L LWR FRONT BODY SIDERAIL		Existing	2.0*#
53	AUTO	REF	REFINISH	L LWR LOWER SIDERAIL COMPLETE			1.0
54				AFTER PULL			
S3 55	200204	MCH	REMOVE/REPLACE	FRAME SUSP SUBFRAME		485.00	3.4
56	200240	MCH	REMOVE/REPLACE	ABS CONTROL MODULE		545.00	2.7 #
S3 57	200258	MCH	REMOVE/REPLACE	CRUISE CONTROL RESERVOIR		19.25	
58	200271	BDY	REMOVE/REPLACE	WHEEL		Sublet	124.00*
59				LINE MARKUP X25.00		31.00	
60	900500	BDY*	ADD'L LABOR OP	WHEEL WIZARD 770-451-6333		Sublet	0.0*
61	900500	BDY*	REMOVE/REPLACE	TIRE MICH Z25/60R16		New	96.00*
62				LINE MARKUP X25.00		24.00	
63	900500	BDY*	ADD'L LABOR OP	MOUNT & BALANCE		Sublet	12.00*
64	900500	BDY*	REMOVE/REPLACE	FENDER EMBLEM		New	12.00*
S3 65	200294	MCH	REMOVE/REPLACE	R FRT SUSP WHEEL HUB		4593003	153.00 INCL #
S3 66	200313	MCH	REMOVE/REPLACE	R FRT SUSP STEERING KNUCKLE		4782124AB	83.00 1.1 #
S3 67	200317	MCH	REMOVE/REPLACE	R FRT SUSP STRUT ASSY		4782012AB	110.00 0.6 #
S3 68	200345	MCH	REMOVE/REPLACE	R LWR FRT SUSP CONTROL ARM ASSY		4616402	145.00 0.4 #
S3 69	200370	MCH	REMOVE/REPLACE	R DRIVE AXLE SHAFT ASSEMBLY		488251B	385.00 0.2 #
S3 70	200388	MCH	REMOVE/REPLACE	R STEERING TIE ROD END		5003930AA	47.50 0.3 #
71	200401	MCH	REMOVE/REPLACE	STEERING FLUID RESERVOIR		4772456AB	28.75 0.7
S3 72	200513	MCH	REMOVE/REPLACE	MODULE		4606810AM	520.00 0.5

ESTIMATE RECALL NUMBER: 08/24/99 11:33:57 11-3332-30501

UltraMate is a Trademark of Mitchell International

Mitchell Data Version:

OCT_99_B

Copyright (C) 1994,1995 Mitchell International

Page 2 of 6

All Rights Reserved

73	200563	BDY	REMOVE/REPLACE	W/SHIELD WASHER RESERVOIR	5011623AA	28.50	0.8
S2 74	200694	BDY	REPAIR	R ROCKER INNER PANEL	Existing		3.0*
S2 75	200695	BDY	REPAIR	L ROCKER INNER PANEL	Existing		2.0*
S2 76	200696	BDY	REPAIR	FRT FLOOR PANEL	Existing		10.0*#
S2 77	200712	BDY	REMOVE/REPLACE	L FRT ROCKER CLADDING	LG55VTE	143.00	0.3
S2 78	200838	BDY	REMOVE/INSTALL	R FRT SEAT ASSY			0.3
S2 79	200839	BDY	REMOVE/INSTALL	L FRT SEAT ASSY			0.3
80	200940	BDY	REMOVE/REPLACE	R FRT DOOR SNELL	5003226AB	650.00	4.8 #
81	AUTO	REF	REFINISH	R FRT DOOR OUTSIDE			C 2.0
82	AUTO	REF	REFINISH	R FRT ADD FOR JAMBS & INSIDE			C 1.0
83	200941	BDY	REMOVE/REPLACE	L FRT DOOR SNELL	5003227AB	650.00	4.8 #
84	AUTO	REF	REFINISH	L FRT DOOR OUTSIDE			C 2.0
85	AUTO	REF	REFINISH	L FRT ADD FOR JAMBS & INSIDE			C 1.0
86	200953	BDY	REMOVE/REPLACE	L FRT DOOR REAR VIEW MIRROR	4574607AC	97.00	INCL #
87	200957	BDY	REMOVE/REPLACE	L FRT DOOR ADHESIVE MOULDING	PT10VTE	41.75	0.1
88	200972	BDY	REMOVE/REPLACE	R FRT DOOR ADHESIVE NAMEPLATE	4805060	24.25	0.1
89	200973	BDY	REMOVE/REPLACE	L FRT DOOR ADHESIVE NAMEPLATE	4805060	24.25	0.1
90	201090	BDY	REPAIR	R REAR DOOR SHELL	Existing		1.0*
91	AUTO	REF	REFINISH	R REAR DOOR OUTSIDE			C 2.0
92	201091	BDY	REPAIR	L REAR DOOR SNELL	Existing		3.5*
93	AUTO	REF	REFINISH	L REAR DOOR OUTSIDE			C 2.0
94	201098	BDY	REMOVE/REPLACE	R REAR UPR DOOR WINDOW MOULDING	4780120A1	184.00	0.3 #
95	201099	BDY	REMOVE/INSTALL	L REAR UPR DOOR WINDOW MOULDING	Existing		0.3**
96	201100	BDY	REMOVE/INSTALL	R REAR DOOR ADHESIVE MOULDING	Existing		0.2*
97	201103	BDY	REMOVE/REPLACE	L REAR DOOR ADHESIVE MOULDING	PT20VTE	37.25	0.2
98	201137	BDY	REMOVE/INSTALL	L REAR DOOR HANDLE			0.6 #
99	201146	BDY	REMOVE/REPLACE	R REAR DOOR OUTSIDE HANDLE	LF02TCNAB	38.50	0.3 #
100	201214	BDY	REPAIR	ROOF PANEL	Existing		4.5*
101	AUTO	REF	REFINISH	ROOF PANEL			C 2.8
102	201263	REF	BLEND	R QUARTER PANEL OUTSIDE			C 0.9
103	900500	BDY*	REMOVE/REPLACE	RT RENDR MOULDING	New	35.00*	0.4*
104	201288	BDY	REPAIR	L QUARTER OUTER PANEL	Existing		5.5*#
105	AUTO	REF	REFINISH	L QUARTER PANEL OUTSIDE			C 1.8
106	201289	BDY	REMOVE/REPLACE	L QUARTER FUEL DOOR	4575521AE	21.75	0.3 #
107	201517	BDY	REMOVE/REPLACE	L COMBINATION LAMP ASSEMBLY	4780051AG	156.00	0.3
108	201539	BDY	REPAIR	REAR BUMPER COVER	Existing		2.5*
109	AUTO	REF	REFINISH	REAR BUMPER COVER			C 2.3
S1 110	936001		ADD'L COST	TONING		400.00*	
S1 111				MARKUP INCL.			
112	AUTO	REF	ADD'L OPR	CLEAR COAT			4.3
113	933005	BDY	ADD'L OPR	RESTORE CORROSION PROTECTION		10.00*	0.3*
114	AUTO		ADD'L COST	PAINT/MATERIALS		738.00*	

* - Judgement Item
 # - Labor Note Applies
 C - Included in Clear Coat Calc

ESTIMATE RECALL NUMBER: 08/24/99 11:33:57 11-3332-30501

UltraMate is a Trademark of Mitchell International
 Copyright (C) 1994,1995 Mitchell International
 All Rights Reserved

Mitchell Data Version: OCT_99_B

Page 3 of 6

Date: 11/12/99 10:24 A.M.
Estimate ID: 11-3332-30501
Estimate Version: 3
Supplement: 3(P) 11/12/99 07:41:
Profile ID: CUSTOMIZED

ESTIMATE RECALL NUMBER: 08/24/99 11:33:57 11-3332-30501

Mitchell Data Version: OCT_99_B

UltraMate is a Trademark of Mitchell International
Copyright (C) 1994,1995 Mitchell International
All Rights Reserved

Page 4 of 6

I. Labor Subtotals	Units	Rate	Add'l		Totals
			Labor Amount	Sublet Amount	
Body	78.7	32.00	10.00	61.95	2,590.35T
Refinish	36.9	32.00	0.00	8.00	1,168.80T
Mechanical	12.0	65.00	0.00	0.00	780.00T
Taxable Labor					4,559.15
Non-Taxable Labor					0.00
Labor Summary	127.6				4,559.15

II. Part Replacement Summary		Amount
Taxable Parts		7,800.75
Parts Adjustments		24.00
Sales Tax	@ 7.000%	547.73
Non-Taxable Parts		124.00
Parts Adjustments		31.00
Total Replacement Parts Amount		8,527.48

III. Additional Costs		Amount
Taxable Costs		738.00
Sales Tax	@ 7.000%	51.66
Non-Taxable Costs		400.00
Total Additional Costs		1,189.66

IV. Adjustments		Amount
Insurance Deductible		250.00-
Customer Responsibility		250.00-

I. Total Labor:	4,559.15
II. Total Replacement Parts:	8,527.48
III. Total Additional Costs:	1,189.66
Gross Total:	14,276.29
IV. Total Adjustments:	250.00-
Net Total:	14,026.29
Less Original Net Total:	8,942.66
Net Supplement Amount:	5,083.63
S1: CLAYTON DINN	400.00
S2: CLAYTON DINN	2,177.04
S3: CLAYTON DINN	2,506.59

Point(s) of Impact
 11 LEFT FRONT CORNER (P)

Inspection Site: Body, Shop
 Inspection Date: 08/24/99

ESTIMATE RECALL NUMBER: 08/24/99 11:33:57 11-3332-30501

Mitchell Data Version: OCT_99_B

UltraMate is a Trademark of Mitchell International
 Copyright (C) 1994,1995 Mitchell International
 All Rights Reserved

Date: 11/12/99 10:24 A.M.
Estimate ID: 11-3332-30501
Estimate Version: 3
Supplement: 3(P) 11/12/99 07:41:
Profile ID: CUSTOMIZED

Body Shop: NEAL POPE JEEP
Address: 4420 BUFORD HIGHWAY
ATLANTA, GA 30341
Telephone: (770) 455-7673
Fax Phone: (770) 986-6807

NOTICE - REPAIRS TO THIS VEHICLE MAY REQUIRE SPECIFIC WELDING
EQUIPMENT AS RECOMMENDED BY THE MANUFACTURER
REVIEWED BY SHOP MANAGER/ASSISTANT MANAGER X.....
THIS IS NOT AN AUTHORIZATION TO REPAIR. ALL SUPPLEMENTS REQUIRE
PRIOR APPROVAL BY A STATE FARM CLAIM REPRESENTATIVE.

ESTIMATE RECALL NUMBER: 08/24/99 11:33:57 11-3332-30501

Mitchell Data Version: OCT_99_B

UltraMate is a Trademark of Mitchell International
Copyright (C) 1994,1995 Mitchell International
All Rights Reserved

Page 6 of 6

Accident Number 990286	Ag. No. NCIC No. 044079E	GEORGIA UNIFORM MOTOR VEHICLE ACCIDENT REPORT		County DeKalb	Date Rec. By DPS
Date 03/17/99	Day Of Week <input type="checkbox"/> Sun <input type="checkbox"/> M <input checked="" type="checkbox"/> T <input type="checkbox"/> W <input type="checkbox"/> Th <input type="checkbox"/> F <input type="checkbox"/> S	Time 1444	OR. Arrived 1445	Total Number Of: Vehicles 1 Injuries 0 Fatalities 0	Inside City Of: Decatur
Road of Occurrence S. Candler	At Its Intersection With <input type="checkbox"/> Interstate <input type="checkbox"/> Lowest St. Rt. <input type="checkbox"/> Co. Road <input checked="" type="checkbox"/> City St.			Corrected Report Yes <input type="checkbox"/> No <input type="checkbox"/>	
Not At Its Intersection But 100	Of: <input type="checkbox"/> Miles <input type="checkbox"/> North <input type="checkbox"/> East <input checked="" type="checkbox"/> South <input type="checkbox"/> West			Suppl. To Original Yes <input type="checkbox"/> No <input type="checkbox"/>	
And Continuing in the Direction Checked Above The Next Reference Point Is			<input type="checkbox"/> Interstate <input type="checkbox"/> Lowest St. Rt. <input type="checkbox"/> Co. Road <input checked="" type="checkbox"/> City St. <input type="checkbox"/> Co. Line		

Driver # UNKNOWN	Last Name UNKNOWN	First	Middle	Driver # 2	Last Name [REDACTED]	First	Middle
Pad <input type="checkbox"/>	Address			Pad <input type="checkbox"/>	Address		
City	State	Zip	DOB	City Stone Mountain GA	State GA	Zip [REDACTED]	DOB [REDACTED]
Driver's License No.	Class	State	<input type="checkbox"/> Male <input checked="" type="checkbox"/> Female	Driver's License No.	Class C	State GA	<input type="checkbox"/> Male <input type="checkbox"/> Female
Posted Speed	Insurance Co.	Policy No.		Posted Speed 35	Insurance Co. STATE FABM	Policy No.	
Year	Make MAXIMA	Model	Telephone No.	Year 99	Make Chrysler	Model 300M	Telephone No. 770-495-4095
VIN	Vehicle Color Dark Green OR Black			VIN 2C3HE66G5XH625418	Vehicle Color TAN		
Tag #	State	County	Year	Tag #	State GA	County DeKalb	Year 00
Trailer Tag #	State	County	Year	Trailer Tag #	State	County	Year
<input type="checkbox"/> Same as Driver	Owner's Last Name	First	Middle	<input checked="" type="checkbox"/> Same as Driver	Owner's Last Name	First	Middle
Address				Address			
City State Zip				City State Zip			
Removed By <input type="checkbox"/> Request <input type="checkbox"/> List				Removed By STW <input type="checkbox"/> Request <input checked="" type="checkbox"/> List			
Alcohol Test	Type	Results	Drug Test	Type	Results		
Driver Condition	Direction of Travel	Vision Obscured	Contributing Factors		Driver Condition 1	Direction of Travel 1	Vision Obscured 1
Vehicle Condition	Vehicle Maneuver	Pedestrian Maneuver			Vehicle Condition 17	Vehicle Maneuver 5	Pedestrian Maneuver 15
Most Harmful Event	Vehicle Class	Vehicle Type			Most Harmful Event 1	Vehicle Class 1	Vehicle Type 1
Traffic Control	Device Inoperative?	<input type="checkbox"/> Yes <input type="checkbox"/> No			Traffic Control 1	Device Inoperative? <input type="checkbox"/> Yes <input type="checkbox"/> No	

Injured Taken To By:

EMS Notified Time EMS Arrival Time Hospital Arrival Time Photos Taken: Yes No By:

Report By: Department Report Date Checked By: Date Checked

Witness(es) Name Address City State Zip Code Telephone No.
Robertson, Michell 1791 Lyn St Decatur GA 30032 (404)284-1977

DPS MICROFILM NUMBER (DO NOT WRITE IN THIS SPACE)

COMMERCIAL VEHICLES ONLY

Carrier Name Vehicle #	Carrier Name Vehicle #						
Address	Address						
City State Zip	City State Zip						
Number of Axles	G.V.W.R.	Fed. Reportable <input type="checkbox"/> Yes <input type="checkbox"/> No	Cargo Body Type	Number of Axles	G.V.W.R.	Fed. Reportable <input type="checkbox"/> Yes <input type="checkbox"/> No	Cargo Body Type
Vehicle Config.	I.C.C.M.C. #	U.S. D.O.T. #	Interstate <input type="checkbox"/> Intrastate <input type="checkbox"/>	Vehicle Config.	I.C.C.M.C. #	U.S. D.O.T. #	Interstate <input type="checkbox"/> Intrastate <input type="checkbox"/>
C.D.L.? <input type="checkbox"/> Yes <input type="checkbox"/> No	C.D.L. Suspended? <input type="checkbox"/> Yes <input type="checkbox"/> No	Hazardous Materials? <input type="checkbox"/> Yes <input type="checkbox"/> No	Released? <input type="checkbox"/> Yes <input type="checkbox"/> No	C.D.L.? <input type="checkbox"/> Yes <input type="checkbox"/> No	C.D.L. Suspended? <input type="checkbox"/> Yes <input type="checkbox"/> No	Hazardous Materials? <input type="checkbox"/> Yes <input type="checkbox"/> No	Released? <input type="checkbox"/> Yes <input type="checkbox"/> No
If YES, Name or 4 Digit Number from Diamond or Box: 1 Digit Number from Bottom of Diamond:				If YES, Name or 4 Digit Number from Diamond or Box: 1 Digit Number from Bottom of Diamond:			
<input type="checkbox"/> Ran Off Road	<input type="checkbox"/> Down Hill Runaway	<input type="checkbox"/> Cargo Loss Or Shift	<input type="checkbox"/> Separation of Units	<input type="checkbox"/> Ran Off Road	<input type="checkbox"/> Down Hill Runaway	<input type="checkbox"/> Cargo Loss Or Shift	<input type="checkbox"/> Separation of Units

DPS-628 (01/94)

REMARKS

Driver #2 stated that he was travelling north bound in the far right lane when a vehicle travelling in the same direction in the left lane side-swiped his car. He attempted to swerve out of the path of the vehicle. He stated at this point his accelerator stuck and he was unable to stop the vehicle. A witness by the name of Michael Robertson confirmed Driver #2's story about being struck by a black or dark green pickup. Driver #2's vehicle stopped after striking and causing extensive damage to the house located at 120 S. Candler Street.

INDICATE ON THIS DIAGRAM WHAT HAPPENED

INDICATE NORTH

SEE PHOTOS



Accident Investigation Site? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	CITATIONS - VEHICLE #1	CITATIONS - VEHICLE #2
Site Number:		

First Harmful Event	Traffic-Way Flow	Weather	Surface Cond.	Light Condition	Manner Of Collision	Location At Area Of Impact	Road Comp.	Road Details	Road Character
					4				
Number of Occupants		VEH. # 1	VEH. # 2	SKID DISTANCE BEFORE IMPACT		AFTER	Width Of Road		
Point Of Initial Contact		UNK	4	VEH. 1		VEH. 1	36'		
Damage To Vehicles		UNK	4	VEH. 2		VEH. 2			

Damage Other Than Vehicle:	House located at 120 S. Candler	Owner:	Agnes Scott College	AGE	SEX	VEH. NO.	POS.	SALARY	TAKEN FOR TREAT.	SUBGT	SAFETY BOLTP.	EXTRIC.	AIR BAG
Occupants	Driver # 1 Or Pedestrian #												
	Driver # 2 Or Pedestrian #							2	1	3	2	2	
Last Name	First	Address	City	State	Zip								

MAIL 101, SEVENSIA DEPARTMENT OF PUBLIC SAFETY, 101 SEVENSIA DEPARTMENT OF PUBLIC SAFETY, P.O. BOX 101, SEVENSIA, OHIO 43081

