

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

333

Date Received

30-JUN-2000

 Od_or _____
 Rt_dt _____
 Od_rt _____
 Up_ltr _____

Reference No.

864620

 Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) (located at front of vehicle or on driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1GNDX03E3YD284661	ITASCA	ADVENTURER	2000	

Purchase Date	Dealer's Name _____	Engine Size (CID/CCL) _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☐ New ☒ Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☐ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☐ Motorbelt ☐ 2-Point Belt	Cruise Control ☐ Yes ☒ No	Drive Train ☐ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Van ☐ Minivan ☐ Other _____ ☐ Sport Utl ☐ Truck ☐ Motorcycle	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____
--	---	---	--	--	---	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06400000	Part Name(s) ELECTRICAL SYSTEM:FUSE AND FUSE RECEPTACLE	Location ☐ Left ☐ Front ☐ Right ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures	Date(s) of Failure(s) 2C-WA*-2000 Mileage at Failure(s) 2011 Vehicle Speed at Failure(s) _____	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
--	---	---------------------------	----------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WHILE DRIVING EAST ON INTERSTATE 10 TRAFFIC WAS HEAVY AND MOTOR WENT DEAD. PULLED OVER. HAD VEHICLE TOWED TO DEALER. DEALER REPLACED A FUSE. THE WIRE THAT WAS RUBING AGAINST A BOLT OF THE FRAME CAUSED THE SHORT. *AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

 U.S. Department of Transportation National Highway Traffic Safety Administration		DOT Auto Safety Hotline Vehicle Owner's Questionnaire (VOQ) NATIONWIDE 1-888-DASH-2-DOT 1-888-327-4236 www.nhtsa.dot.gov/hotline		FOR AGENCY USE ONLY 333 Date Received 00 JUL 25 AM 11 30 JUN 2000 OFFICE DEFECTS INVESTIGATION Reference No. 864620 Work Number _____ Home Number _____	
OWNER INFORMATION (Type or Print) [Redacted]				Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer. Signature of Owner _____ Date 07/15/2000	
VEHICLE INFORMATION					
Vehicle Ident. No. (VIN) (Located at bottom of windshield on driver's side) 1GNDX03E3YD284661		Vehicle Make CHEVROLET TRUCK		Vehicle Model VENTURE ADVENTURER	
Vehicle Year 2000		Current Odometer Reading 2311 FIRST TIME 2569 2ND TIME			
Purchase Date 04-20-2000		Dealers Name JOH HALL CHEVROLET		Engine Size (CID/CC/L) _____ No Cylinders 6	
☒ New ☐ Used		City DAYTONA BEACH State FL Zip Code 32115			
Transmission Type ☐ Manual ☒ Automatic		Antilock Brakes ☒ Yes ☐ No		Restraint System ☒ 3-Point Belt ☐ Motorbelt ☒ Driverside Airbag ☐ 2-Point Belt ☒ Passengerside Airbag	
Cruise Control ☒ Yes ☐ No		Drive Train ☒ Front ☐ Rear ☐ 4-Wheel		Vehicle Type ☐ Car ☐ Van ☒ Minivan ☐ Other	
Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other					
FAILED COMPONENT(S)/PART(S) INFORMATION					
Component 08400000		Part Name(s) ELECTRICAL SYSTEM:FUSE AND FUSE RECEPTACLE WIRE RUBBED BARE - SHORT IN WIRING		Location ☐ Left ☐ Right ☐ Front ☐ Rear	
No of Failures 2		Date(s) of Failure(s) 26-MAY-2000 28 MAY 2000 Mileage at Failure(s) 2311 - 2569 Vehicle Speed at Failure(s) 60 MPH 65 MPH		Failed Part(s) Available? ☒ Yes ☐ No	
NHTSA Previously Contacted? ☐ Yes ☐ No					
APPLICATION INCIDENT INFORMATION (Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies) on the back of this form)					
Crash ☐ Yes ☒ No		Fire ☐ Yes ☒ No		Number of Persons Injured _____ Number of Fatalities _____ Estimated Property Damage _____ Reported to Police ☐ Yes ☒ No	
NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)					
WHILE DRIVING EAST ON INTERSTATE 10 TRAFFIC WAS HEAVY AND MOTOR WENT DEAD. PULLED OVER. HAD VEHICLE TOWED TO DEALER. DEALER REPLACED A FUSE. (THE WIRE THAT WAS RUBING AGAINST A BOLT OF THE FRAME CAUSED THE SHORT. *AK*) DEALER #2 5-26-00 DEALER #1 REPLACED FUSE AND REFUSED TO CHECK TO SEE WHY FUSE BLEW. 5-28-00 MOTOR AGAIN WENT DEAD WHILE DRIVING IN HEAVY TRAFFIC. TOWED AGAIN TO DIFFERENT DEALER WHO CHECKED TO SEE WHY THE FUSE BLEW AND FOUND THE RUBING WIRE AND FIXED IT. DEALER #1 GERRY LAKE CHEV - BATON ROUGE, LA DEALER #2 PETER MOORE CHEV					
The Privacy Act of 1974-Public Law 93-579 This Information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.					

PESE MOORE CHEV IN PENSACOLA, FLORIDA



**GREAT SERVICE
STARTS HERE!**

PETE MOORE

AUTOMOTIVE TEAM



CHEVY: 103 NEW WARRINGTON ROAD

IMPORTS: 106 NEW WARRINGTON ROAD

PENSACOLA, FLORIDA 32506

CHEVY: (850) 456-7000 • IMPORTS: (850) 457-1000

DISCLAIMER OF WARRANTIES

THE SELLER HEREBY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THE PARTS.

I ACKNOWLEDGE
RECEIPT OF THE
PARTS AND LABOR
LISTED BELOW X

INVOICE TO

DRIVER/OWNER INFORMATION — INVOICE: W67774

FOR OFFICE USE

TAG: 3782 ADV: 114 DAVIS, WA INVOICE: PRELIN WAR W ET
TAX RULES: NYINY INVOICED: 05/29/2000 10:10:05
ODOMETER IN: 2569 OUT: 2569 DIST: 160
DATES BEGIN: 05/29/00 DONE: 05/29/00

VEHICLE INFORMATION

VIN 1GNDX03E3YD284661 LICENSE NUMBER: [REDACTED]
00 CHEVROLET VENTURE AIR XTREME
DATES INSERVICE: 042000

CONCERN	CAUSE	CORRECTION	PART NUMBER	PO#	NOTE	DESCRIPTION	QTY	OPERATION	TECH	HOURS	AMOUNT
51	ENGINE QUITS WHILE DRIVING	CHAFED HARNESS & A/C ACCUMULATOR						NO6604	070	.5	132.50
		REPAIRED WIRE CIRCUIT & RE-ROUTED. CONDITION CORRECTED.								1.9	
			000 012092079			FUSE	3			.96	2.88
			000 012337820			STRAP, I/P	3			.22	.66
		PARTS: COUNT 6									
FACTORY	COMPLAINT : PU				FAIL CODE : 7J						

SUBTOTAL

PARTS	4.95
LABOR	132.50
TOTAL CHARGE FOR CONCERN	137.45

TYPE: W

CONCERN 52 P C M FUSE BLOWS
CAUSE SEE LINE 51
CORRECTION NO CHARGE
FACTORY COMPLAINT : OJ
FP-012092079

FAIL CODE : .

OPERATION	TECH	HOURS	AMOUNT
NC	998	.0 B	.00

SUBTOTAL

TOTAL CHARGE FOR CONCERN	.00
--------------------------	-----

TYPE: W

CONCERN 53 A.B.S. LIGHT COMES ON
CAUSE SEE LINE 51
CORRECTION NO CHARGE
FACTORY COMPLAINT : WA

FAIL CODE : .

OPERATION	TECH	HOURS	AMOUNT
NC	998	.0 B	.00

SUBTOTAL

TOTAL CHARGE FOR CONCERN	.00
--------------------------	-----

TYPE: W

PAGE 1

CUSTOMER COPY



CHEVROLET
6505 FLORIDA BLVD
BATON ROUGE, LA 70806
TEL. (225) 926-4600

Thank You! We Appreciate Your Business!

Thank You! We Appreciate Your Business!