

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

156

Date Received

21-AUG-2000

 Od_or _____
 rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

868201

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) (located at front of vehicle or on driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1HFSK3911XA100213	HONDA MOTORCYCLE	VT1100C3	1999	

Purchase Date	Dealer's Name _____	Engine Size (CID/CC) _____	☐ Turbo
☒ New ☐ Used	City _____ State _____ Zip Code _____	No. Cylinders _____	☐ Diesel
			☐ Gas
			☐ Fuel Injection

Transmission Type	Antilock Brakes	Restraint System	Cruise Control	Drive Train	Vehicle Type	Body Style
☐ Manual ☐ Automatic	☐ Yes ☒ No	☐ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☐ Motorcycle ☐ 2-Point Belt	☐ Yes ☒ No	☐ Front ☐ Rear ☐ 4-Wheel	☐ Car ☐ Van ☐ Minivan ☐ Other	☐ Sport Vlt ☐ Truck ☐ Motorcycle ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06210000	Part Name(s) FUEL CARBURETOR UNKNOWN TYPE	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures	Date(s) of Failure(s) 14-AUG-2000 Mileage at Failure(s) 26 Vehicle Speed at Failure(s) _____	Failed Part(s) Available? Yes No	NHTSA Previously Contacted? Yes No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash	Fire	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police
☐ Yes ☒ No	☐ Yes ☒ No				☐ Yes ☒ No

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE CARBURETOR IS SET TOO "LEAN TO RUN" WHICH IS SET BY THE EPA WHICH CAUSES THE MOTORCYCLE TO STALL UNEXPECTEDLY WHICH MAY RESULT A CRASH. THE DLR SAID THAT THE CONSUMER NEEDS TO "REKIT" THE CARBURETOR WITH RICHARD JET NEEDLES. THE DLR CANNOT MODIFY THE CARBURETOR DUE TO EPA STANDARDS. PLEASE PROVIDE FURTHER INFORMATION.

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.