

 DOT Auto Safety Hotline Vehicle Owner's Questionnaire (VOQ) U.S. Department of Transportation National Highway Traffic Safety Administration NATIONWIDE 1-888-DASH-2-DOT 1-888-327-4236 www.nhtsa.dot.gov/hotline		FOR AGENCY USE ONLY 241	
OWNER INFORMATION (Type or Print) 866729		Date Received 16-JAN-2001	Od_or _____ rt_dt _____ od_rt _____ up_itr _____ Reference No. 878212
		Work Number Home Number	
Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.			
Signature of Owner _____		Date ____/____/____	
VEHICLE INFORMATION			
Vehicle Ident. No. (VIN) (Located at bottom of windshield on driver's side) 3C8FY4BB61T279692		Vehicle Mak CHRYSLER TRUC	Vehicle Mode PT CRUISER
		Vehicle Year 2001	Current Odometer Reading
Purchase Date ☐ New ☒ Used	Dealers Name _____ City _____ State _____ Zip Code _____		Engine Siz (CID/CC/L) _____ No Cylinders _____ ☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injectio
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☒ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Contro ☐ Yes ☒ No
		Drive Trai ☐ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Van ☐ Minivan ☐ Other _____ ☐ Sport Ult ☐ Truck ☐ Motorcycle
		Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☒ Pick Up ☐ Truck	
FAILED COMPONENT(S)/PART(S) INFORMATION			
Component 01150000 09002000 02100000	Part Name(s) STEERING: COLUMN SHAFT UPPER LIGHTING: GENERAL OR UNKNOWN COMPONENT: HEAD LIGHTS SUSPENSION: INDEPENDENT FRONT		Location ☐ Left ☐ Front ☐ Right ☐ Rear
		Failed Part(s) ☐ Original ☐ Replacement	
No of Failures	Date(s) of Failure(s) 14-JUN-2000 Mileage at Failure(s) 16000 Vehicle Speed at Failure(s)		Failed Part(s) ☐ Yes ☐ No
		NHTSA Previously ☐ Yes ☐ No	
APPLICATION INCIDENT INFORMATION			
(Please describe in detail the incident(s), failure(s), crash(es) and injury(ies) on the back of this form)			
Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalitie
		Estimated Property Damag	Reported to Polic ☐ Yes ☒ No
NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)			
1. STEERING WHEEL BECAME LOOSE ON SHAFT WHILE TRAVELING AT 68-70 MPH; 2. HEADLIGHTS WOULD FLICKER FROM BRIGHT TO DIM, AND 3. FRONT WHEELS OUT OF ALIGNMENT. MOST PROBLEM WAS CORRECTED BY DEALER. >> PLEASE FEEL FREE TO PROVIDE ANY FURTHER DETAILS ON THIS MATTER. *AK			
CONTINUE ON BACK IF NEEDED			
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.			