



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY

294

Date Received

12-FEB-2001

Od_or _____
rt_dt _____
pd_rt _____
ip_ltr _____

Reference No.

880364

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner

Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Located at bottom of windshield on driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1G4NY55M7RC265263	BUICK	SKYLARK	1994	

Purchase Date ☒ New ☐ Used	Dealer's Name _____ City _____ State _____ Zip Code _____	Engine Size _____ (CID/CCL) _____ No Cylinders _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
--	--	--	--

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☐ Yes ☒ No	Drive Train ☐ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____
--	---	---	--	--	---	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 09540000	Part Name(s) COMMUNICATIONS:HORN ASSEMBLY:WIRE:HORN:FUSIBLE	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures	Date(s) of Failure(s) Mileage at Failure(s) 87 Vehicle Speed at Failure(s)	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
--	---	---------------------------	----------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WHEN COLD LEATHER CONTRACTS AROUND STEERING WHEEL, CAUSING HORN TO GO OFF.
OWNER HAD TO DISCONNECT FUSE TO HORN ASSEMBLY. MANUFACTURE HAS BEEN NOTIFIED.*AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond. This questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT
1-888-327-4236
www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 284

Date Received

11 MAR -5 PM 4:20
12-FEB-2001
OFFICE
OF THE
SAFETY INVESTIGATION

Od or

R dt

od rt

up_ltr

Reference No.

880364

OWNER INFORMATION (Type or Print)

674166

Work Number

Home Number

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?

☐ YES☒ NO

In the absence of an authorization, NHTSA will not provide your name and address to the vehicle manufacturer.

Signature of Owner

Date 2/20/01

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Located at bottom of windshield on driver's side)		Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1G4NV55M7RC265263		BUICK	SKYLARK	1994	95966
Purchase Date	Dealer's Name		Engine Size (CID/CC/L)	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection	
☒ New ☐ Used	City _____ State _____ Zip Code _____		No Cylinders 6		
Transmission Type	Antilock Brakes	Restraint System	Cruise Control	Drive Train	Vehicle Type
☐ Manual ☒ Automatic	☐ Yes ☒ No	☒ 3-Point Belt ☐ Motorbelt ☒ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	☒ Yes ☐ No	☒ Front ☐ Rear ☐ 4-Wheel	☒ Car ☐ Sport Utr ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other
					Body Style
					☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 89640000	Part Name(s) COMMUNICATIONS:HORN ASSEMBLY:WIRE:HORN:FUSIBLE	Location ☐ Left ☒ Front ☐ Right ☐ Rear	Failed Part(s) ☒ Original ☐ Replacement
No of Failures 5-10	Date(s) of Failure(s) Nov + Dec. of 2000 Mileage at Failure(s) 87 Vehicle Speed at Failure(s) parked	Failed Part(s) Available? ☐ Yes ☒ No	NHTSA Previously Contacted? ☐ Yes ☒ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
--	---	---------------------------	----------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WHEN COLD, LEATHER CONTRACTS AROUND STEERING WHEEL, CAUSING HORN TO GO OFF. OWNER HAD TO DISCONNECT FUSE TO HORN ASSEMBLY. MANUFACTURE HAS BEEN NOTIFIED.*AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.