



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 117

Date Received

23-MAR-2001

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

884047

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield or driver's side)		Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1FMDU34X7TUA48912		FORD TRUCK	EXPLORER	1996	
Purchase Date	Dealer's Name _____		Engine Size (CID/CC/L _____)	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection	
☐ New ☒ Used	City _____ State _____ Zip Code _____		No Cylinders _____		
Transmission Type	Antilock Brakes	Restraint System	Cruise Control	Drive Train	Vehicle Type
☐ Manual ☐ Automatic	☐ Yes ☒ No	☒ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☐ Motorbelt ☐ 2-Point Belt	☐ Yes ☒ No	☐ Front ☐ Rear ☐ 4-Wheel	☐ Car ☐ Van ☐ Minivan ☐ Other _____ ☐ Sport Utl ☐ Truck ☐ Motorcycle
					Body Style
					☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 09301000	Part Name(s) LIGHTING:FUSE:HIGH/LOW BEAM DIMMER	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure	Date(s) of Failure(s) 05-MAR-2001 110 Mileage at Failure(s) _____	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
--	---	---------------------------	----------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

LOW BEAM ON HEADLIGHTS FAIL TO COME ON. OTHER LIGHTS WORKING. CONTACTED MANUFACTURER AND INFORMED NO RECALLS. TOOK TO INDEPENDENT MECHANIC, AND LOW BEAM WAS REPAIRED. INFORMED HAD A SHORT IN ELECTRICAL WIRING. MECHANIC COULD SMELL BURNING WIRES.*AK

COPIES OF REPORTS - FREE -

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 117

Date Received

23-MAR-2001

Od_or

stck

od_rt

up_ltr

Reference No.

884047

OWNER INFORMATION (Type or Print)

582439

Work Number

Home Number

Do you authorize NHTSA
to the absence of an
Signature of Owner

to the manufacturer of your vehicle?
provide your name and address to the vehicle manufacturer.

☒ YES

☐ NO

Date 4/17/2001

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) (Located at bottom of

Vehicle Make

Vehicle Model

Vehicle Year

Current Odometer Reading

FORD TRUCK

EXPLORER

1996

Purchase Date

Dealer's Name

Thomas Ford

Engine Size

4.0

(CID/CC/L

☐ Turbo

☐ Diesel

☒ Gas

☐ Fuel Injection

☐ New ☒ Used

City

Beverly

State

MASS

Zip Code

01915

Transmission Type

Antilock Brakes

Restraint System

Cruise Control

Drive Train

Vehicle Type

Body Style

☐ Manual

☒ Yes

☒ 3-Point Belt

☐ Motorbelt

☒ Yes

☐ Front

☐ Car

☒ Sport Ut

☐ 2-Door

☒ Automatic

☒ No

☒ Driverside Airbag

☐ 2-Point Belt

☒ No

☐ Rear

☒ 4-Wheel

☐ Van

☒ 4-Door

☒ Passengerside Airbag

☐ Minivan

☐ Motorcycle

☐ Stationwagon

☐ Pick Up Truck

☒ Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Component
09301000

Part Name(s)

LIGHTING:FUSE:HIGH/LOW BEAM DIMMER

Location

☐ Left

☐ Right

☐ Front

☐ Rear

Failed Part(s)

☐ Original

☐ Replacement

No of Failures

Date(s) of Failure(s) 05-MAR-2001

Mileage at Failure(s) 110

Vehicle Speed at Failure(s) 0

Failed Part(s)
Available?

☒ Yes ☐ No

NHTSA Previously
Contacted?

☐ Yes ☒ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash

Fire

Number of Persons Injured

Number of Fatalities

Estimated Property Damage

Reported to Police

☐ Yes ☒ No

☐ Yes ☒ No

0

0

0

☐ Yes ☒ No

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

LOW BEAM ON HEADLIGHTS FAIL TO COME ON. OTHER LIGHTS WORKING. CONTACTED MANUFACTURER AND INFORMED NO RECALLS. TOOK TO INDEPENDENT MECHANIC, AND LOW BEAM WAS REPAIRED. INFORMED HAD A SHORT IN ELECTRICAL WIRING. MECHANIC COULD SMELL BURNING WIRES.*AK

NO Low beam Headlights. Short in Electrical wiring.

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.