



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 758

Date Received

08-MAY-2001

Od_or _____
rt_dt _____
od_rt _____
ip_lr _____

Reference No.

887697

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side) 4UZ6XFB8VC759657	Vehicle Make FLEETWOOD	Vehicle Model DISCOVERY	Vehicle Year 1997	Current Odometer Reading _____
Purchase Date ☐ New ☒ Used	Dealer's Name _____ City _____ State _____ Zip Code _____		Engine Size (CID/CC/L) _____ No Cylinders _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
Transmission Type ☐ Manual ☒ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☐ Rear ☐ 4-Wheel
Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____		Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____		

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 08310000 09201000	Part Name(s) ELECTRICAL SYSTEM:WIRING:HARNES:FRONT:UNDERHOOD LIGHTING:LAMP OR SOCKET:HIGH/LOW BEAM DIMMER	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure	Date(s) of Failure(s) 01-NOV-2000 Failure(s) 22000 Mileage at Failure(s) _____	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
--	---	---------------------------	----------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WHEN HEADLIGHTS WERE TURNED ON ELECTRICAL WIRING AND HEADLIGHT SWITCH STARTED MELTING, THERE WAS SMOKE UNDER DASH. CONSUMER COULD ONLY DRIVE DURING DAY TIME.*AK

COPIES OF REPORTS - FREE -

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 758

Date Received

01 JUN 12 PM
08-MAY-2001OFFICE
DEFECTS INVESTIGATION

Od_or

Al_or

od_or

up_lr

Reference No.

887697

Work Number

Home Number

OWNER INFORMATION (Type or Print)

690929

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?

☒ YES☐ NO

In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner

Date 6/5/01

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Located at bottom of windshield on driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
4UZ6XFB8VC759657	FLEETWOOD	DISCOVERY	1997	25732

Purchase Date 9-30-00	Dealer's Name General RV	Engine Size (CID/CCIL) 222	☒ Turbo ☒ Diesel ☐ Gas ☐ Fuel Injection
☐ New ☒ Used	City Mt. Clemens	State MT	Zip Code 48043

Transmission Type ☐ Manual ☒ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Van ☐ Sport Util ☐ Truck ☐ Minivan ☒ Motorcycle ☒ Other RV	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other RV
---	---	---	--	--	---	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 08310000 09201000	Part Name(s) ELECTRICAL SYSTEM: WIRING: HARNESS: FRONT UNDERHOOD LIGHTING: LAMP OR SOCKET: HIGH/LOW BEAM DIMMER	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☒ Original ☐ Replacement
-----------------------------------	---	--	--

No. of Failures 2	Date(s) of Failure(s) 01-NOV-2000	Mileage at Failure(s) 22000	Vehicle Speed at Failure(s) 45	Failed Part(s) Available? ☐ Yes ☒ No	NHTSA Previously Contacted? ☐ Yes ☐ No
----------------------	--------------------------------------	--------------------------------	-----------------------------------	--	---

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage 0	Reported to Police ☐ Yes ☒ No
--	---	--------------------------------	---------------------------	--------------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WHEN HEADLIGHTS WERE TURNED ON ELECTRICAL WIRING AND HEADLIGHT SWITCH STARTED MELTING, THERE WAS SMOKE UNDER DASH. CONSUMER COULD ONLY DRIVE DURING DAY TIME. *AK

Lights went out. We were on a winding road on side of a mountain at night.

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.