



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 758

Date Received

12-JUL-2001

Od_or

rt_dt

od_rt

ip_lr

Reference No.

892595

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner

Date

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
2FALP74W4VXI69808	FORD	CROWN VICTORI	1997	
Purchase Date ☐ New ☒ Used	Dealer's Name		Engine Size (CID/CC/L)	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
	City		No Cylinders	
	State	Zip Code		
Transmission Type ☐ Manual ☒ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☐ Rear ☐ 4-Wheel
Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other			

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 02152000	Part Name(s) SUSPENSION:INDEPENDENT FRONT CONTROL ARM:LOWER:BALL JOINT	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure	Date(s) of Failure(s) 10-JUL-2001 88000 Mileage at Failure(s)	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
--	---	---------------------------	----------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WHILE DRIVING 5 MPH VEHICLE DROPPED ON RIGHT SIDE. TOWED TO DEALER, AND LOWER BALL JOINT WAS REPLACED. *AK

COPIES OF REPORTS ARE AVAILABLE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

DOT Auto Safety Hotline Vehicle Owner's Questionnaire (VOQ) NATIONWIDE 1-888-DASH-2-DOT 1-888-327-4236 www.nhtsa.dot.gov/hotline		FOR AGENCY USE ONLY 753	
		Date Received 01 AUG 17 AM 11:00 DEFFECTS INVESTIGATION OFFICE Od. or rt. dr. 02 od. rt. 02 Ref. No. 892595	
OWNER INFORMATION (Type or Print)			
		702098	
Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☒ YES ☐ NO In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.			
Signature of Owner _____		Date _____	
VEHICLE INFORMATION			
Vehicle Ident. No. (VIN) (Located at bottom of windshield on driver's side) 2FALP74W4VX169808		Vehicle Make FORD	Vehicle Model CROWN VICTORI
		Vehicle Year 1997	Current Odometer Reading 88,000
Purchase Date 2/98 ☐ New ☒ Used	Dealer's Name Malif Ford City N. Brunswick State NJ Zip Code 08904		Engine Size (CID/CC/L) 4.6 No Cylinders 8 ☐ Turbo Diesel Gas Fuel Injection
Transmission Type ☐ Manual ☒ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☒ 3-Point Belt ☐ Motorbelt ☒ Driverside Airbag ☐ 2-Point Belt ☒ Passengerside Airbag	Cruise Control ☒ Yes ☐ No
		Drive Train ☐ Front ☒ Rear ☐ 4-Wheel	Vehicle Type ☒ Car ☐ Sport Ut ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other
		Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other	
FAILED COMPONENT(S)/PART(S) INFORMATION			
Component 02152000	Part Name(s) SUSPENSION INDEPENDENT FRONT CONTROL ARM LOWER BALL		Location ☐ Left ☒ Right ☒ Front ☐ Rear
		Failed Part(s) ☒ Original ☐ Replacement	
No of Failures	Date(s) of Failure(s) 10-JUL-2001 Mileage at Failure(s) 88000 Vehicle Speed at Failure(s)		Failed Part(s) Available? ☐ Yes ☒ No
		NHTSA Previously Contacted? ☐ Yes ☐ No	
APPLICATION INCIDENT INFORMATION (Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies) on the back of this form)			
Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0
		Estimated Property Damage 500	Reported to Police ☐ Yes ☒ No
NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)			
WHILE DRIVING 5 MPH VEHICLE DROPPED ON RIGHT SIDE. TOWED TO DEALER, AND LOWER BALL JOINT WAS REPLACED. *AK			
CONTINUE ON BACK IF NEEDED			
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.			