



5-13-00

WOULD LIKE TO REPORT THE FAILURE OF THE GASKET BETWEEN THE BODY & TAIL LIGHT ASSY. IT ALLOWS WATER TO ENTER THREW THE BACK SIDE OF THE TAIL LIGHTS INTO THE SPARE TIRE WELL, JACK WELL. I.V MY CASE THERE WAS 4 1/2" OF WATER IN BOTH AREAS & CAUSED ~~THE~~ A SHORT FOR THE SAFETY RELAY SWITCH FOR THE FUEL PUMP & TAIL LIGHTS. THIS STANDING WATER COULD ALSO CAUSE HEALTH PROBLEMS FROM MOLD SPORE, COULD CAUSE THE RUSTING OUT OF THE SPARE TIRE WELL ETC. I DISCOVERED THIS PROBLEM AFTER I STOPPED GARAGING THIS CAR.

