



Toyota Customer Services

Toyota Motor Sales, U.S.A., Inc.
19001 South Western Avenue, S207
Torrance, CA 90509

December 3, 2009

Associate Administrator for Enforcement
National Highway Traffic Safety Administration
U.S. Department of Transportation
1200 New Jersey Avenue S.E.
Washington, DC 20590

Gentlemen:

Pursuant to Section 579.5, Chapter V, Title 49, enclosed is one copy of each document sent during the month of November 2009:

TOYOTA TECHNICAL SERVICE BULLETIN

1 NUMBER: T-SB- 0373-09
SECTION: Automatic Transmission/Transaxle
DATE: November 3, 2009
MODEL: '09 Tacoma

2 NUMBER: T-SB- 0374-09
SECTION: Lighting (ext)
DATE: November 3, 2009
MODEL: '06-'09 Prius

3 NUMBER: T-SB- 0375-09
SECTION: Battery/Charging
DATE: November 3, 2009
MODEL: '09 RAV4

4 NUMBER: T-SB- 0376-09
SECTION: Emission Control
DATE: November 4, 2009
MODEL: '10 Sienna

5 NUMBER: T-SB- 0377-09
SECTION: Interior Panels/Trim
DATE: November 5, 2009
MODEL: '09 Venza

6 NUMBER: T-SB- 0053-09 Rev1
SECTION: Seat Belt
DATE: November 5, 2009
MODEL: '10 4Runner, Avalon, Camry, Camry HV, Corolla, FJ Cruiser, Highlander, Highlander HV, Land Cruiser, Matrix, Prius, RAV4, Sequoia, Sienna, Tacoma, Tundra, Yaris

7 NUMBER: T-SB- 0294-09 Rev1
SECTION: Pre-Delivery Service
DATE: November 9, 2009
MODEL: '10 4Runner

8 NUMBER: T-SB- 0378-09
SECTION: Heating/Air Conditioning
DATE: November 10, 2009
MODEL: '06-'09 RAV4

9 NUMBER: T-SB- 0379-09
SECTION: Heating/Air Conditioning
DATE: November 10, 2009
MODEL: '07-'09 FJ Cruiser

10 NUMBER: T-SB- 0380-09
SECTION: Heating/Air Conditioning
DATE: November 10, 2009
MODEL: '05-'10 Tacoma

11 NUMBER: T-SB- 0381-09
SECTION: Transfer/4wd/Awd
DATE: November 16, 2009
MODEL: '09-'10 Matrix, Venza
'06-'10 RAV4

12 NUMBER: T-SB- 0383-09
SECTION: Body Structure
DATE: November 18, 2009
MODEL: '07-'08 Avalon

13 NUMBER: T-SB- 0067-08 Rev1
SECTION: Audio/Video
DATE: November 18, 2009
MODEL: '06-'09 4Runner, Prius
'07 Camry, Camry HV, FJ Cruiser,
'06-'08 RAV4
'07-'08 Solara, Yaris

14 NUMBER: T-SB- 0085-08 Rev1
SECTION: Audio/Video
DATE: November 18, 2009
MODEL: '08-'09 Camry, Camry HV, Highlander,
Highlander HV, Sequoia
'08 Solara
'07-'09 Tundra

15 NUMBER: T-SB- 0384-09
SECTION: Heating/Air Conditioning
DATE: November 19, 2009
MODEL: '09-'10 Corolla

16 NUMBER: T-SB- 0385-09
SECTION: Clutch
DATE: November 23, 2009
MODEL: '07-'10 FJ Cruiser
'05-'10 Tacoma

17 NUMBER: T-SB- 0386-09
SECTION: Heating/Air Conditioning
DATE: November 23, 2009
MODEL: '09-'10 RAV4

18 NUMBER: T-SB- 0387-09
SECTION: Heating/Air Conditioning
DATE: November 23, 2009
MODEL: '10 Prius

19 NUMBER: T-SB- 0388-09
SECTION: Heating/Air Conditioning
DATE: November 25, 2009
MODEL: '09-'10 RAV4

20 NUMBER: T-SB- 0389-09
SECTION: Steering Column
DATE: November 30, 2009
MODEL: '05-'09 Avalon

21 NUMBER: T-SB- ST002-06 **OBSOLETE**
SECTION: Steering
DATE: November 30, 2009
MODEL: '05-'06 Avalon

SCION TECHNICAL SERVICE BULLETIN

1 NUMBER: S-SB- 0049-09
SECTION: Body Structure
DATE: November 5, 2009
MODEL: '08 xB

2 NUMBER: S-SB- 0030-09 Rev1
SECTION: Engine Control
DATE: November 19, 2009
MODEL: '05-'10 tC

3 NUMBER: S-SB- NV001-08 **OBSOLETE**
SECTION: NVH
DATE: November 5, 2009
MODEL: '08 xB

LEXUS TECHNICAL SERVICE BULLETIN

1 NUMBER: L-SB- 0153-09
SECTION: Interior Panels/Trim
DATE: November 6, 2009
MODEL: '07-'09 ES350

2 NUMBER: L-SB- 0154-09
SECTION: Heating/Air Conditioning
DATE: November 10, 2009
MODEL: '06-'08 GX470

3 NUMBER: L-SB- 0155-09 SECTION: Brake (front) DATE: November 10, 2009 MODEL: '07-'08 GS350, GS450H '06-'07 GS430 '08-'09 GS460 '06-'09 IS250, IS350	4 NUMBER: L-SB- 0156-09 SECTION: Pre-Delivery Service DATE: November 12, 2009 MODEL: '10 LS600H
5 NUMBER: L-SB- 0157-09 SECTION: Pre-Delivery Service DATE: November 12, 2009 MODEL: '10 LS600H	6 NUMBER: L-SB- 0158-09 SECTION: Pre-Delivery Service DATE: November 12, 2009 MODEL: '10 LS600H
7 NUMBER: L-SB- 0159-09 SECTION: Pre-Delivery Service DATE: November 12, 2009 MODEL: '10 LS600H	8 NUMBER: L-SB- 0160-09 SECTION: Pre-Delivery Service DATE: November 12, 2009 MODEL: '10 LS600H
9 NUMBER: L-SB- 0161-09 SECTION: Pre-Delivery Service DATE: November 12, 2009 MODEL: '10 LS600H	10 NUMBER: L-SB- 0162-09 SECTION: Pre-Delivery Service DATE: November 12, 2009 MODEL: '10 LS600H
11 NUMBER: L-SB- 0163-09 SECTION: Pre-Delivery Service DATE: November 12, 2009 MODEL: '10 LS600H	12 NUMBER: L-SB- 0164-09 SECTION: Pre-Delivery Service DATE: November 12, 2009 MODEL: '10 LS600H
13 NUMBER: L-SB- 0165-09 SECTION: Pre-Delivery Service DATE: November 12, 2009 MODEL: '10 LS600H	14 NUMBER: L-SB- 0166-09 SECTION: Pre-Delivery Service DATE: November 12, 2009 MODEL: '10 LS600H
15 NUMBER: L-SB- 0167-09 SECTION: Transfer/4wd/Awd DATE: November 16, 2009 MODEL: '10 RX350	16 NUMBER: L-SB- 0168-09 SECTION: Engine Control DATE: November 18, 2009 MODEL: '06 GS300, GS430
17 NUMBER: L-SB- 0169-09 SECTION: Audio/Video DATE: November 18, 2009 MODEL: '07-'09 ES350, LS460 '08-'09 IS F, LS600H '06-'09 IS250, IS350	18 NUMBER: L-SB- 0170-09 SECTION: Automatic Transmission/Transaxle DATE: November 18, 2009 MODEL: '08 GS350, IS350
19 NUMBER: L-SB- 0171-09 SECTION: Door/Hatch DATE: November 19, 2009 MODEL: '03-'06 GX470	20 NUMBER: L-SB- 0172-09 SECTION: Pre-Delivery Service DATE: November 24, 2009 MODEL: '10 GX460
21 NUMBER: L-SB- 0173-09 SECTION: Pre-Delivery Service DATE: November 24, 2009 MODEL: '10 GX460	22 NUMBER: L-SB- 0174-09 SECTION: Pre-Delivery Service DATE: November 24, 2009 MODEL: '10 GX460

21 NUMBER: L-SB- 0175-09
SECTION: Pre-Delivery Service
DATE: November 24, 2009
MODEL: '10 GX460

22 NUMBER: L-SB- 0176-09
SECTION: Pre-Delivery Service
DATE: November 24, 2009
MODEL: '10 GX460

23 NUMBER: L-SB- 0177-09
SECTION: Heating/Air Conditioning
DATE: November 25, 2009
MODEL: '10 RX350

24 NUMBER: L-SB- 0121-08 Rev2 **OBSOLETE**
SECTION: Brake (front)
DATE: November 10, 2009
MODEL: '07-'08 GS350, GS450H
'06-'07 GS430
'08 GS460
'06-'08 IS250, IS350

REGION/DISTRIBUTOR LETTER

- 1 LSC 90D - Limited Service Campaign for 2001-2004 Model Year Tacoma's Kentucky Dealer Information Packet
- 2 LSC 90D - Limited Service Campaign for 2001-2004 Model Year Tacoma's Rhode Island Dealer Information Packet
- 3 LSC 90D - Limited Service Campaign for 2001-2004 Model Year Tacoma's Illinois Dealer Information Packet
- 4 Owner Renotification of Non-Completed Service Campaigns - 90A, 90B and 90C
- 5 Toyota Consumer Safety Advisory. Safety Campaign (Special Service Campaign) - 90L Dealer Notification on Potential Floor Mat Interference with Accelerator Pedal
- 6 Toyota Consumer Safety Advisory. Certain 2000 - 2003 MY Toyota Tundra Vehicles in Severe Cold Climate States Excessive Corrosion of the Rear Cross-Member (Spare Tire Carrier)

DEALER LETTER

- 1 LSC 90D - Limited Service Campaign for 2001-2004 Model Year Tacoma's Kentucky Dealer Information Packet
- 2 LSC 90D - Limited Service Campaign for 2001-2004 Model Year Tacoma's Rhode Island Dealer Information Packet
- 3 LSC 90D - Limited Service Campaign for 2001-2004 Model Year Tacoma's Illinois Dealer Information Packet
- 4 Owner Renotification of Non-Completed Service Campaigns - 90A, 90B and 90C
- 5 Toyota Consumer Safety Advisory. Safety Campaign (Special Service Campaign) - 90L Dealer Notification on Potential Floor Mat Interference with Accelerator Pedal

- 6 Toyota Consumer Safety Advisory. Certain 2000 - 2003 MY Toyota Tundra Vehicles in Severe Cold Climate States Excessive Corrosion of the Rear Cross-Member (Spare Tire Carrier)


ELECTRONIC COMMUNICATION

- 1 Owner Renotification of Non-Completed Service Campaigns - 9LA, 9LB and 9LC
- 2 Owner Renotification of Non-Completed Service Campaigns - 90A, 90B and 90C
- 3 Filing of Defect Investigation Report. Certain 2000 - 2003 MY Toyota Tundra Vehicles in Severe Cold Climate States Excessive Corrosion of the Rear Cross-Member (Spare Tire Carrier)
- 4 Special Service Campaign (SSC) - 40G. (2001 to Mid-2003 MY Prius HV Battery Modification Chemical Update)
- 5 Special Service Campaign (Safety Recall). Certain 2000 - 2003 MY Toyota Tundra Vehicles in Severe Cold Climate States Excessive Corrosion of the Rear Cross-Member (Spare Tire Carrier)
- 6 Toyota Consumer Safety Advisory. Certain 2000 - 2003 MY Toyota Tundra Vehicles in Severe Cold Climate States Excessive Corrosion of the Rear Cross-Member (Spare Tire Carrier)
- 7 Safety Campaign (Special Service Campaign) - 9LG
Dealer Notification on Potential Floor Mat Interference with Accelerator Pedal
- 8 Safety Campaign (Special Service Campaign) - 90L
Dealer Notification on Potential Floor Mat Interference with Accelerator Pedal

If you require further copies or information, please contact this office.

Respectfully,

TOYOTA MOTOR SALES, U.S.A., INC.



George Morino
National Quality Compliance Manager

/dg

Enclosures