# FIELD TECHNICAL REPORT



TQCN_FTR-082340025		Affiliate TMS	Dept. Vehicle &	e & FTS	Location AREA-CENTRAL		Ref 82473575	Date 09/03/2008
Problem Area PPO/DIO-TMS	Primary M	lodel	Model Year 2008	1	Production Date 2008-02-08	Odor 372		17 characters): 62885
Condition Title Gas pedal gets s	tuck on w	inter floor n	nat					

Do not type in YELLOW shaded fields - This data is auto-populated from the TQCN system:

Repair Date	Optional Ref.	Optional Approval	Ch	frame of the same
8/1/2008			Dan	PYHEIRER
		and the	grant,	

# **Condition Description**

Customer states that his IS-F had an unintended acceleration.

630-505-4355

# **Diagnostic Steps:**

The technician confirmed that the gas pedal got caught by the floor mat on hard acceleration. The winter floor mat was not attached to the hold down clips.

# **Probable Cause**

The winter floor mat was not clipped in position and so physically interfered with the pedals arc of return.

Part#1:	Part # 2:	Part # 3:	Parts Disposition:	Parts Shipping Destination:
[이 시작 기업 및 기업 및 기업 및 경험 기업	그들 이 하는 하는 이번 때문을 하는 것이 없는데 없다.			[1일 그리고 기계 집안 10 12 12 12 12 12 12 12 12 12 12 12 12 12

#### Repair Process

The technician repositioned and clipped the mat down with the factory hold down clips.







The pedal is held down by the out of position winter floor mat.