



GENERAL MOTORS LLC
Global Interior and Safety Center

July 30, 2010

Mr. Daniel C. Smith
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Recall Management Division (NVS-215)
1200 New Jersey Avenue, SE – Room W45-306
Washington, D.C. 20590

Dear Mr. Smith:

The following information is submitted pursuant to the requirements of 49 CFR Part 579.11. General Motors has decided to conduct a Safety Recall involving certain 2010 model year Chevrolet Silverado trucks.

This Safety Recall involves vehicles that were manufactured and sold outside of the United States. General Motors sold substantially similar trucks in the United States. Please contact me if you have any further questions concerning this report.

Vehicles identified in this letter as "substantially similar" under the broad definition specified in 49 CFR Part 579, can have significant differences in design, performance, durability, etc. These trucks may not be "substantially similar" except for purposes of reporting under 49 CFR Part 579.

Sincerely,

Gay P. Kent
Director, Product Investigations
and Safety Regulations

2010 -3 N100237 FR 579 Letter
Attachment



GENERAL MOTORS CORPORATION

579.11 REPORT

MANUFACTURER:	General Motors LLC
MAKE:	Chevrolet
MODEL & YEAR:	Certain 2010 Model Year (MY) Chevrolet Silverado 1500 Light Duty Pickup Trucks.
NUMBER OF VEHICLES:	3,641 Trucks (Produced from September 8, 2009 through June 25, 2010.)
ACTION TYPE DETERMINATION:	Safety Recall
CONDITION:	Certain Chevrolet Silverado pickup trucks produced at the Silao Assembly Plant in Mexico, with a manual transmission, may have a condition where the fuel lines may come in contact with the under body of the truck. This contact is the result of the assembler selecting the incorrect lower bolt bracket hole, in place of the correct upper bolt bracket hole (assembler did not follow work instruction). This fuel line contact with the under body, caused by the assembler's incorrect attachment of the fuel lines to the manual transmission, could result in a fuel leak with the potential for a vehicle fire.
CORRECTION:	A Safety Recall will be conducted to inspect the fuel lines for proper routing, and re-replace and reroute any improperly routed fuel lines.
DATE OF DETERMINATION:	July 23, 2010
ACTION COMMENCED:	Scheduled August 2010
COUNTRIES INVOLVED:	Mexico
SUBSTANTIALLY SIMILAR U.S. VEHICLE:	2010 MY Chevrolet Silverado and GMC Sierra Trucks
COMMENT:	2010 MY Chevrolet Silverado 1500 Light Duty Pickup Trucks with a manual transmission produced at Silao Assembly in Mexico are not exported to the United States. Therefore, there are no involved vehicles in the United States.