



---

**NISSAN NORTH AMERICA, INC.**

Corporate Headquarters  
One Nissan Way  
Franklin, TN 37068

Mailing Address: P.O. Box 685001  
Franklin, TN 37068-5001

Telephone: 615.725.1000

November 3, 2010

Associate Administrator for Safety Assurance  
National Highway Traffic Safety Administration  
Attention: Early Warning Division (NVS-217)  
Room 217  
1200 New Jersey Avenue, SE  
Washington, D.C. 20590

Dear Associate Administrator:

We are transmitting the enclosed Report of a Defect in a Vehicle in a Foreign Country.

Very truly,

John Gibbons  
Senior Manager  
Technical Compliance

Encl.

**REPORT OF A SAFETY RECALL OR OTHER SAFETY CAMPAIGN  
IN A FOREIGN COUNTRY**

**1. Manufacturer**

Nissan Motor Company, Ltd. Japan.

**2. Vehicles Potentially Involved**

Certain 2008 to 2011 Model year Nissan and Infiniti vehicles shown in the table below:

<b><u>Model Year</u></b>	<b><u>Model</u></b>	<b><u>Manufacturing Date</u></b>
2008-2011	Nissan Murano	July 2, 2007 to August 28, 2010
2008-2011	Infiniti EX35	July 28, 2007 to August 27, 2010
2009-2011	Infiniti FX35/50	November 20, 2007 to August 26, 2010
2011	Infiniti QX56	April 12, 2010 to September 8, 2010

No vehicles sold in the United States are affected because they are not equipped with daytime running lights.

**3. Total Number of Vehicles Potentially Involved**

Approximately 19,565.

<b><u>Model Year</u></b>	<b><u>Model</u></b>	<b><u>Number of Vehicles (Approximately)</u></b>
2008-2011	Nissan Murano	10,928
2008-2011	Infiniti EX35	5,975
2009-2011	Infiniti FX35/50	2,568
2011	Infiniti QX56	94

4. Description of the Defect

The filament in the bulb of the daytime running light may burn out due to a shorter lifespan than expected. Should both daytime running light bulbs burn out, this may result in the vehicle being less visible to other drivers

5. Foreign Country in which the Safety Recall or Other Safety Campaign is Being Conducted

Canada.

6. Date of Determination

October 27, 2010

7. Determination Made By

Manufacturer

8. Date the Recall or Other Campaign will Commence

December, 2010

9. Descriptive of Corrective Action

Owners of all potentially affected vehicles will be notified to take their vehicle to a Nissan or Infiniti dealer. The daytime running light bulbs will be replaced with a long life type bulb.

10. Vehicles in the United States (If known)

The following vehicles sold in the U.S. are on a similar "platform" as the Infiniti EX35, FX35 and FX50 vehicles sold in Canada:

Model year 2008-2011 Infiniti EX35;  
Model year 2009-2011 Infiniti FX35 and FX50;  
Model year 2008-2011 Infiniti G37;  
Model year 2009-2011 Nissan 370Z and;  
Model year 2011 Infiniti M37 and M50.

The following vehicles sold in the U.S. are on a similar "platform" as the Nissan Murano sold in Canada:

Model year 2008-2011 Nissan Murano;  
Model year 2007-2011 Nissan Altima and;  
Model year 2009-2011 Nissan Maxima.

The following vehicles sold in the U.S. are on a similar "platform" as the Infiniti QX56 sold in Canada:

Model year 2011 Infiniti QX56;  
Model year 2004-2010 Infiniti QX56;  
Model year 2004-2011 Nissan Titan;  
Model year 2004-2011 Nissan Armada;  
Model year 2005-2011 Nissan Pathfinder;  
Model year 2005-2011 Nissan Frontier and;  
Model year 2005-2011 Nissan Xterra

A service campaign to install longer life bulbs was planned to address this issue. However, after consultation with Transport Canada, Nissan agreed that although a burnt out bulb is not a safety related defect, the short lifespan of the current bulbs does not meet the intent of CMVSS 108 and that a recall campaign should be conducted.

Vehicles sold in the United States are not affected because they are not equipped with daytime running lights