



Volvo Cars of North America, LLC.

1 Volvo Drive
P.O. Box 914
Rockleigh, NJ 07647
201-768-7300
www.volvocars.com

July 29, 2011

Mr. Daniel C. Smith
Senior Associate Administrator, Vehicle Safety
National Highway Traffic Safety Administration
1200 New Jersey Ave.
SE/W45-231
Washington, D.C. 20590

Dear Mr. Smith

Submission of TREAD report form per 49 CFR, Part 579, subpart B

Subject: R69238 Power Steering Return Pipe

This is to inform you that Volvo Car Corporation and/or its various subsidiaries and affiliates have decided to conduct one Field Service Action (Ref. R69238) in a foreign country. Details of this field action are included in the attached report form.

If you have any further questions, please contact me at 201-768-7300 ext. 7908

Attachments:

1. Report of field action

Sincerely,

A handwritten signature in black ink, appearing to read "Adam Kopstein".

Adam Kopstein,
Volvo Cars of North America, LLC.
Automotive Safety and Compliance
Mgr. Product Safety & Compliance
1 Volvo Drive, Building B
Rockleigh, NJ 07647

MANUFACTURER:

Volvo Car Corporation
Product Compliance Office,
Dept. 58500
HAKVS
S-405 31 Gothenburg,
Sweden

Designated Agent

Volvo Cars of North America, LLC
PO Box 914
1 Volvo Drive
Rockleigh, NJ 07647

PRODUCT IDENTIFICATION:

The following Volvo vehicles, including only those equipped with 4 cylinder gas and diesel engines (B4164T, B4164T2, B4164T3 and D4162T), are included in this recall.

Model	Model Year	Production Date Range
S80	2011-2012	09/16/2010 - 03/17/2011
S60	2011-2012	11/16/2010 - 03/23/2011
V70	2011-2012	09/14/2010 - 03/21/2011
V60	2011-2012	11/16/2010 - 03/21/2011

NUMBER OF VEHICLES POTENTIALLY AFFECTED:

7,124

DESCRIPTION OF DEFECT:

The quick connector in the upper power steering return pipe may disengage resulting in power steering fluid leakage.

COUNTRY(S) WHERE CONDUCTED:

U.A.E. Arabian Gulf	United Kingdom	Portugal
Austria	Greece	Quatar
Belgium	Hungary	Romania
Bulgaria	Ireland	Russian Federation
Brazil	Italy	Saudi Arabia
Belarus	Jamaica	Sweden
Switzerland	Jordan	Singapore
Colombia	Japan	Slovenia
Cyprus	Kuwait	Slovakia
Czech Republic	Lithuania	Syrian Arab Republic
Germany	Latvia	Turkey
Denmark	Mexico	Taiwan
Ecuador	Netherlands	VCC Internal
Estonia	Norway	VCI Sales small markets
Egypt	Oman	South Africa
Finland	Philippines	Zambia
France	Poland	

TYPE OF CAMPAIGN:

Safety Recall

DECISION MADE BY:

Volvo

DESCRIPTION OF THE REMEDY PROGRAM:

Replace the upper power steering return pipe.

KEY DATES:

The decision to recall was made on July 14, 2011.

The recall will commence with notification to dealers on or about July 14, 2011.

IDENTITY OF SUBSTANTIALLY SIMILAR VEHICLES SOLD IN THE U.S.:

The recalled model and model year vehicles listed above are all substantially similar to the same make and model vehicles sold in the U.S. However, Volvo did not certify for sale nor sell in the U.S. any of these vehicles equipped with a 4 cylinder gas or diesel engine. Accordingly, none of the vehicles sold in the U.S. are subject to the recall.