



Volvo Cars of North America, LLC.

1 Volvo Drive
P.O. Box 914
Rockleigh, NJ 07647
201-768-7300
www.volvocars.com

November 22, 2011

Mr. Daniel C. Smith
Senior Associate Administrator, Vehicle Safety
National Highway Traffic Safety Administration
1200 New Jersey Ave.
SE/W45-231
Washington, D.C. 20590

Dear Mr. Smith

Submittal of TREAD report form per 49 CFR, Part 579, subpart B

Subject: R39247 Windshield Washer Fluid Pump Harness

This is to inform you that Volvo Car Corporation and/or its various subsidiaries and affiliates have decided to conduct one Field Service Action (Ref. R39247) in a foreign country. Details of this field action are included in the attached report form.

If you have any further questions, please contact me at 201-768-7300 ext. 7908

Attachments:

1. Report of field action

Sincerely,

A handwritten signature in blue ink, appearing to read "Adam Kopstein", with a stylized flourish at the end.

Adam Kopstein,
Volvo Cars of North America, LLC.
Automotive Safety and Compliance
Mgr. Product Safety & Compliance
1 Volvo Drive, Building B
Rockleigh, NJ 07647

MANUFACTURER:

Volvo Car Corporation
Product Compliance Office,
Dept. 58500
HAKVS
S-405 31 Gothenburg,
Sweden

Designated Agent

Volvo Cars of North America, LLC
PO Box 914
1 Volvo Drive
Rockleigh, NJ 07647

PRODUCT IDENTIFICATION:

The following Volvo Right Hand Drive vehicles are included in this recall.

Model	Model Year	Production Date Range
C30	2008-2010	11/14/07 – 04/02/10
C70	2008-2011	11/09/07 – 03/11/11
S40	2008-2011	11/14/07 – 03/19/11
V50	2008-2010	11/14/07 – 04/02/10

NUMBER OF VEHICLES POTENTIALLY AFFECTED:

60,008

DESCRIPTION OF DEFECT:

Windshield washer fluid may intrude into the harness leading to the Central Electronic Module connector.

COUNTRY(S) WHERE CONDUCTED:

England
Netherlands

TYPE OF CAMPAIGN:

Safety Recall

DECISION MADE BY:

Volvo

DESCRIPTION OF THE REMEDY PROGRAM:

To mount capillarity breaking crimps on the washer fluid pump wiring harness.

KEY DATES:

The decision to conduct a recall was made on November 17, 2011. Volvo will commence with notification to dealers on or about November 17, 2011.

IDENTITY OF SUBSTANTIALLY SIMILAR VEHICLES SOLD IN THE U.S.:

The recalled model and model year vehicles listed above are Right Hand Drive vehicles that are not sold in the U.S. The windshield washer fluid pump is in a different location on Left Hand Drive vehicles.