



December 15, 2011

Via FedEx

Ms. Anamari Alonso
United States Department of Transportation
National Highway Traffic Safety Administration
ODI/Recall Management Division - NVS-215
Room W48-305
1200 New Jersey Avenue S.E.
Washington, DC 20590

Re: UD Trucks North America

Dear Ms. Alonso:

Enclosed is UD Trucks North America defect information report pursuant to 49 C.F.R. Part 573.6.

This information report is for a Foreign Recall on similar or substantially similar to US models. The US models will not be involved in this recall as the substantially similar vehicles were not sold in the US.

Please contact me if you have any questions.

Sincerely,

Sincerely,
Les Wells
Senior Manager Service Operations
UD Trucks North America
972-756-5523

UD Trucks North America
6012 West Campus Circle Drive Suite 288
Irving, Texas 75063

1	Country	Japan
2	Group	Safety Recall
3	Determination	Manufacturer (UD Trucks)
4	Notification number	Issued as Campaign No 2863 by Ministry of Land,Infrastructure,Transport and Tourism in Japan
5	Date of determination	6th December, 2011
6	Date of campaign	Same as above.
7	Representation models of campaign	MK35,36,37 LK36,37 PK36,37
8	Model year	Product from February 2, 2010 to May 31, 2010
9	Similar vehicles in USA	MKA371, MKB371, LKC371, PKA371 and PKC371
10	Part	Rear axle hub inner bearing
11	Phenomenon	Delamination on rear axle hub inner bearing
12	Number of Vehicles Involved	1417
13	Percentage involved	100%
14	Cause	Low strength bearing material, which was made under improper molten temperature.
15	Remedy	Both inner and outer rear axle hub bearings will be replaced.
16	Notes	Relevant vehicles have not sold in the USA market.