



Adam Kopstein

Manager, Product Safety & Compliance

December 31, 2014

Mrs. Nancy Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Ave.
SE/W45-306
Washington, D.C. 20590

Submission of TREAD report form per 49 CFR, Part 579, subpart B
Subject: R39560 Front Headlamp Aim - Corrected Production Dates

Dear Mrs. Lewis:

This is to inform you that Volvo Car Corporation and/or its various subsidiaries and affiliates have decided to conduct one Field Service Action (Recall R39560) in a foreign country.

A deviation was found in the headlight aim calibration tool during the regular calibration check included in weekly factory maintenance. As a result, certain vehicles in the attached chassis range may have incorrect headlight aim calibration.

The corrective action is to inspect and if needed perform a headlight aim adjustment.

The referenced Volvo S60L and XC60 vehicles are manufactured in China and are not offered for sale in the U.S.

Details of this field action are included in the attached report form. If you have any further questions, please contact me at 201-768-7300 ext. 7908.

Drive Safely,

A handwritten signature in blue ink that reads "A. Kopstein".

Adam Kopstein
Manager, Product Safety and Compliance
201-768-7300 ext# 7908
akopstei@volvocars.com



MANUFACTURER:

Volvo Car Corporation
S-405 31 Gothenburg,
Sweden

Designated Agent

Volvo Cars of North America, LLC
PO Box 914
1 Volvo Drive
Rockleigh, NJ 07647

PRODUCT IDENTIFICATION:

The following Volvo vehicles are included in this recall.

Model	Model Years	Number Vehicles	Production Dates	Chassis Numbers
S60L	2015 - 2016	159	11/12/14 - 11/19/14	025156 - 085047
XC60	2015 - 2016	526	11/12/14 - 11/19/14	688848 - 775042

NUMBER OF VEHICLES POTENTIALLY AFFECTED: 685

DESCRIPTION OF DEFECT:

A deviation was found in the headlight aim calibration tool during the regular calibration check included in weekly factory maintenance. As a result, certain vehicles in the attached chassis range may have incorrect headlight aim calibration.

COUNTRY(S) WHERE CONDUCTED:

China

TYPE OF CAMPAIGN:

Non - Compliance Recall

DECISION MADE BY:

Volvo Cars Sweden

DESCRIPTION OF THE REMEDY PROGRAM:

The corrective action is to inspect and if needed perform a headlight aim adjustment.

KEY DATES: The decision to conduct a recall was made on December 19, 2014. Volvo has commenced with notification to dealers on December 19, 2014.

IDENTITY OF SUBSTANTIALLY SIMILAR VEHICLES SOLD IN THE U.S.: The referenced Volvo S60L and XC60 vehicles are manufactured in China and are not offered for sale in the U.S.