

TOYOTA

**Toyota Motor Engineering &
Manufacturing North America, Inc.**

Vehicle Safety & Compliance
Liaison Office
Mail Code: S-104
19001 South Western Avenue
Torrance, CA 90501

August 4, 2015

Mr. Frank S. Borris II
Acting Associate Administrator for Enforcement
National Highway Traffic Safety Administration
Attn: Recall Management Division (NVS-210)
1200 New Jersey Ave, SE
Washington, D.C. 20590

Re: Foreign Safety Recall/Other Safety Campaign Report
Certain Toyota Vehicles

Dear Mr. Borris:

In accordance with 49 CFR 579.12, attached is a copy of our Foreign Safety Recall/Other Safety Campaign Report for the subject vehicles.

Should you have any questions about this report, please contact me directly.

Sincerely,



Abbas Saadat
Vice President
Vehicle Safety & Compliance Liaison Office
Toyota Motor Engineering & Manufacturing
North America, Inc.

Enclosures
Foreign Safety Recall/Other Safety Campaign Report

Foreign Safety Recall / Other Safety Campaign Report

Subject: Driver frontal airbag issue on certain Toyota vehicles

1. Vehicle Manufacturer Name:

Toyota Motor Manufacturing France S.A.S. ["TMMF"]
 Gac Toyota Motor Co., Ltd. ["GTMC"]
 Toyota do Brasil Ltda. ["TDB"]
 Toyota De Venezuela, C.A. ["TDV"]

2. Involved Vehicles:

Make/ Car Line	Model Year	Country/Region	Action	Production Period	Number of Vehicles
Toyota/ Yaris, Corolla	*1	Europe, China, Mexico, Africa, Middle East, Central and South America, Oceania	Safety Recall: Europe, China Other Safety Campaign: Other countries	January, 2006 through December, 2011	Approx. 1,513,000

*1: Most countries/regions do not use a model year designation.

3. Substantially Similar Vehicles sold in the U.S.:

Model Year/Make/ Car Line:	2006-2012MY	Toyota Yaris, Corolla, Corolla Matrix
	2006-2010MY	Scion tC, Pontiac Vibe
	2006-2009MY	Toyota Prius
	2008-2012MY	Scion xD
	2012MY	Toyota Prius C

4. Description of Problem:

The subject vehicles are equipped with a single-stage driver frontal air bag inflator (Takata-designated SDI) which may have been manufactured in such a way as to have a potential for the intrusion of moisture over time. Depending on the circumstances, they could potentially be susceptible to rupture and the driver front air bag could deploy abnormally in a crash, increasing the risk of injury to the occupant. The relationship of moisture intrusion, if any, to the risk of rupture of the airbag is not known.

5. Description of Corrective Repair Action:

For all affected vehicles, the dealer will replace the driver frontal airbag inflator with a newly manufactured one.

6. Determination to Conduct Safety Recall / Other Safety Campaign:

- The determination was made by Toyota Motor Corporation;
- Date of determination : July 29, 2015
- Date campaign will commence : As soon as remedy parts are available (depending on the country)

7. Reason the similar vehicles sold in the U.S. are not involved in this safety recall / other safety campaign:

The above mentioned involved Toyota vehicles sold outside of the U.S. are equipped with driver frontal airbag assemblies with the Takata single stage inflator (Takata-designated SDI). Substantially similar vehicles sold in the U.S. are not equipped with the affected SDI inflators and are equipped with inflators produced by different suppliers. None of the involved vehicles have been exported to or sold in the U.S.