



Jason Guidi

Manager – Warranty, Regulatory & Compliance

June 03, 2016

Mr. Greg Rea
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Ave.
SE/W45-306
Washington, D.C. 20590

Submission of TREAD report form per 49 CFR, Part 579, subpart B
Subject: R89703 Air Bag Module

Dear Mr. Rea:

This is to inform you that Volvo Car Corporation and/or its various subsidiaries and affiliates have decided to conduct one Field Service Action (Recall R89703) in a foreign country.

Volvo has identified that certain model year 2016 and 2017 vehicles may have a manufacturing defect in the airbag module. Due to a potential manufacturing defect, the gas generator in the driver's airbag may not deploy stage 2 as intended. The corrective action is to replace the airbag module.

Volvo has identified a total of 283 affected vehicles currently at or en route to Volvo U.S. Port Processing Centers. These vehicles will be repaired prior to shipment to U.S. Volvo retailers.
No affected vehicles were shipped to U.S. Volvo retailers prior to the release of this recall.

Details of this field action are included in the attached report form. If you have any further questions, please contact me at 617-784-6027.

Drive Safely,

A handwritten signature in blue ink that reads "Jason Guidi".

Jason Guidi
Manager, Warranty, Regulations and Compliance
jason.guidi@volvocars.com

**MANUFACTURER:**

Dalphi Metal Espana S.A., Safebag
Zona Ind. Da Germiera
Lotes 15/20
4990-645 Ponte de Lima
Portugal
Jorge Rios
jorge.rios@zf.com
+35 1258900840

PRODUCT IDENTIFICATION:

The following Volvo vehicles are included in this recall.

MODEL	YEAR	CHASSIS RANGE	ASSEMBLY PLANT
V40	2017	360678 - 362795	Ghent, Belgium
V40CC	2017	115161 - 115571	Ghent, Belgium
V60	2017	330922 - 331567	Torslanda, Sweden
V60CC	2017	023487 - 023593	Torslanda, Sweden
XC60	2017	002858 - 006260	Ghent, Belgium
XC70	2016	273009 - 273950	Torslanda, Sweden

NUMBER OF VEHICLES POTENTIALLY AFFECTED: 1,759**DESCRIPTION OF DEFECT:**

Volvo has identified that certain model year 2016 and 2017 vehicles may have a manufacturing defect in the airbag module. Due to a potential manufacturing defect, the gas generator in the driver's airbag may not deploy stage 2 as intended.

COUNTRY(S) WHERE CONDUCTED:

Argentina	Czechia	Italy	Turkey	Israel
Denmark	Germany	Netherlands	Taiwan	India
Finland	Spain	Poland	South Africa	Kuwait
Norway	France	Portugal	Chile	Sri Lanka
Sweden	United Kingdom	Slovenia	Colombia	Morocco
Austria	Greece	Slovakia	Cyprus	New Zealand
Belgium	Hungary	Australia	Estonia	
Switzerland	Ireland	Russian Federation	Guatemala	



TYPE OF CAMPAIGN:

Safety Recall

DECISION MADE BY:

Volvo Cars Sweden

DESCRIPTION OF THE REMEDY PROGRAM:

The corrective action is to replace the airbag module.

KEY DATES:

The decision to conduct a recall was made on May 27, 2016. Volvo has commenced with notification to non U.S. dealers on May 27, 2016.

IDENTITY OF SUBSTANTIALLY SIMILAR VEHICLES SOLD IN THE U.S.

Volvo has identified a total of 283 affected vehicles currently at or en route to Volvo U.S. Port Processing Centers. These vehicles will be repaired prior to shipment to U.S. Volvo retailers. No affected vehicles were shipped to U.S. Volvo retailers prior to the release of this recall.