

NISSAN

NISSAN NORTH AMERICA, INC.

Corporate Headquarters
One Nissan Way
Franklin, TN 37068

Mailing Address: P.O. Box 685001
Franklin, TN 37068-5001

Telephone: 615.725.1000


September 19, 2016

Associate Administrator for Safety Assurance
National Highway Traffic Safety Administration
Attention: Early Warning Division (NVS-217)
Room 217
1200 New Jersey Avenue, SE
Washington, D.C. 20590

Dear Associate Administrator:

We are transmitting the enclosed Report of a Defect in a Vehicle in a Foreign Country.

Very truly,

A handwritten signature in black ink, appearing to read 'Derek Latta', with a long horizontal flourish extending to the right.

Derek Latta
Manager
Technical Compliance

Encl.

**REPORT OF A SAFETY RECALL OR OTHER SAFETY CAMPAIGN
IN A FOREIGN COUNTRY**

1. Manufacturer

Nissan Motor Co., Ltd., Japan.

2. Vehicles Potentially Involved

Skyline vehicles produced from May 26, 2014 to March 4, 2015 at Nissan Motor Co., Ltd. in Japan.

3. Total Number of Vehicles Potentially Involved

Approximately 1,480.

4. Description of the Defect

The lever which controls the cooling water channel in the water pump of the engine may break due to insufficient strength. This could cause the piston for the cooling water channel control to be pushed out by the cooling water and result in a leak. If the vehicle continues to be driven in this condition, the acceleration may be restricted by the engine protection control mode. This is not a safety related issue; however, this condition may not meet the requirements of local regulations of Japan.

5. Foreign Country in which the Safety Recall or Other Safety Campaign is Being Conducted

Japan.

6. Date of Determination

September 12, 2016

7. Determination Made By

Manufacturer

8. Date the Recall or Other Campaign will Commence

September 16, 2016

9. Descriptive of Corrective Action

Owners of potentially affected vehicles will be notified to take their vehicle to a dealer. The bolt securing the heat insulator on the water pump will be replaced with a counter-measured one to prevent the plunger from coming out even if the lever breaks.

10. Vehicles in the United States (If known)

Model year 2009-2016 Nissan 370Z vehicles, model year 2010-2016 Nissan 370Z Roadster vehicles, model year 2003-2014 Infiniti G Sedan vehicles, model year 2015 Infiniti Q40 vehicles, model year 2014-2016 Infiniti Q50 vehicles, model year 2003-2013 Infiniti G Coupe vehicles, model year 2014 Infiniti Q60 Coupe vehicles, model year 2017 Infiniti Q60 vehicles, model year 2009- 2013 Infiniti G Convertible vehicles, model year 2014-2015 Infiniti Q60 Convertible vehicles, model year 2008-2013 Infiniti EX35 vehicles, model year 2014-2017 Infiniti QX50 vehicles, model year 2006-2013 Infiniti M vehicles, model year 2014-2016 Infiniti Q70 vehicles, model year 2003-2013 Infiniti FX vehicles and model year 2014-2017 Infiniti QX70 vehicles sold in the U.S. are on a similar "platform" as the Infiniti Q50/Skyline vehicles sold in Japan. However, these U.S. vehicles are not affected because they use a different water pump than the affected vehicles.