

NISSAN

NISSAN NORTH AMERICA, INC.

Corporate Headquarters
One Nissan Way
Franklin, TN 37068

Mailing Address: P.O. Box 685001
Franklin, TN 37068-5001

Telephone: 615.725.1000


September 30, 2016

Associate Administrator for Safety Assurance
National Highway Traffic Safety Administration
Attention: Early Warning Division (NVS-217)
Room 217
1200 New Jersey Avenue, SE
Washington, D.C. 20590

Dear Associate Administrator:

We are transmitting the enclosed Report of a Defect in a Vehicle in a Foreign Country.

Very truly,

A handwritten signature in black ink, appearing to read 'Derek Latta', with a long horizontal flourish extending to the right.

Derek Latta
Manager
Technical Compliance

Encl.

**REPORT OF A SAFETY RECALL OR OTHER SAFETY CAMPAIGN
IN A FOREIGN COUNTRY**

1. Manufacturer

Nissan Motor Manufacturing UK Ltd., United Kingdom.

2. Vehicles Potentially Involved

Infiniti Q30 vehicles produced from August 4, 2015 to July 16, 2016 at Nissan Motor Manufacturing UK Ltd. in the United Kingdom. No vehicles sold in the United States are affected because they were produced after countermeasures were taken to correct the issue in the assembly process.

3. Total Number of Vehicles Potentially Involved

Approximately 3,016.

4. Description of the Defect

The mounting nuts holding the rear seat belt buckle anchors to the floor may not be properly tightened due to an inappropriate operation in the manufacturing process. In rare cases, the nut may come off preventing proper restraint of the rear seat occupants.

5. Foreign Country in which the Safety Recall or Other Safety Campaign is Being Conducted

Austria, Azerbaijan, Bahrain, Belgium, Bulgaria, Czech, France, Germany, Holland, Hong Kong, Hungary, Italy, Jordan, Korea, Kuwait, Lebanon, Oman, Poland, Qatar, Saudi Arabia, Singapore, Switzerland, Taiwan, United Arab Emirates and United Kingdom.

6. Date of Determination

September 23, 2016

7. Determination Made By

Manufacturer

8. Date the Recall or Other Campaign will Commence

September 30, 2016

9. Descriptive of Corrective Action

Owners of potentially affected vehicles will be notified to take their vehicle to a dealer. The tightening torque of the mounting nut will be inspected. If the nut is tightened incorrectly, the mounting nut will be re-tightened with the specified tightening torque.

10. Vehicles in the United States (If known)

Model year 2017 Infiniti QX30 vehicles sold in the U.S. are on a similar "platform" as the Infiniti Q30 vehicles sold in above countries. However, none of the affected vehicles were exported to the U.S. market because the issue was found and countermeasures adopted before any vehicles were exported to the U.S. market