

NISSAN

NISSAN NORTH AMERICA, INC.

Corporate Headquarters
One Nissan Way
Franklin, TN 37068

Mailing Address: P.O. Box 685001
Franklin, TN 37068-5001

Telephone: 615.725.1000


October 3, 2016

Associate Administrator for Safety Assurance
National Highway Traffic Safety Administration
Attention: Early Warning Division (NVS-217)
Room 217
1200 New Jersey Avenue, SE
Washington, D.C. 20590

Dear Associate Administrator:

We are transmitting the enclosed Report of a Defect in a Vehicle in a Foreign Country.

Very truly,

A handwritten signature in black ink, appearing to read 'Derek Latta', with a long horizontal flourish extending to the right.

Derek Latta
Manager
Technical Compliance

Encl.

REPORT OF A SAFETY RECALL OR OTHER SAFETY CAMPAIGN IN A FOREIGN COUNTRY

1. Manufacturer

Nissan Motor Manufacturing UK Ltd., United Kingdom.

2. Vehicles Potentially Involved

Infiniti Q30 vehicles produced from March 2015 to April 26, 2016 at Nissan Motor Manufacturing UK Ltd. in the United Kingdom. No vehicles sold in the United States are affected because they were produced in the different assembly processes as discussed below.

3. Total Number of Vehicles Potentially Involved

Approximately 1,210.

4. Description of the Defect

Due to improper kitting in the material handling area, RH and LH seat belt retractors may have been installed on opposite sides of the vehicle. This may cause the belt to be operated at an improper angle resulting in lock up of the mechanism. In rare cases, the front passengers may not be restrained in the event of a frontal impact.

5. Foreign Country in which the Safety Recall or Other Safety Campaign is Being Conducted

Austria, Belgium, Bulgaria, Croatia, France, Germany, Holland, Hong Kong, Hungary, Italy, Korea, Poland, Russia, Singapore, Spain, Switzerland, Turkey and United Kingdom.

6. Date of Determination

September 27, 2016

7. Determination Made By

Manufacturer

8. Date the Recall or Other Campaign will Commence

October 3, 2016

9. Descriptive of Corrective Action

Owners of potentially affected vehicles will be notified to take their vehicle to a dealer. The part number of both front seat belts will be inspected. If incorrect part is installed, the front seat belt will be replaced with a correct one.

10. Vehicles in the United States (If known)

Model year 2017 Infiniti QX30 vehicles sold in the U.S. are on a similar "platform" as the Infiniti Q30 vehicles sold in above countries. Affected U.S. vehicles are pre-production vehicles being used internally within Nissan and no vehicles sold in the U.S. are affected by this issue.