

NISSAN

NISSAN NORTH AMERICA, INC.

Corporate Headquarters
One Nissan Way
Franklin, TN 37068

Mailing Address: P.O. Box 685001
Franklin, TN 37068-5001

Telephone: 615.725.1000


February 15, 2017

Associate Administrator for Safety Assurance
National Highway Traffic Safety Administration
Attention: Early Warning Division (NVS-217)
Room 217
1200 New Jersey Avenue, SE
Washington, D.C. 20590

Dear Associate Administrator:

We are transmitting the enclosed Report of a Defect in a Vehicle in a Foreign Country.

Very truly,

A handwritten signature in black ink, appearing to read 'Derek Latta', with a long horizontal flourish extending to the right.

Derek Latta
Manager
Technical Compliance

Encl.

**REPORT OF A SAFETY RECALL OR OTHER SAFETY CAMPAIGN
IN A FOREIGN COUNTRY**

1. Manufacturer

Nissan Motor Manufacturing UK Ltd., United Kingdom

2. Vehicles Potentially Involved

Infiniti Q30/QX30 vehicles produced from November 24, 2015 to June 20, 2016 at Nissan Motor Manufacturing UK Ltd. in the United Kingdom. Only vehicles that have received an ACU service part have the potential to be affected. No vehicles sold in the United States are affected because no ACU's have been replaced in the US market and all affected service parts have been quarantined.

3. Total Number of Vehicles Potentially Involved

Approximately 56.

Warranty replacements: 46 vehicles

Parts supplied to dealers for non-warrantable accident repairs: 10

4. Description of the Defect

Due to an incorrect data setting in the ACU service part, the re-programming procedure performed during an ACU replacement cannot be completed successfully. This may leave the ACU with incorrect sensitivity data that does not match the subject vehicle. As a result, the restraint system may not function as designed in the event of a crash.

5. Foreign Country in which the Safety Recall or Other Safety Campaign is Being Conducted

Belgium, Bulgaria, France, Germany, Italy, Poland, Spain, Turkey and United Kingdom.

6. Date of Determination

February 10, 2017

7. Determination Made By

Manufacturer

8. Date the Recall or Other Campaign will Commence

February 20, 2017

9. Descriptive of Corrective Action

Owners of potentially affected vehicles will be notified to take their vehicle to a dealer. The serial number of the ACU will be inspected. If it is confirmed as a service part within the incident range, the ACU will be reprogrammed using the correct programming equipment.

10. Vehicles in the United States (If known)

US vehicles with similar "platform" to the Infiniti Q30/QX30 sold in Europe:
Model year 2017 Infiniti QX30

As noted above, this issue affects no vehicles sold in the U.S.