



Mr. Jeffrey Giuseppe
Associate Administrator for Enforcement
NATIONAL HIGHWAY TRAFFIC SAFETY
ADMINISTRATION
Attn: Early Warning Division (NVS-215)
1200 New Jersey Ave., SE
Washington, DC 20590
United States of America

Automobili
Lamborghini S.p.A.

Notification of Recall Pursuant to 49 CFR Part 579.11 (c)
2019 Porsche Cayenne, Brake wear warning system
Sant'Agata Bolognese, February 20, 2019

Vs. riferimento
Vs. data
Oggetto
Data

Dear Mr. Giuseppe:

Pursuant to 49 CFR 579.11(c), Automobili Lamborghini S.p.A. hereby submits the following recall that will be conducted overseas.

Via Modena, 12
I-40019 Sant'Agata
Bolognese
Telefono +39 051-681 76 11
Telefax +39 051-681 76 44

- (1) Manufacturer Name
Porsche AG
- (2) Date of Determination by the Manufacturer
13th of February 2019
- (3) Identification of Vehicles, Basis of Determination and How Vehicles Differ from Identical or Substantially Similar Vehicles Not Included in Recall

Make: Porsche

Line: Cayenne

Model Year: 2019

Date of Production: August 2017 – May 2018 (for details please see 573 report submitted by Porsche North America)

Basis for Determination: Customers could use the vehicle with worn out brake pads. In certain traffic this might lead to a higher risk of a crash.

Reason U.S. Vehicles Are Not Affected: Lamborghini vehicles that are substantially similar to the line under this recall communication already mount a different system and optimized

Capitale Sociale
€ 130.000.000
R.E.A. Bologna 259882
Codice Fiscale 03049840378
Partita I.V.A IT00591801204
A socio unico
Società del Gruppo Audi



software version related to this feature since start of production. Therefore, no Lamborghini vehicle sold in U.S. market have the non-compliant software version subject to this recall.

- (4) Description of Defective Component(s) and Manufacturer
The defect is caused by a software failure.
- (5) Total Number of Vehicles Affected
31.802
- (6) Description of Defect.
Due to a missing assignment within the instrument cluster's software, the red brake wear warning light is not illuminated continuously when the brake pads are worn out. Only a yellow warning message is shown in the multi-functional display, which can be confirmed and then suppressed until the next ignition switch-on event. Hence, the vehicles do not fully comply with FMVSS 135.
- (7) Affected Countries
Argentina, Australia, Bahrain, Belarus, Belgium, Bosnia Hercegovina, Bulgaria, Cambodia, Canada, Chile, Colombia, Croatia, Cyprus, Czech Republic, Denmark, Deutschland, Dominican Republic, Dubai, Ecuador, El Salvador, Estonia, Finland, France, Georgien, Great Britain, Greece, Guadeloupe, Guatemala, Hong Kong, Hungary, India, Indonesia, Island, Italy, Japan, Kuwait, Latvia, Lebanon, Lithuania, Luxembourg, México, Macedonia, Malaysia, Malta, Moldova, Morocco, Netherlands, New Caledonia, Norway, Austria, P.R. China, Panama, Peru, Poland, Qatar, Republic of Korea, Republik Kasachstan, Romania, Russian, Federation, Saudi Arabia, Schweiz, Serbia/Montenegro, Singapore, Slovakia, Slovenia, South Africa, Spain. Sultanate of Oman, Sweden, Tahiti, Taiwan, Thailand, Turkey, Ukraine, United Arab Em., United Arab Emirates, Uruguay, USA, Ukraine, United Arab Emirates, Uruguay, USA
- (8) Type of Campaign
Recall
- (9) Determination made by:
Porsche AG
- (10) Manufacturers Program of Remedy
The vehicles will be recalled to the workshop and the instrument cluster will be re-programmed with an optimized software.



(11) Start of Campaign

TBD

(12) Identification of Identical or Substantially Similar Vehicles to U.S. Market

2019 Lamborghini Urus

Sincerely,

A handwritten signature in black ink, appearing to read "Paolo Gabrielli", written over a horizontal line.

Paolo Gabrielli
Head of After Sales
Automobili Lamborghini S.p.A.

A handwritten signature in black ink, appearing to read "Maria Francesca Portincasa", written over a horizontal line.

Maria Francesca Portincasa
Legal Services
Automobili Lamborghini S.p.A.