



June 8, 2023

Ms. Anne Collins
Associate Administrator, Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
Washington, DC 20590

RE: TREAD Act Required Report of a Recall in a Foreign Country

Dear Ms. Collins:

Pursuant to the TREAD Act and Section 579.11 of Part 579 of Title 49 of the Code of Federal Regulations, and on behalf of Hyundai Motor Company ("HMC"), Hyundai Motor North America ("HMNA") is submitting information concerning a recall that is being conducted in Europe, Asia, Australia, South America, Africa, and the Middle East. Specific information as required by Section 579.12 of Part 579 of Title 49 of the Code of Federal Regulations, given HMNA's best understanding of the information as of the date of this submission, is as follows:

1. Manufacturer:

Hyundai Motor Company ("HMC")

2. Identification of the vehicles potentially containing the defect:

The involved vehicles include certain model year 2011 Hyundai Elantra and i30/Elantra Touring vehicles produced between December 2, 2010 through December 30, 2010, by HMC for sale in Europe, Asia, Australia, South America, Africa, and the Middle East.

3. Total number of vehicles potentially containing the defect:

1,354

4. Description of the defect/noncompliance:

The subject vehicles are equipped with driver's side airbag modules containing ARC single-stage inflators that could rupture during a commanded deployment event. If the inflator ruptures during deployment, the airbag may not fully inflate, and the release of high-pressure gas may propel pieces of the inflator and airbag module into the occupant compartment. This could increase the risk of injury to occupant(s) in a crash.

5. Foreign country in which the safety recall or other safety campaign is being conducted:

This recall is being conducted in Europe, Asia, Australia, South America, Africa, and the Middle East.

Hyundai Motor America

6. Description of the foreign action as a safety recall or other safety campaign:

This action is a safety recall being conducted to gather inflators from a suspect production lot for evaluation of root cause and potential remedy.

7. Determination to conduct the recall made by the manufacturer or by a foreign government:

The determination to conduct this recall was made by Hyundai Motor Company.

8. Manufacturer's program for remedying the defect or noncompliance:

All owners of the subject vehicles will be notified by first class mail with instructions to bring their vehicles to a Hyundai dealer for replacement of the driver's side airbag inflator.

9. Date of the determination and the date the recall was commenced in each foreign country:

The determination to conduct this campaign was made on May 31, 2023. Hyundai plans to notify Korea Automobile Testing & Research Institute ("KATRI") on June 9, 2023 and involved owners on a date yet to be determined.

10. Identify all motor vehicles sold or offered for sale in the United States that are identical or substantially similar to the motor vehicles covered by the foreign recall or campaign:

Model year 2011 Hyundai Elantra and i30/Elantra Touring vehicles manufactured for sale in the specified markets are substantially similar to U.S. specification 2011 Hyundai Elantra and Elantra Touring vehicles; however, the U.S. specification vehicles are equipped with airbags containing dual-stage inflators produced separately from the suspect production lot.

Sincerely,



Cole Stutz
Executive Director, North America Safety Office