

EA02-025

FORD 10/27/03

APPENDIX N

BOOK 22 OF 61

PART 1 OF 4

I hereby authorize the repair work herein set forth to be done during ordinary business hours and agree that you are not responsible for loss of damage to vehicle or articles left in vehicle in case of fire, theft or any other cause beyond your control or for any damage caused by unsuitability of parts or design in parts shown or by the supplier or subcontractor. I understand that under state law I am entitled to a written estimate, if my final bill will exceed \$50.00. I REQUEST A WRITTEN ESTIMATE. I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED \$_____. THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL. I DO NOT REQUEST A WRITTEN ESTIMATE.

SIGNED: _____ DATE: _____

12/22
13:00
CHW

PLEASE READ CAREFULLY, INITIAL ONE OF THE STATEMENTS BELOW, AND SIGN: I UNDERSTAND THAT UNDER STATE LAW I AM ENTITLED TO A WRITTEN ESTIMATE, IF MY FINAL BILL WILL EXCEED \$50.00. I REQUEST A WRITTEN ESTIMATE. I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED \$_____. THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL. I DO NOT REQUEST A WRITTEN ESTIMATE.

SIGNED: _____ DATE: _____

INSTRUCTIONS ON WORK TO BE DONE

51* PAY TYPE: BOD STATE FARM INSURANCE CLAIM CLAIM# 7-4002-006	TECH # TECH NO. LAST 4 - BOD BOD	OPERATION	TIME	CONDITION
52 PAY TYPE: BOD TOWING	TECH # TECH NO. LAST 4 - BOD BOD			
53 PAY TYPE: BOD	TECH # TECH NO. LAST 4 - BOD BOD			
	TECH # TECH NO. LAST 4 - BOD BOD			

TECH #	OPERATION	TIME	CONDITION
813A		4.5	PG 1 OF 1

5202

RD 44997 *TAG 6341* LIC: FL L9600P SVC ADV: 271 ANABELLA SWANSON
92 **VIN: 1LMLN81W5 NY
LINCOLN TOWN CAR CO. CD: WHI
EXECUTIVE 4DR SED
LICENSED WHITE CAR
SVC DLRI 11624 SLM: 59
IN-5001-031292 PROD: 031292
ODOMETER LAST: 70876 CURRENT: 73925
AVG PER DAY: 30 PER MONTH: 900
DIST CODE: 1FA

NAPLES FL

HOME: _____



DEALERSHIPS USING DAILY JOB TICKETS SHOULD
AFFIX THE JOB STICKERS IN THIS AREA.

TECHNICIAN COMMENTS
INCLUDE DESCRIPTION OF CAUSE

CON-
TIN-
TION
CODE

EMP. NO.

LABOR TIME

PARTS RETURN

DATE

Regrate leaky brake press. replace a
broken wire harness's

CAUSE:

CAUSE:


CAUSE:

CAUSE:

3713 4870

92 TOWN C&E PARTD

Parato of 92/93 Town Cars With Engine On, Off/Unknown and Related BPS Symptoms



Notes:

- The shaded region represents vehicles with engine off/unknown.
- The unshaded region represents vehicles with engine on.
- 1 Represents BPS symptoms


There were 11 vehicles in the unknown category.
3 engine off/unknown, 1 relates to a BPS symptom.

8 engines on.

Originator: J.Keddi
File: Bellright.xls
Date issued: 4/18/99
Date revised: 4/18/99

92 CV 6M 100000

Parade of 92/93 CV/GM Vehicles With Engine On/Off/Unknown and Related BPS Symptoms



Note:

- The shaded region represents vehicles with engine off/unknown.
- The unshaded region represents vehicles with engine on.
- 1 Represents BPS symptoms

There were 4 vehicles in the unknown category.
 3 engine off/unknown, 2 relate to BPS symptoms.
 1 engine on, 1 relates to a BPS symptom.

Originator: JGdail
 File: Buildchrt.xls
 Date issued: 4/10/99
 Date revised: 4/10/99



AGENDA

- **CONTRIBUTING FACTORS AND ROBUST DESIGN DIALOGUE**
- **OVERVIEW TIME LINE**
- **SYSTEM OVERVIEW**
 - **SWITCH AND CONNECTOR**
- **IS / IS NOT TABLE**
- **CAUSE AND EFFECT DIAGRAMS**
- **THEORIES**
 - **BRAKE FLUID IGNITION**
 - **PLASTIC IGNITION**
- **TEST RESULTS**
- **CONTRIBUTING FACTORS AND ROBUST DESIGN DIALOGUE**
- **ROBUST DESIGN ALTERNATIVES**


C:\McGill\99\presentation



1. Connector Seal to P/S
2. Power continuously available
 - A. Operator notifications
3. Switch orientation/location
4. Current limit / fuse
5. Hexport isolation
6. Plastic ignition robustness
 - A. Nearby fuels
7. Kapton seal of P/S
8. Environmental seal of P/S



OVERVIEW OF CONCERN TIME LINE




Attachment



Brake Switch Overview

- Mounted under hood...14 inches under master cylinder
- Mounted on proportional valve at frame of vehicle
- Switch oriented approximately 25 degrees off vertical (connector up)
- Switch controls speed control...normally closed, opens at 130 psi
- Continuously powered by battery 15 amp connection






TEXAS
INSTRUMENTS

Brake Pressure Switch

Potential Thermal Event Theory Profile 4/21/99



REFINED BRAKE FLUID IGNITION THEORY POSSIBLE CAUSE THEORIES "FEB '99 FOCUS"



C:\McGill\99presentation

Attachment


Brake Pressure Switch Test Log, Updated 3/10/99

Category	Test	Location	Test Parameters	Results Update
Lab Simulation of Potential Ignition in Switch	1	TI	Various Levels of 'new' Brake Fluid, Water Switch 14Vdc to one terminal, hezport grounded Water Conc: 0%, 4%, 8%, 10%, 75%	250+ hours, Current draw in the 0.5mA to 5mA range Fluid has discolored. No Significant Temperature Rise. Test Suspended. Internal Analysis in Progress.
	2	TI	Various Levels of 'new' Brake Fluid, Water, 1 Amp through switch terminals	250+ hours. Constant temperature. No significant temperature rise with time Test Suspended.
	3	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal Hezport Grounded	> 300 hours into test, next current 7mA No significant change with time. Test ongoing
	4	AVT	'new' Brake Fluid in Switch, 24 VDC to one terminal Hezport Grounded, Ambient at 100 C	16 hours into test max current 5mA No significant temperature rise with time. Test suspended.
	5	AVT	'new' Brake Fluid in Switch, 18 Amps Through switch terminals	Temperature rise of 20 C above room temp Delta T reached steady state at 20 C. Test suspended.
	5a	AVT	'new' Brake Fluid in Switch approx. 50 Amps through Switch Terminals	Temperature rose to approx. 270 F. No smoke. No ignition Test suspended.
	6	TI	Build heater elements into Switch. Heat oil failure, include sparking. With Fluid & Dry Pure 'new' brake fluid with metal shavings 5% brake fluid solution	2 tested. Smoke observed, ignition observed on part wheeler See attachment Test complete Brake fluid in cavity slows down heat build-up Smoke observed at 875 F, Base melts and falls off at 800 F
	6a	TI	Couple heater by corroding spring arm Salt water solution, 14V between spring and hezport	One out of 15 devices increased resistance to 5 ohms. Others either very low resistance or megohms It took about 100 hours to reach the 5 ohm stage. The 5 ohm device ignited under conditions similar to test 6.
	6b	TI	Re-run igniting test to understand repeatability, current path	Switch ignition with repeated 5% water solution into switch Current path is through hezport. See plots and video. Additional test include tap water, old BF, new BF and other.



- TI and Ford not successful in creating ignition with "new" brake fluids

FISH BONE DIAGRAM






Brake Pressure Switch

Potential Thermal Event Theory Profile 4/21/99



Generated by: ReliaSoft's Weibull++ 8.0 - www.Weibull.com - 888-888-0410

77PSL2-1 COMBINED DATA



$\beta = 5.83, \eta = 1.64 \times 10^6, \rho = 0.91$




- "Town Car" switch meets accelerated/simulated life cycle specification shown by "success" and "end-of-life" testing

BLOCK DIAGRAM



**PROCESS FLOW DIAGRAM
"CORROSION" POTENTIAL CAUSE FLOW ANALYSIS**




FALCOE STENERID



5. High current flow to case through water and ionic contamination

2. 12V Battery source to drive corrosion and provide energy

6. Plastic connector melts. Once it opens, oxygen enters the switch cavity. Arm terminal/corrosion becomes "RED HOT" igniting the plastic



1. Water and "ionic" contamination (e.g. NaCl or cleaner) enters the switch cavity

4. Contact arm & terminal corrosion increases resistance (acts like heater wire).



3. Hexport grounded accelerates corrosion

Attachment 2

TEST SETUP



5% Salt Water Ingress Experiment Test 1




TI Report PS/99/12
03/15/99

Test 1: Figure 1 and Figure 2.



5% Salt Water Ingress Experiment
Temperature vs. Time

Top Temp Clutch Temp Bottom Temp




C:\McGraw99\presentation

CURRENT SAMPLE



5% Salt Water Ingress Experiment




C:\McGill\99\ps\ps13\ps13_01.cmx 'Intentional ignition created thru TI fluid ingress lab test PS/99/13'

Brake Pressure Switch Potential Thermal Event Theory Profile 4/21/99



Hexport Current vs. Time
(3) Hour Fluid Ingress Experiment
(15 Amps Full Scale)



Intentional ignition created thru TI fluid ingress lab test PS/99/13

INITIATION OF SWIREL



77PS
45° Orientation in 15 Amp Circuit
5% Salt Water Ingress

Cellanex 4300 Base



Cellanex 3316 Base




'Intentional ignition created thru TI fluid ingress lab test PS/99/13'

C:\McQuis\99\presentation

SYMPTOMS



“Corrosion” potential cause time line Theory Time Line




FILE



77PS Noryl Base


45° Orientation in 15 Amp Circuit

5% Salt Water Ingress






**PROCESS FLOW DIAGRAM
"CORROSION" POTENTIAL CAUSE FLOW ANALYSIS**






ECONOLINE VS. TOWN CAR P/S



FILE - DEF 02/07/00



77PS Cellanex 4300 Base
Vertical Orientation in 15 Amp Circuit
5% Salt Water Ingress



Not Enough Printer Memory -- See User's Guide




5% Salt Water - 15 Amp Circuit - Vertical - Zytel



Not Enough Printer Memory - See User's Guide




5% Salt Water - 15 Amp Circuit - Vertical - Zytel




Not Enough Printer Memory - See User's Guide



"Corrosion" potential cause time line
Theory Time Line




VARIOUS FLUIDS



Hexport Current vs. Time
(3) Hour Fluid Ingress Experiment
(0.015 Amp Full Scale)


— New Brake Fluid	— New Brake Fluid w/ 5% water	— Used Brake Fluid w/ 5% Water
— Tap Water	— Used Brake Fluid	— Rain Water
— 5% Salt Water	— 100 per. Mov. Avg. (5% Salt Water)	



'Intentional Ignition created thru TI fluid ingress lab test PS/99/13'




**Hexport Current vs. Time
(24) Hour Fluid Ingress Experiment
(0.815 Amp Full Scale)**



3713 4413




“Corrosion” potential cause time line Theory Time Line



RELAY SCHEMATIC




77PS Proposed Wiring Schematic





200 mAmp Current Limit Circuit Test Setup





Brake Pressure Switch **Potential Thermal Event Theory Profile 4/21/99**



Today's Date: UPDATED 04/21/99

Scope or Effect Description

1. Operational Definition (Problem Statement): TOWN CAR UNDERHOOD FIRES			
2. Description	IS	IS NOT	Get Information
WHAT	Town Car MY '92, '93, '94	Crown Victoria? Grand Marquis? T8 Super Coupe? MY '91, '93, '95? '92, '93 Bronco/limo?	COMPARE PLATFORMS
	PIES... - Electrical pressure switch - Connector - Serve system - Electrical Distribution SYSTEM ISSUES... - Cables insensitive - Locked in park - Host insensitive - Brake lights insensitive - Discharged battery - Door lock? - Exhaust leak?	Not only pressure switches Other circuits	COLLECT/TEST OTHER SYSTEM COMPONENTS FOR "SYNERGY" COMPARE VEHICLE OPTIONS FOR SYNERGY COMPARE WARRANTY
WHERE	Driver side head Minimum height in engine compartment	Passenger side head Dash - gear compartment Not high in engine compartment Not low in engine compartment	EVALUATE HEAT SOURCES
WHEN	1-24 hours after parking Ignition off After 4-5 years After XXX miles After AAA switch cycles	Not while driving Not while ignition on Not before 3 years? Not before VVV miles Not before FFFS cycles	EVALUATE POWER AND HEAT AND WIND SOURCES REVIEW MILES
HOW BIG	149 cars / 223k units "candle star" flame	Not all cars? Not "explosion"	COMPARE PLATFORMS READ FIRE RPTS
	Several pressure switches	Not all underhood fire Not all pressure switches	PARTO UNDERHOOD

C:\McQuis\99\represent\99




**Brake Pressure Switch
Potential Thermal Event Theory Profile 4/21/99**




Texas Instruments
Automotive Sensors & Controls
8D Report

Concern Title 77 PS Thermal Events		Open Date 3/9/99	
T.I. CAR Report Number DAR 80-20		Updated 4/21/99	
Status Date	Vehicle Lincoln	Part Name	Electric Speed Control Deactivation System Switch
	Model Town Car	Part No.	77PS D-1
	Plant Vietnam		
1. Team: S. Bergholm B. Dugas A. Feltman A. McGuirk C. Douglas G. Baker T. Rashed		2. Problem Description Underhood car fire	
3. Containment Actions: Under review, considering disabling speed control system		% Effectiveness:	Implementation Date
4. Root Cause: See attachment 3, IS - IS NOT Table, (Timeline of 3/15/99) - Water enters pressure switch and connector - Continuous power drives controller - Controller causes high resistance - Resistance causes local heating - Several exposures over time (?) - Local heating ignites pressure switch and connector plastic - Operator protocol violation		% Containment	Unknown
5. Chosen Permanent Corrective Actions See attachment 3, 3.4 Under Review: - Reduce current - Containment cover - Create ground fault protector - Improve connector seal - Eliminate constant power - Change PS orientation - Provide power fault power reduction - Identify plastic parameters - Optimize polarity - Move to ground potential		Verification TBD by lab experiments	% Effectiveness Unknown
6. Implemented Permanent Corrective Actions		Implementation:	
7. Actions to Prevent Recurrence Eliminate constant power, reduce power to function used, set code after "Bugal" electrical function		Implementation:	
8. Congratulate Team	Class Date:	Reported By: A. McGuirk	
		Dept. Name: QRA Manager	
		Telephone No.: (281) 236-3000	

C:\McGuirk\8D\8Dreport.doc




PRESSURE SWITCH "FLOW DIAGRAM" ('92, '93, TOWN CAR)





SUMMARY OF 4/21/99





TEXAS
INSTRUMENTS

Brake Pressure Switch

Potential Thermal Event Theory Profile 4/21/99



77ps2-1		GROSS QTY		COMPLETE	COMPLETE	BEGIN	IMPACT	COMMENTS/CONCERNS
COMPONENT	DESCRIPTION	REQUIRED	SUPPLIER	1KK	2KK	PARTIAL	TO TI	
27405-1	CONVERTER	2,040,000	KF BASSLER	10 WKS	18 WKS	2 WKS	NONE	ADD OVERTIME/MATERIAL AVAILABILITY
27839-1	WASHER / A	2,040,000	DIEMASTER	10 WKS	18 WKS	2 WKS	NONE	MATERIAL AVAILABILITY
27713-1	CUP 77PS	2,040,000	VALENTINE	8 WKS	10 WKS	1 WK	NONE	RAW MATERIAL AVAILABILITY
36868-27	57P8	2,040,000	DISC DEPT	12+ WKS	24 WKS	3 WKS	TOOL \$?	POSSIBLE CAPACITY ISSUE
36900-1	HEXPORT 77	2,040,000	ELCO	10 WKS	25 WKS	3 WKS	NONE	RAW MATERIAL AVAILABILITY
74224-1	KAPTON	204	EI DUPONT	2 WKS	2 WKS	2 WKS	NONE	
27225-1	KAPTON ST	1,102	EI DUPONT	3 WKS	3 WKS	2 WKS	NONE	
74353-1	GASKET	2,040,000	JBL PARKER	8 WKS	18 WKS	3 WKS	NONE	ELIMINATE CORES WILL INCREASE DEL. BY 10%
36888-1	STATIONARY	2,040,000	KF BASSLER	10 WKS	18 WKS	2 WKS	NONE	ADD OVERTIME/MATERIAL AVAILABILITY/ REELS
28744-1	CONTACT-S	2,040,000	DERRINGER	4 WKS	8 WKS	1 WK	NONE	MATERIAL AVAILABILITY
36887-1	MOVABLE TI	2,040,000	KF BASSLER	10 WKS	18 WKS	2 WKS	NONE	ADD OVERTIME/MATERIAL AVAILABILITY/REELS
27716-1	BE/CU ISSU	449	BRUSHWELL	1 WK	2 WKS	1 WK	NONE	NONE
74918-1	RIVET	2,040,000	JOHN HASS	8 WKS	11 WKS	4 WKS	NONE	RAW MATERIAL AVAILABILITY
48515-2	PRESSURE	2,040,000	MIT/MOLDIN	18 WKS	32 WKS	4 WKS	NONE	RAW MATERIAL CHANGE OVER/PRESS CAPACITY
74078-143	CERAMIC PI	2,040,000	PARATECH	7 WKS	15 WKS	2 WKS	NONE	
74247-4	BLUE O'RING	2,040,000	JBL PARKER	8 WKS	10 WKS	2 WKS	NONE	ELIMINATE CORES WILL INCREASE DEL. BY 10%
74787-1	CRIMP RING	2,040,000	VALENTINE	8 WKS	10 WKS	1 WK	NONE	RAW MATERIAL AVAILABILITY
74888-1	RED THREAD	2,040,000	MARK IV CAS	3 WKS	8 WKS	1 WK	NONE	

77PS

SWITCH

TI

7/15,8/1,8/15 250K/MONTH

7 day weeks, thru summer vacations, 'old' plastic mold

3713 4422

1992-94 Town Car/Crown Victoria Mercant Under hood Fire Openings

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Customer Information

Model Year: 92 Make: TOWN CAR VIN: 1KAM81NSM Mileage: 70,000 (+/-)

Do you still own the vehicle? YES If not, do you know where it is? AT RESIDENCE

Customer Name: [REDACTED] Phone: [REDACTED]

Address: [REDACTED] NAPLES, FL [REDACTED]

Did a dealer inspect your vehicle? YES If yes, name of the dealer DERMAIN L-M

INSURANCE CO ALSO INSPECTED VEHICLE

Incident Info

Where did the fire start? Engine compartment? YES Specific location/component? TRANSMISSION OR BRAKE SYSTEM

Was the vehicle:

Engine on? NO Engine off? YES If off, how long was it off? LESS THAN 10 minutes

Moving? NO Parked? YES If on, how long was it on? [REDACTED]

Did customer notice anything unusual prior to fire, such as:

Difficulty shifting out of park? NO

Speed control not working? NO

Brake warning lamp illuminated? NO

Battery not holding a charge? NO

Passes blowing? NO

Stop lamp inoperative? NO

Other? NO

MUST FILL THIS SECTION

NOT FAX TRANSMISSION Date: 3-8-99 Page: 3

NAME: <u>JOE NAME</u>	NAME: <u>FARREN ANSARI</u>
PHONE: <u>[REDACTED]</u>	PHONE: <u>[REDACTED]</u>
TELEPHONE: <u>621-9147</u>	TELEPHONE: <u>313-845-5517</u>
FAX: <u>[REDACTED]</u>	FAX: <u>[REDACTED]</u>

Did you inspect the vehicle? YES

If yes, Did you find any of the following:

Any underhood relays show evidence of overheating? NO

Were the underhood fuse links blown? YES

Were there any fuses that were blown or show evidence of other damage? YES

What areas of the vehicle were damaged? ↑

Was there any damage to any wiring in the area where you believe the fire was started? ↑

Does the air suspension pump show evidence of overheating? NO

Damaged
REARVIEW MIRRORS
CRUISE CONTROL
WIRING WAS REPAIRED
(AGAINST THE FIREWALL)

Was the vehicle equipped with any aftermarket components such as car alarm or remote start?
NO

Was the vehicle repaired? YES When? 12/23 Where? DERMATIN L-M

If the vehicle has not been repaired and was involved in an underbody fire or fire of unknown origin that involved the engine compartment, we would like to inspect it.

Would you allow a Ford representative to inspect your vehicle and if necessary, replace some parts?
YES

COST OF REPAIRS \$272⁰⁰

For Insurers: Parts that we would like from vehicle:

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

EDMS 8 module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay

Other suspect parts

NOTES

- CUSTOMER STILL HAS DAMAGED PARTS
- STATE FARM INSURANCE
AGENT: JOHN W. GRAY
PHONE: 941-261-5623
REP: [REDACTED]

MAR -08'99(MON) 12:44

TEL:313 446 7873

P.003

NYNPS10

NAVIS Vehicle Inquiry

03/08/99 12:39:13

VEHICLE ID: 11NYNPS10 (WARRPARKS) VIN: 11NYNPS10
Vehicle Line: CUB Convey Deliv: 031792 Orig P-Lvl: 218 Selling Dlr: 18A030
Order Receipt: 011592 ShipTo Stat: Curr P-Lvl: 218 Sale Date: 032292
Orig Sched: 032392 Rls-To Stat: NY Order Dlr: 18030 Demo Date:
Inv Frmp: 030592 Orig Int St: 031592 Orig Rls Dlr: 18028 Deliv Type: M
Prod Date: 031292 Curr Int St: 031592 Rls Dlr P&A: 10296 Sales Prd: 092032
Rls Date: 031292 Dlrfin Ext: Warr Start: 032292 Cancel SI:
Memo Consgn: F&C Ext: 041092 WarrG-Ind: Sale Status: G
Orig Fltbus: 031292 Advert Ext: -Date- -Dealer-
Curr Fltbus: 031292 Slopam S&I: Shipped: 031292 88CF69
T/Vname: 9 Curr Stock: 031292 18A030
Addr: State: NY 1st-Prior:
City: CHEMUNAGA N/A-Nopt: 032392 2nd-Prior:
Zip: Warr-Inn-Ind: 3rd-Prior:
V.O.: 1 2 3 4 5 6 7 8
1234567890123456789012345678901234567890123456789012345678901234
MS1NY 43 9623C1019 GA D P1 3P 2GL6L C P T18A030 0 AY8
8 9 0 1 2 3 4 5 6
567890123456789012345678901234567890123456789012345678901234567890
AY H WILLMS 9 B K A751A SWP BU126
FlaHelp F3=Exit F4=Primary Menu F5=Financial Screen F9=Screen 93

LFREL10

*42



3/4/99 called and spoke to Mrs. Gross

Case # 16

NHTSA

1992-95 Town Car/Crown Vic/Grand Marquis Under hood Fire Questionnaire

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Customer Information

Model Year: 92 Make: TOWN CAR VIN: 1LNLM81N0NY Mileage:

Do you still own the vehicle? Yes If not, do you know where it is?

Customer Name:

Address: WEST DAVENPORT, FL

Did a dealer inspect your vehicle? NO If yes, name of the dealer Jenkins L-M / Roland L-M

Was the vehicle involved in a natural disaster and as a result, destroyed? No
If yes, where was the clean-up of the incident performed?

What is the repair history of the vehicle? NOTHING OTHER BRAKES REPLACED

- FRONT BRAKES Repaired one month prior to fire

- Fuse blown few weeks prior to fire

Insurance Agency Information (if relevant)

Insurance agency name: Vehicle did not
Insurance agent address: have full coverage
phone number: N/A
claim number:

Incident Info

Date of Loss: 3-6-99

Where did the fire start? Engine compartment? Specific location/component? Left side of under hood
fire started under steering near brakes, master cylinder

Was the vehicle:
Engine on? Engine off? YES If off, how long was it off? 10-15 MIN
If on, how long was it on?

Moving?
Parked? If parked, where was the vehicle parked? (street, garage or carport) parking lot

Did customer notice anything unusual prior to fire, such as:

Difficulty shifting out of park? NO
Speed control not working? NO
Brake warning lamp illuminated? NO
Battery not holding a charge? NO
Fuses blowing? NO
Stop lamp inoperative? NO
Other?

Did you inspect the vehicle? yes

If yes, Did you find any of the following:

Any underhood relays show evidence of overheating? _____

Were the underhood fuse links blown? YES

Were there any fuses that were blown or show evidence of other damage? YES

What areas of the vehicle were damaged? HOOD, GRILLE, WINDSHIELD, SOME INTERIOR

Was there any damage to any wiring in the area where you believe the fire was started? BURNS

Does the air suspension pump show evidence of overheating? _____

Was the vehicle equipped with any aftermarket components such as car alarm or remote start? _____

Was the vehicle repaired? NO When? _____ Where? _____

If the vehicle has not been repaired and was involved in an underhood fire or fire of unknown origin that involved the engine compartment, we would like to inspect it.

Would you allow a Ford representative to inspect your vehicle and if necessary, replace some parts?

YES

For inspectors: Parts that we would like from vehicles

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

EDIS 3 module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay

Other suspect parts

updated 3/11/99

Ansari, Farsen (F.)

NHTSA

From: Ray Nevi [rnevi@gw.ford.com]
Sent: Friday, March 12, 1999 9:44 AM
To: farsen1@mail.ford.com
Cc: logel@mail.ford.com; rnevi@gw.ford.com
Subject: Lincoln Town Car Underhood Fires

I received info on two more Town Cars this morning. Please arrange to have the vehicles inspected as soon as possible. All the info I have follows:

1. Location: ~~Fort Lauderdale, Florida~~ ~~Fort Lauderdale, Florida~~
VIN: ~~1LNLM81W0N~~ ~~1LNLM81W0N~~ Date of Incident: ~~March 6, 1999~~ ~~March 6, 1999~~ Reported by: ~~owner~~ ~~owner~~

2. Location: ~~Daytona Beach, Florida~~ ~~Daytona Beach, Florida~~
VIN: ~~1LNLM81W0N~~ ~~1LNLM81W0N~~ Date of Incident: ~~March 6, 1999~~ ~~March 6, 1999~~ Reported that vehicle is still at owners home.

Note that it is possible that these are the same incident. The first was reported to me by Bill Peller of Design Analysis. Bill did not provide a VIN. The second was reported to me by the NHTSA.

Contacted
customer
3/12

Regards,
R. A. Nevi PROF8 ID: RNEVI Phone: 88-47888 FAX: 88-42268
Car Safety Investigations Manager, Automotive Safety Office
Suite 500, Fairlane Plaza South

NMVP510

NAVIS Vehicle Inquiry

03/12/99 10:24:34

==>
 VEHICLE ID: 11NY (NMVP510) VIN: 1LNLM81W0NY Div: 3 Status: 800
 Vehicle Line: CVB Convy Deliv: 052992 Orig P-Lvl: 218 Selling Dir: 45K1E8
 Order Recpt: 032092 ShipTo Stat: Curr P-Lvl: 218 Sale Date: 061092
 Orig Sched: 052592 Rls-To Stat: MI Order Dir: 451E8 Demo Date:
 Inv Prep: 051892 Orig Int St: 052792 Orig Rls Dir: 45791 Deliv Type: H
 Prod Date: 052692 Curr Int St: 052792 Rls Dir PAA: 09623 Sales Prd: 092061
 Rls Date: 052692 Dirfin Ext: Warr Start: 061092 Cancel Sl:
 Memo Consign: PAC Ext: 062592 Warrs-Ind: Sale Status: G
 Orig Pltbus: 052692 Advert Ext: -Date- -Dealer-
 Curr Pltbus: 052692 Sleepin #88: Shipped: 052792 88M911
 T/Name: 9 Curr Stock: 052692 45K1E8
 Addr: State: OK 1st-Prior:
 City: OKLAHOMA CITY M/A-Rept: 060992 2nd-Prior:
 Zip: Warr-Ins-Ind: 3rd-Prior:
 V.O. 1 2 3 4 5 6 7 8
 1234567890123456789012345678901234567890123456789012345678901234
 M81NY 43 5125E0346 KC F 3 P1 3P 2UL6L C P K45K1E8 1VAYG
 8 9 0 1 2 3 4 5 6
 567890123456789012345678901234567890123456789012345678901234567890
 BT H WILMLD 9 B 2P A751A WP HZ050
 Fl-Help F3-Exit F4-Primary Menu F5-Financial Screen F9-Screen #3

LPREL10

3/12/99 - AM
 - called
 - not in.
 3/12/99 - PM
 - reached MR. CROW.

3713 4429

CASE #15

NHTSA

1992-95 Town Car/Crown Vic/Grand Marquis Under hood Fire Questionnaire

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Customer Information

Model Year: 92 Make: TOWN CAR VIN#: 1LNLM82N4NY Mileage: 82,000

Do you still own the vehicle? NO If not, do you know where it is? INS. CO OWNS VEH.

Customer Name: [REDACTED] Phone: [REDACTED]

Address: [REDACTED] HOUSTON TX [REDACTED]

Did a dealer inspect your vehicle? NO If yes, name of the dealer WESTPOINT C-M
HOUSTON, TX

Was the vehicle involved in a natural disaster and as a result, destroyed? NO
If yes, where was the clean-up of the incident performed? —

What is the repair history of the vehicle? Transmission overhaul - This
repair was completed 5 day before incident (11-24-98)
Repair was done at DOWNTOWN TRANSMISSION (Conover ST
in Houston.

Insurance Agency Information (if pertinent)

Insurance agency name: USAA AUTOCUINS / MICHELLE TORRES Date of
Insurance agent address: 9802 Fredericksburg, San Antonio TX 78229 incident
phone number: 877-276-0129 - 82 11-29-98
claim number: 11947345

Incident Info

Date of Loss: 11-29-98

Where did the fire start? Engine compartment? Specific location/component?
Started on the ground (possibly from fluid leak) then into engine.

Was the vehicle:
Engine on? — Engine off? YES If off, how long was it off? 2 1/2 hrs
If on, how long was it on? —

Moving? —
Parked? YES If parked, where was the vehicle parked? (street, garage or airport) —

Did customer notice anything unusual prior to fire, such as:

Difficulty shifting out of park? NO
Speed control not working? NO
Brake warning lamp illuminated? YES
Battery not holding a charge? NO
Fuses blowing? NO
Stop lamp inoperative? NO
Other? —

Vehicle was driven
1 hour prior to
parking.

Fluid dripping
under the vehicle
in front end

Leak near
cooling lines
near radiator

Did you inspect the vehicle? Yes

If yes, Did you find any of the following:

Any underhood relays show evidence of overheating? _____

Were the underhood fuse links blown? _____

Were there any fuses that were blown or show evidence of other damage? _____

What areas of the vehicle were damaged? _____

Was there any damage to any wiring in the area where you believe the fire was started?

Does the air suspension pump show evidence of overheating? _____

Was the vehicle equipped with any aftermarket components such as car alarm or remote start?

Was the vehicle repaired? NO When? - Where? -

If the vehicle has not been repaired and was involved in an underhood fire or fire of unknown origin that involved the engine compartment, we would like to inspect it.

Would you allow a Ford representative to inspect your vehicle and if necessary, replace some parts?
YES

For Inspectors: Parts that we would like from vehicle

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

EDIS II module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay

Other suspect parts

revised 3/11/99

*See
attached
fire report*

Ansari, Fares (F.)

From: Ray Nevi [rnevi@gw.ford.com]
Sent: Wednesday, March 10, 1999 2:58 PM
To: faneart1@mail.ford.com
Cc: rnevi@gw.ford.com; jlogel@mail.ford.com
Subject: Lincoln Town Car Investigation

As I indicated in my phone message, the NHTSA has informed Ford of a Town Car underhood fire. Information provided: insurance adjuster name - Michelle Torres; telephone number - (577) 275-0129; date of incident - 11/98; VIN 1LNLM8ZW4NY. Please make investigation arrangements. The NHTSA may want to participate in any vehicle inspections. Therefore please provide me with a couple possible dates for a vehicle inspection if one is to be conducted and I will arrange with the agency.

Regards,
R. A. Nevi PROFS ID: RNEVI Phone: 59-47888 FAX: 59-42288
Car Safety Investigations Manager, Automotive Safety Office
Suite 500, Fairlane Plaza South

Michelle Torres
USA autoclaims dept
Shell return to office 3/11/99
3/10/99 left message.

3/11/99 2nd time -
called
Michelle Torres.

Vehicle located
Insurance Auto Auction
12575 Hiram Clarke Drive
Houston, TX 77045
713-721-5611



CLAIMS FACSIMILE COVER SHEET

DATE: 3-12-99

TO: FAREEN
Ford Motor Comp.FROM: Michelle Torres
USAA CLAIMS

FAX #: 313-845-5669

PHONE #: 877-276-0129

RE: (NAME) [REDACTED]

FAX #: 800-292-8582

YOUR FILE #: 14

OUR INSURED: [REDACTED]

DATE OF LOSS: 11-29-98

OUR FILE #: 11947345

* URGENT

TOTAL # OF PAGES SENT (INCLUDING THIS PAGE): 3

IF YOU DO NOT RECEIVE FULL TRANSMISSION, CALL: 877-276-0129

COMMENTS: I spoke to Jeff at Biera Engineering.

He told me that we, USAA, would not agree to
extraction of any parts at this time. Jeff would
like to be present at the testings and if, at
that time, he feels it is o.k. to allow parts
to be removed, he can approve that.
Thank you.

Michelle Torres

CONFIDENTIALITY NOTICE

The information contained in this facsimile transmission is a CONFIDENTIAL CLAIMS COMMUNICATION and may be protected by one or more legal privileges. It is intended solely for the use of the recipient identified above. If you are not the intended recipient, you are hereby notified that reading, copying, or distributing this transmission is STRICTLY PROHIBITED. The sender has not waived any applicable privilege by sending the accompanying transmission. If you have received this transmission in error, please notify the sender immediately by telephone, and we will arrange to have the transmission returned at no cost to you. Thank you.

03278-9104

3713 4433

MAR 12 '99 11:50 FR FIE HOUSTON 2

1 800 292 8582 TO 913138455669

P.02/03

1118 12/03/98 ATC1

HFIR INCIDENT SUMMARY

0350 010 15:41:16

ENTRY SOURCE STATION FUNCTION (A, C, I) B

REFER TO ARSON ()

INC# 981129409 SUPP 00

DATE: 11/29/98 TIME: 17:51

ADDRESS: 02339

APT/SUITE:

TYPE OF SITUATION FOUND

TYPE OF ACTION TAKEN

DOLLAR LOSSES

VEHICLE FIRE

EXTINGUISHMENT

SUPP 00: \$ 10,000

OVERALL: \$ 10,000

SUPPLEMENTS:

00-00

APT/SUITE: _____

APT/SUITE: _____

CASUALTIES: FIRE: 00 INJURY, 00 FATALITY

CIVIL: 00 INJURY, 00 FATALITY

HAZMAT: NO

OFF IN CHARGE: 071567 JACOBY

CASEY

R CAPTAIN

UNIT: E 033 SHIFT: B RECORD COMPLETE?(Y/N) Y

NUM FIRE PERSONNEL: 004 MUTUAL AID GIVEN OR RECEIVED?(G/R) _

HOLD? _

ARSON RADIO NUMBERS: / FIRE PREV RADIO NUMBER:

DISPATCH DATA: TYPE: SA CAR ON FIRE.

FIRE DISTRICT: 021

DISP ADDR: 02339 GOLDSMITH

APT/SUITE:

GREENERLAR

DR

KEYMAP: 532G BOX: 14252

EMS INC#

ALARM LEV: 0 DISP TIME: 17:53 1097: 17:56 (E 033)

TAPOUT: / : ()

EQUIP: E 033

3713 4434

HOUSTON FIRE DEPARTMENT
FIRE INCIDENT REPORT

DISTRICT 021 STAT 033 B
JACOB CASEY
CAPTAIN - 71567

LINE

A- INCIDENT NUMBER: 98129409 SUPP: 0 INCIDENT DATE: 11/29/1998 INCIDENT TIME: 17:53
 N- NUMBER OF PERSONNEL: 4 MUTUAL AID: NONE ARSON RADIOP / FIRE PREV#
 D- ADDRESS: [REDACTED] APT/SUITE: CENSUS TRAC: 31602
 B- TYPE OF SITUATION FOUND (13): VEHICLE FIRE TYPE OF ACTION TAKEN (1): EXTINGUISHMENT
 C- FIXED PROPERTY USE (982): PAVED PUBLIC STREET IGNITION FACTOR (54): SHORT CIR, GROUND FAULT
 E- OCCUPANTS NAME: UNK TELEPHONE: () -
 F- OWNERS NAME : UNK TELEPHONE: () -
 F- OWNERS ADDRESS: UNK HOUSTON TX
 J- COMPLEX (98): NO COMPLEX MOBILE PROPERTY TYPE (11): AUTOMOBILES
 K- AREA OF FIRE ORIGIN (83): ENGINE AREA, RUNNING GEAR EQUIPMENT INVOLVED (41): FIXED WIRING
 L- FORM OF HEAT OF IGNITION (14): HEAT/LIQUID FUELED EQUIP TYPE OF MATERIAL (51): RUBBER
 L- FORM OF MATERIAL (61): ELECTRICAL WIRE METHOD OF EXTINGUISHMENT (5): PRECONNECTED HOSE LINE
 M- LEVEL OF FIRE ORIGIN (1): GRADE LEVEL TO 9 FT ABOVE ESTIMATED DOLLAR LOSS: \$10,000
 N- NUMBER OF STORIES () : CONSTRUCTION TYPE () :
 D- EXTENT OF FLAME DAMAGE () : EXTENT OF SMOKE DAMAGE () :
 P- DETECTOR PERFORMANCE () : SPRINKLER PERFORMANCE () :
 Q- MATERIAL GENERATING SMOKE () : AVENUE OF SMOKE TRAVEL () :
 R- FORM MATERIAL GEN MOST SMOKE () :
 S- MOBILE PROPERTY YR: 92 MAKE: LINCOLN MODEL: TOWN CAR LIC# JDC268 SER# 1LN1K82U4NY757859
 T- EQUIP INVOLVED YR: MAKE: MODEL: SER#

COMMENTS:

E33 ARRIVED TO FIND A CAR WITH FIRE COMING FROM THE ENGINE COMPARTMENT. HE
 USED TANK WATER TO QUELL THE FLAMES AND WERE ABLE TO SALVAGE MANY ARTICLES FROM
 THE BACK SEAT.

MR 12 '99 11:51 FR FILE HOUSTON 2

1 888 282 8582 TO 91313845569

P.03/03

3713 4435

Case #4

NHTSA

1992-95 Town Car/Crown Vic/Grand Marquis Under hood Fire Questionnaire

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Customer Information

Model Year: 93 Make: TOWN CAR VIN: 1LNLA82WXPY642041 Mileage: _____

Do you still own the vehicle? NO If not, do you know where it is? STATE FARM

Customer Name: _____ Phone: _____

Address: NOT AVAILABLE / CUSTOMER LIVES PART TIME IN OREGON AND FLORIDA

Did a dealer inspect your vehicle? NO If yes, name of the dealer DERMAIN L-M IN FT. MYERS FLORIDA

Was the vehicle involved in a natural disaster and as a result, destroyed? NO
If yes, where was the clean-up of the incident performed? N/A

What is the repair history of the vehicle? See attached AWS print

Insurance Agency Information (If available)

Insurance agency name: STATE FARM / DANIEL GREENE
Insurance agent address: SANISCO FACILITY (SAVING YD)
phone number: 941-636-7610
other: CLAIM # 592100441

Incident Info

Where did the fire start? Engine compartment? _____ Specific location/component? _____ DATE OF FIRE: 1-11-99

Was the vehicle:
Engine on? _____ Engine off? _____ If off, how long was it off? _____
If on, how long was it on? _____

Moving? NO
Parked? YES If parked, where was the vehicle parked? (street, garage or airport) _____

Did customer notice anything unusual prior to fire, such as:

Difficulty shifting out of park? _____
Speed control not working? _____
Brake warning lamp illuminated? _____
Battery not holding a charge? _____
Fuses blowing? _____
Stop lamp inoperative? _____
Other? LOUD BANG

Did you inspect the vehicle? _____

If yes, Did you find any of the following:

Any underhood relays show evidence of overheating? YES

Were the underhood fuse links blown? _____

Were there any fuses that were blown or show evidence of other damage? _____

What areas of the vehicle were damaged? _____

Was there any damage to any wiring in the area where you believe the fire was started?

Does the air suspension pump show evidence of overheating? _____

Was the vehicle equipped with any aftermarket components such as car alarm or remote start?

Was the vehicle repaired? NO When? _____ Where? _____

If the vehicle has not been repaired and was involved in an underhood fire or fire of unknown origin that involved the engine compartment, we would like to inspect it.

Would you allow a Ford representative to inspect your vehicle and if necessary, replace some parts?
YES

For Inspectors: Parts that we would like from vehicles

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

EDMS 8 module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay

Other suspect parts

updated 2/1999

Dan Greene-State Farm- 3-3-99

Conversation with Dan Greene (State Farm) (3-3-99)

-both vehicles had similar fires

-he thinks this involved the ignition switch

-both vehicles had recently been driven (within the past 12 hours of the respective incidents)

-both vehicles had been parked when the fires occurred

-a loud bang noise was heard, after something was smouldering under the hood

Standard Claims List For Model Year 1993

11NLM2WXP	CVB	CM	CPC	CNR	CR	BA	CRK	CYN	14-OCT-1992	27-OCT-1992	325943	USA	3	7792	011001	FIVY	17528	A	W10	93
AWS Chain Keys	725102	Trx Code:	1	Labor Hrs:	2	Labor Cost:	8.8	Material Cost:	23.68	Total Cost:	32.48									
Dt: CA-Sub C:	11601-0	Name:	RICK STARR				PL:	561-4614043	St: FL	City C:	USA	Reg C:	NA	Repr			30-DEC-1992			Do
Cost Comments:			WIPER QUALITY POOR ON DRIVERS SIDE																	
Tech Comments:			REPLACE WIPER BLADES																	
11NLM2WXP	CVB	CM	CPC	CNR	CR	BA	CRK	CYN	14-OCT-1992	27-OCT-1992	325943	USA	3	4024	001001	FIVY	3230	D	N11	01
AWS Chain Keys	725104	Trx Code:	2	Labor Hrs:	9	Labor Cost:	39.6	Material Cost:	104.67	Total Cost:	144.27									
Dt: CA-Sub C:	11601-0	Name:	RICK STARR				PL:	561-4614043	St: FL	City C:	USA	Reg C:	NA	Repr			30-DEC-1992			Do
Cost Comments:																				
Tech Comments:			REPLACE MUFFLER																	
11NLM2WXP	CVB	CM	CPC	CNR	CR	BA	CRK	CYN	14-OCT-1992	27-OCT-1992	325943	USA	11	6006	NANANA	*	7051013	*	N09	12
AWS Chain Keys	725107	Trx Code:	2	Labor Hrs:	5	Labor Cost:	28.5	Material Cost:	0	Total Cost:	28.5									
Dt: CA-Sub C:	11260-0	Name:	KEN SMITH MOTORS INC				PL:	201-4422200	St: NJ	City C:	USA	Reg C:	NA	Repr			27-AUG-1993			Do
11NLM2WXP	CVB	CM	CPC	CNR	CR	BA	CRK	CYN	14-OCT-1992	27-OCT-1992	325943	USA	11	6001	011001	*	17008	*	M10	08
AWS Chain Keys	725106	Trx Code:	2	Labor Hrs:	5	Labor Cost:	28.5	Material Cost:	1.47	Total Cost:	31.97									
Dt: CA-Sub C:	11260-0	Name:	KEN SMITH MOTORS INC				PL:	201-4422200	St: NJ	City C:	USA	Reg C:	NA	Repr			27-AUG-1990			Do
11NLM2WXP	CVB	CM	CPC	CNR	CR	BA	CRK	CYN	14-OCT-1992	27-OCT-1992	325943	USA	24	3413	070100	*	7A056	*	A09	PT
AWS Chain Keys	1227266	Trx Code:	270	Labor Hrs:	0	Labor Cost:	0	Material Cost:	0	Total Cost:	0									
Dt: CA-Sub C:	11601-0	Name:	RICK STARR				PL:	561-4614043	St: FL	City C:	USA	Reg C:	NA	Repr			10-OCT-1994			Do
11NLM2WXP	CVB	CM	CPC	CNR	CR	BA	CRK	CYN	14-OCT-1992	27-OCT-1992	325943	USA	24	3413	070100	*	7A056	*	A09	PT
AWS Chain Keys	1227262	Trx Code:	705	Labor Hrs:	0	Labor Cost:	0	Material Cost:	0	Total Cost:	0									
Dt: CA-Sub C:	11601-0	Name:	RICK STARR				PL:	561-4614043	St: FL	City C:	USA	Reg C:	NA	Repr			10-OCT-1994			Do

3713 4440

11NLME2WXP	CVB	CM	CPC	CBR	CB	BA	CDK	CVN	14-OCT-1992	27-OCT-1992	325043	USA	24	7P01	110581	FVVY	13K399	C	W05	42
AWS Claim Key:	1227265	Trx Code:	ED	Labor Hrs:	5	Labor Cost:	23.96	Material Cost:	54.58	Total Cost:	78.54									
Dr- Cd-Sub Cd:	11601-*	Name:	BUCK STARR	Lincoln-Mercury Inc	Ph:	561-6614043	St: FL	City Cd:	USA	Reg Cd:	NA	Repr	10-OCT-1994	Do						
Cost Comments:																				
Tech Comments:	DRAG B AND R MULTIFUNCTION SWITCH TO REPLACE BAD CONTACTS																			
11NLME2WXP	CVB	CM	CPC	CBR	CB	BA	CDK	CVN	14-OCT-1992	27-OCT-1992	325043	USA	24	7P07	131161	*	19A366	*	L14	42
AWS Claim Key:	1227264	Trx Code:	ED	Labor Hrs:	5	Labor Cost:	23.96	Material Cost:	0	Total Cost:	23.96									
Dr- Cd-Sub Cd:	11601-*	Name:	BUCK STARR	Lincoln-Mercury Inc	Ph:	561-6614043	St: FL	City Cd:	USA	Reg Cd:	NA	Repr	10-OCT-1994	Do						
Cost Comments:																				
Tech Comments:	ANTITHEFT DIAG PASS PERFORM SHELL ORISE B AND R ANTITHEFT MODULE REMOVE AND TAPK PIN 27																			
11NLME2WXP	CVB	CM	CPC	CBR	CB	BA	CDK	CVN	14-OCT-1992	27-OCT-1992	325043	USA	24	3A13	078180	FVVY	7A896	A	N16	00
AWS Claim Key:	1227266	Trx Code:	ED	Labor Hrs:	8.5	Labor Cost:	421.69	Material Cost:	441.25	Total Cost:	862.94									
Dr- Cd-Sub Cd:	11601-*	Name:	BUCK STARR	Lincoln-Mercury Inc	Ph:	561-6614043	St: FL	City Cd:	USA	Reg Cd:	NA	Repr	10-OCT-1994	Do						
Cost Comments:	TRANS WHEES ON AOCIL WHEN YOU LET OFF ON GAS COES AWAY GETTING WORSE WORSE AFTER SEVERAL HOURS ON T																			
Tech Comments:	R AND TRANS TO OVERHUAL REPLACE PLANET AND REV SUN SHELL ARSY NOISY FLUSH CONVERTOR LINE COOLER READ TEST OK																			
11NLME2WXP	CVB	CM	CPC	CBR	CB	BA	CDK	CVN	14-OCT-1992	27-OCT-1992	325043	USA	25	7W12	061405	FVVY	54432A38	B	B15	42
AWS Claim Key:	1227267	Trx Code:	ED	Labor Hrs:	3	Labor Cost:	14.36	Material Cost:	24.35	Total Cost:	38.73									
Dr- Cd-Sub Cd:	11601-*	Name:	BUCK STARR	Lincoln-Mercury Inc	Ph:	561-6614043	St: FL	City Cd:	USA	Reg Cd:	NA	Repr	26-OCT-1994	Do						
Cost Comments:	TRUNK WILL NOT CLOSE																			
Tech Comments:	DIAG ELECTRICAL SYS REPLACE TRUNK SWITCH TEST OK																			
11NLME2WXP	CVB	CM	CPC	CBR	CB	BA	CDK	CVN	14-OCT-1992	27-OCT-1992	325043	USA	39	*	*	*	*	*	*	*
AWS Claim Key:	1227268	Trx Code:	95B4	Labor Hrs:	5	Labor Cost:	25.77	Material Cost:	11	Total Cost:	46.62									
Dr- Cd-Sub Cd:	11604-*	Name:	GERMAIN LINC-MERC OF	NAPLES	Ph:	941-9970011	St: FL	City Cd:	USA	Reg Cd:	NA	Repr	14-DEC-1995	Do						
Cost Comments:	95B4																			
Tech Comments:	95B4 REPLACED SENSOR FOR RECALL																			
11NLME2WXP	CVB	CM	CPC	CBR	CB	BA	CDK	CVN	14-OCT-1992	27-OCT-1992	325043	USA	39	7H12	126308	FVVY	19980	A	A25	01
AWS Claim Key:	1227269	Trx Code:	ED	Labor Hrs:	9	Labor Cost:	46.29	Material Cost:	237.77	Total Cost:	367.35									
Dr- Cd-Sub Cd:	11604-*	Name:	GERMAIN LINC-MERC OF	NAPLES	Ph:	941-9970011	St: FL	City Cd:	USA	Reg Cd:	NA	Repr	14-DEC-1995	Do						
Cost Comments:	MAB A-C BUTTON CRACKED																			
Tech Comments:	CRACKED CONTROL ASSEMBLY-AIR CONDITIONER - REPLACE																			

ILNLMSWXP	C/VB	CM	CPC	CBR	CB	BA	C/DK	C/VN	14-OCT-1992	27-OCT-1992	325043	USA	39	SV01	068301	*	1182	*	N27	14
AWS Claim Key:	18508162	Trx Code:	EM	Labor Hrs:	3.5	Labor Cost:	188.31	Material Cost:	218.97	Total Cost:	475.99									
Dir CA-Sub Cb:	11624-*	Name:	GERMAN LIN-MERC OF																	
			NAPLES																	
Cost Comments:	[REDACTED]																			
Tech Comments:	WARPED BRAKE SHOCK - PAD ASSEMBLIES - HYDRAULIC - REMOVE AND INSTALL OR R																			
ILNLMSWXP	C/VB	CM	CPC	CBR	CB	BA	C/DK	C/VN	14-OCT-1992	27-OCT-1992	325043	USA	41	3A08	078100	ESZZ	7992	ARM	P66	D1
AWS Claim Key:	18292292	Trx Code:	EM	Labor Hrs:	6	Labor Cost:	309.24	Material Cost:	179.16	Total Cost:	551.11									
Dir CA-Sub Cb:	11624-*	Name:	GERMAN LIN-MERC OF																	
			NAPLES																	
Cost Comments:	TORQUE CONV TECH 166																			
Tech Comments:	LEAKING CONVERTER ASSEMBLY - REMOVE AND INSTALL OR REPLACE																			
ILNLMSWXP	C/VB	CM	CPC	CBR	CB	BA	C/DK	C/VN	14-OCT-1992	27-OCT-1992	325043	USA	43	1H83	090804	PIAZ	50460	A	E29	08
AWS Claim Key:	18292248	Trx Code:	EM	Labor Hrs:	2.5	Labor Cost:	139.5	Material Cost:	30.66	Total Cost:	174.89									
Dir CA-Sub Cb:	11619-*	Name:	PORT MYERS																	
			LINCOLN-MERCURY INC																	
Cost Comments:	[REDACTED]																			
Tech Comments:	DIFFERENTIAL SENSOR VOLTAGE TO LOW SERVICE BAY DIAGNOSTIC SYSTEM (SDS) START-UP - DIAGNOSIS																			
ILNLMSWXP	C/VB	CM	CPC	CBR	CB	BA	C/DK	C/VN	14-OCT-1992	27-OCT-1992	325043	USA	43	0H87	010802	FOVY	8213	B	M66	02
AWS Claim Key:	19226466	Trx Code:	EM	Labor Hrs:	3	Labor Cost:	36.02	Material Cost:	7.55	Total Cost:	46.21									
Dir CA-Sub Cb:	11619-*	Name:	PORT MYERS																	
			LINCOLN-MERCURY INC																	
Cost Comments:	THE LINCOLN EMBLEM IS OFF CENTER TO THE LEFT...LEANS																			
Tech Comments:	LINCOLN HOOD ORNAMENT DISTORTED IN TIME TO REPLACE HOOD ORNAMENT																			
ILNLMSWXP	C/VB	CM	CPC	CBR	CB	BA	C/DK	C/VN	14-OCT-1992	27-OCT-1992	325043	USA	43	6A12	018302	*	5436780	*	F12	81
AWS Claim Key:	192264012	Trx Code:	EM	Labor Hrs:	0	Labor Cost:	112.5	Material Cost:	0	Total Cost:	112.5									
Dir CA-Sub Cb:	11619-*	Name:	PORT MYERS																	
			LINCOLN-MERCURY INC																	
Cost Comments:	RUST ON LEFT REAR WINDOW RIM																			
Tech Comments:	LFT REAR WINDOW DIVISION BAR RUSTING TO REPAIR AND REFINISH THE DIVISION BAR IN THE LFR DOOR PANE																			

Any comments? You can contact

NVMP510

NAVIS Vehicle Inquiry

03/03/99 10:47:24

==>
VEHICLE ID: 1LPY (NWZPBBBBS) VIN: 1LNLM82WXPY Div: 3 Status: 801
Vehicle Line: CVB Convy Deliv: 102792 Orig P-Lvl: 310 Selling Dlr: 25C043
Order Recpt: 100692 ShipTo Stat: Curr P-Lvl: 310 Sale Date: 051293
Orig Sched: 101992 Els-To Stat: FL Order Dlr: 25043 Demo Date: 091692
Inv Prep: 100792 Orig Int St: 101692 Orig Els Dlr: 25043 Deliv Type: R
Prod Date: 101492 Curr Int St: 101692 Els Dlr Pak: 11601 Sales Prd: 093052
Els Date: 101492 Dirfin Ext: 111092 Warr Start: 091692 Cancel Sl:
Warrs-Ind: Sale Status: G
Warrs-Ind: -Date- -Dealer-
Orig Pltbus: 101492 Advert Ext: 111092
Curr Pltbus: 101492 Slepen SS#: 6848 Shipped: 101492
T/Name: 1 Curr Stock: 091692 25C043
Addr: State: FL 1st-Prior:
City: FORT PIERCE W/A-Rcpt: 051393 2nd-Prior:
Zip: Warr-Ins-Ind: 3rd-Prior:
V.O.: 1 2 3 4 5 6 7 8
1234567890123456789012345678901234567890123456789012345678901234
M82FY 4L A 2 19K9908 6K S P1 3P8 4 2 L6 A K8 25C043 4 YZ
8 9 0 1 2 3 4 5 6
567890123456789012345678901234567890123456789012345678901234567890
D6 H8 WILNLX 0 D 755A59WP
F1-Help F3-Exit F4-Primary Menu F5-Financial Screen F9-Screen #3

LPREL10

Spoke to LHM GREENE 01/13/99.

CASE # 1

Questions to ask:

1. Was the fire underhood? YES

~~2. Was anyone injured in the fire?~~ NO "Was everyone alright?"
"If anyone was OK"

3. Has the vehicle already been repaired since the fire? NO, VEHICLE WAS TOTALLED

4. Is your insurance company handling this incident? (agency name and agent phone #) STATE FARM INS.
REP. DANIEL GREENE
Phone # 941-656-7610
CLAIM # 592100441

5. Is the vehicle available for Ford inspection? YES

6. What is the exact date of the fire? 1-11-99

7. Was a fire report done? YES

8. Where is the vehicle now? INS. CO. OWNS VEHICLE, IT IS LOCATED AT THEIR
"SADISCO FACILITY" (SAVING)
(TWO)

9. What is the name of the Ford dealer involved, or the nearest dealer?
DERMAIN LINK-MERC in FT. MYERS,
FL.

10. What is the VIN number, the make, model and year of the vehicle?
VEHICLE
MILEAGE: 1LNLM82WXPY642041 '93 TOWN CAR

11. Customer's name, address and phone number?
THOMAS RADTKE - CUSTOMER LIVES IN GERMANY
PART-TIME RESIDENT OF USA / FLORIDA

left message
for Dan
Greene
3/4/99
he's checking stuff

3/10/99
left msg
for Dan
Greene.

left message
3/11/99

- Sunshine Auto owns vehicle.
 - Lewis / shop manager says that parts were removed from vehicle.
 - no inspection would be possible.
- 3/12/99

3/10/99 Ray Nevi spoke to Attorney.
EPA / NHTSA will need to inspect.
Contacted (left message) for BOB JACKSON
WAITING FOR CALL BACK.

Glen Bolton 903-566-1980
he will be in touch w/EPA
vehicles located in TYLER, TX

left
msg
3/12

need to find out loc. of vehicle.

Case # 17

NHTSA

1992-95 Town Car/Crown Vic/Grand Marquis Under hood Fire Questionnaire

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Customer Information

Model Year: 92 Make: TOWN CAR VIN: 1LNLM8ZW6NY Mileage: 80,000-90,000 ^{miles}

Do you still own the vehicle? NO If not, do you know where it is? INSURANCE COMPANY

Customer Name: [REDACTED] Phone: [REDACTED]

Address: [REDACTED] BONITA SPRINGS, FL (customer)

Did a dealer inspect your vehicle? NO If yes, name of the dealer Fort. Myers Line Auto

Was the vehicle involved in a natural disaster and as a result, destroyed? NO

If yes, where was the clean-up of the incident performed? [REDACTED]

What is the repair history of the vehicle? not available

Insurance Agency Information (if applicable)

Insurance agency name: NATIONWIDE INSURANCE

Insurance agent address: PO Box 9052 Fort Charlotte, FL 33149

phone number: BON STENART/REP 941-743-6520

claims number: 7709BA268238

Incident Info

Date of Loss: 3-8-99

Where did the fire start? Engine compartment? YES Specific location/component? Vehicle TOTALLED
(around Firewall)

Was the vehicle:

Engine on? NO Engine off? YES If off, how long was it off? 8-10 hours
If on, how long was it on? [REDACTED]

Moving? NO

Parked? NO If parked, where was the vehicle parked? (street, garage or airport) under the house
(houses are built on stilts)

Did customer notice anything unusual prior to fire, such as:

Difficulty shifting out of park? NO

Speed control not working? NO

Brake warning lamp illuminated? NO

Battery not holding a charge? NO

Fuses blowing? NO

Stop lamp inoperative? NO

Other? [REDACTED]

Did you inspect the vehicle? _____

If yes, Did you find any of the following:

Any underhood relays show evidence of overheating? Not Sure

Were the underhood fuse links blown? _____

Were there any fuses that were blown or show evidence of other damage? Not Sure

What areas of the vehicle were damaged? entire engine, entire front end

Was there any damage to any wiring in the area where you believe the fire was started?

yes - all burnt out

Does the air suspension pump show evidence of overheating? not Sure

Was the vehicle equipped with any aftermarket components such as car alarm or remote start?

Was the vehicle repaired? NO When? - Where? -

If the vehicle has not been repaired and was involved in an underhood fire or fire of unknown origin that involved the engine compartment, we would like to inspect it.

Would you allow a Ford representative to inspect your vehicle and if necessary, replace some parts?

YES

For inspectors: Parts that we would like from vehicles

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

EDIS 8 module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay

Other suspect parts

Vehicle located: ^{Mr. Stearns} (would like to be present)
CUSTOM KAR TOPS
1968 CUSTOM DR.
FORT MYERS FL 33907
(941) 936-6229

updated 2/1/99

Mr C6-Sub Cdr	13189-A	Name:	NEWMAN LINCOLN-MERCURY INC	Ph:	860-2890387	St:	CT	City Cdr	USA	Reg Cdr	NA	Repr	Date:19-SEP-1994	Doc				
Cost Comments:	TRANSMISSION SHUDDERS																	
11NLMS2WGN1	CVB	CM	CFC	CGR	CB	BA	CDE	CVN 22-APR-1992	23-MAY-1992	325037	USA	32	SP07 068701	P4AZ	2805	B	H82	41
AWS Claim Key:	2979292	Trs Code:	EB4	Labr Hrs:	2	Labr Cost:	41.31	Material Cost:	133.78	Total Cost:	215.22							
Mr C6-Sub Cdr	11619-A	Name:	FORT MYERS LINCOLN-MERCURY INC	Ph:	941-4332300	St:	FL	City Cdr	USA	Reg Cdr	NA	Repr	Date:15-DEC-1994	Doc	8-86			
Cost Comments:	CUST STATES FRONT BRAKES ARE HANGING UP. ADV>																	
Tech Comments:	BRAKE BOOSTER BINDING BRAKE BOOSTER ASSEMBLY - REPLACE>																	
11NLMS2WGN1	CVB	CM	CFC	CGR	CB	BA	CDE	CVN 22-APR-1992	23-MAY-1992	325037	USA	32	YW06 180197	POVY	14486	A	L15	D4
AWS Claim Key:	2212278	Trs Code:	EB3	Labr Hrs:	1.3	Labr Cost:	67.13	Material Cost:	98.58	Total Cost:	164.88							
Mr C6-Sub Cdr	11619-A	Name:	FORT MYERS LINCOLN-MERCURY INC	Ph:	941-4332300	St:	FL	City Cdr	USA	Reg Cdr	NA	Repr	Date:15-DEC-1994	Doc	8-86			
Cost Comments:	CUST STATES L F DOOR LOCK NUMBER PAD IS DISCOLORED. ADV>																	
Tech Comments:	KEYLESS ACTUATOR FEELING KEYLESS ENTRY SYSTEM - DIAGNOSIS>																	
11NLMS2WGN1	CVB	CM	CFC	CGR	CB	BA	CDE	CVN 22-APR-1992	23-MAY-1992	325037	USA	32	SC06 060500	POVY	18978	A	T90	81
AWS Claim Key:	2979271	Trs Code:	EB4	Labr Hrs:	1.9	Labr Cost:	98.12	Material Cost:	14.88	Total Cost:	117.46							
Mr C6-Sub Cdr	11619-A	Name:	FORT MYERS LINCOLN-MERCURY INC	Ph:	941-4332300	St:	FL	City Cdr	USA	Reg Cdr	NA	Repr	Date:15-DEC-1994	Doc	8-86			
Cost Comments:	CUST STATES BOTH FRONT DOOR SPEAKER GRILLERS ARE DISCOLORED. ADV>																	
Tech Comments:	BOTH F SPEAKER COVERS DISCOLORED TRIM PANEL-FRONT DOOR - REMOVE AND INSTALL>																	
11NLMS2WGN1	CVB	CM	CFC	CGR	CB	BA	CDE	CVN 22-APR-1992	23-MAY-1992	325037	USA	32	7644 150105	*	18806	*	A15	D4
AWS Claim Key:	2977292	Trs Code:	EB3	Labr Hrs:	.6	Labr Cost:	38.98	Material Cost:	0	Total Cost:	33.38							
Mr C6-Sub Cdr	11619-A	Name:	FORT MYERS LINCOLN-MERCURY INC	Ph:	941-4332300	St:	FL	City Cdr	USA	Reg Cdr	NA	Repr	Date:23-DEC-1994	Doc	8-86			
Cost Comments:	REINSTALL RADIO>																	
Tech Comments:	RADIO FEELING RADIO - REMOVE>																	
11NLMS2WGN1	CVB	CM	CFC	CGR	CB	BA	CDE	CVN 22-APR-1992	23-MAY-1992	325037	USA	39	7085 1801XX	*	20013	*	H19	28
AWS Claim Key:	2149692	Trs Code:	EB3	Labr Hrs:	1.7	Labr Cost:	87.62	Material Cost:	0	Total Cost:	87.62							
Mr C6-Sub Cdr	11624-A	Name:	GERMAIN LINC-MERC OF NAPLES	Ph:	941-9976811	St:	FL	City Cdr	USA	Reg Cdr	NA	Repr	Date:04-AUG-1995	Doc	8-86			
Cost Comments:	ANTI LOCK BRK LIGHT CO MBS ON AND STAYS ON TIL TURN CAR OFF INTERM>																	
Tech Comments:	OPEN CIRCUIT WIRING ASSEMBLY - REPAID>																	
11NLMS2WGN1	CVB	CM	CFC	CGR	CB	BA	CDE	CVN 22-APR-1992	23-MAY-1992	325037	USA	41	7084 1203XX	*	19888	*	C20	V3
AWS Claim Key:	2149679	Trs Code:	EB3	Labr Hrs:	.5	Labr Cost:	25.77	Material Cost:	0	Total Cost:	25.77							

Dir C6-Sub C6	11424*	Name:	GERMAIN LIND-MERC OF	Ph:	941-5974011	St:	FL	City C6	USA	Reg C6	NA	Rep:	Mon:20-SEP-1995	Doc:	206
Car Comments:	AC BLOWE OUT TOP AND BOTTOM ONLY AFTER DRIVING, NOTING OUT VENTS														
Tech Comments:	REPAIRED VACUUM LEAK VACUUM TUBE-HOSE - REPAIR														

Any comments? You can contact



webmaster@aus-ford.com

3713 4463

NVNP510

NAVIS Vehicle Inquiry

03/12/99 15:36:23

```

==>
VEHICLE ID: 1LNY (NWIFAMMMS) VIN: 1LN1MB2W6N DIV: 3 Status: 800
Vehicle Line: CVB Convy Deliv: 042992 Orig P-Lvl: 218 Selling Dlr: 25B037
Order Recpt: 030292 ShipTo Stat: Curr P-Lvl: 218 Sale Date: 052392
Orig Sched: 042092 Elm-To Stat: FL Order Dlr: 25037 Demo Date:
Inv Prep: 041092 Orig Int St: 042792 Orig Rls Dlr: 25037 Deliv Type: 0
Prod Date: 042292 Curr Int St: 042792 Rls Dlr P&A: 11619 Sales Prd: 092053
Rls Date: 042392 Dlrfin Ext: 052592 Warr Start: 052392 Cancel Sl:
Memo Consgn: P&C Ext: 052592 Warrs-Ind: Sale Status: G
Orig Pltbus: 042392 Advert Ext: 052592 -Date- -Dealer-
Curr Pltbus: 042392 Slspn 88: 7022 Shipped: 042392
T/Name: Curr Stock: 042392 25B037
Addr: State: FL 1st-Prior:
City: FT MYERS H/A-Recpt: 052692 2nd-Prior:
Zip: Warr-Ins-Ind: 3rd-Prior:
V.O. 1 2 3 4 5 6 7 8
12345234567890123456789012345678901234567890123456789012345678901234
MB2NY 4L 2 20D8520 2C D P14 3P 4 2 L6L P 25B037 1 YZ
8 9 0 1 2 3 4 5 6
567890123456789012345678901234567890123456789012345678901234567890
DU H8 W1LNL6 4 D 755A 9WP
F1-Help F3-Exit F4-Primary Menu F5-Financial Screen F9-Screen #3

```

LPREL10

Case # 1

1992-95 Town Car/Crown Vic/Grand Marquis Under hood Fire Overheating

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Customer Information

Model Year: 92 Make: TOWN CAR VIN: 1LNLM81W5NY Mileage: 70,000 (+/-)

Do you still own the vehicle? YES If not, do you know where it is? AT RESIDENCE

Customer Name: [REDACTED] Phone: [REDACTED]

Address: [REDACTED] NAPLES, FL

Did a dealer inspect your vehicle? YES If yes, name of the dealer DERMAIN L-M
INSURANCE CO ALSO INSPECTED VEHICLE

Incident Info

Where did the fire start? Engine compartment? YES Specific location/component? TRANSMISSION OR
BRAKE SYSTEM

Was the vehicle:

Engine on? NO Engine off? YES If off, how long was it off? LESS THAN 10 minutes
If on, how long was it on? [REDACTED]

Moving? NO Parked? YES

Did customer notice anything unusual prior to fire, such as:

Difficulty shifting out of park? NO

Speed control not working? NO

Brake warning lamp illuminated? NO

Battery not holding a charge? NO

Fuses blowing? NO

Stop lamp inoperative? NO

Other? NO

Did you inspect the vehicle? YES

If yes, Did you find any of the following:

Any underhood relays show evidence of overheating? NO

Were the underhood fuse links blown? YES

Were there any fuses that were blown or show evidence of other damage? YES

What areas of the vehicle were damaged? TRANSMISSION

Was there any damage to any wiring in the area where you believe the fire was started? YES

Does the air suspension pump show evidence of overheating? NO

Damaged

- REARVIEW MIRRORS
- CRUISE CONTROL
- WIRING WAS REPLACED (AGAINST THE FIREWALL)

Was the vehicle equipped with any aftermarket components such as car alarm or remote start?

NO

Was the vehicle repaired? YES When? 12/23 Where? DERMAIN C-M

If the vehicle has not been repaired and was involved in an underhood fire or fire of unknown origin that involved the engine compartment, we would like to inspect it.

Would you allow a Ford representative to inspect your vehicle and if necessary, replace some parts?

YES

COST OF REPAIRS \$272⁰⁰

For Inspectors: Parts that we would like from vehicle

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

EDMS II module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay

Other suspect parts

NOTES

- CUSTOMER STILL HAS DAMAGED PARTS
- STATE FARM INSURANCE
AGENT : JOHN W. GRAY
PHONE : 941-261-5623
REP - JACKIE

NVNPS10

NAVIS Vehicle Inquiry

03/08/99 12:39:13

==>
 VEHICLE ID: 11NY (WNIPBHHH) VIN: 11NLM81W5NY Div: 3 Status: 800
 Vehicle Line: CVB Convy Deliv: 031792 Orig P-Lvl: 218 Selling Dlr: 18A030
 Order Recpt: 011692 ShipTo Stat: Curr P-Lvl: 218 Sale Date: 032292
 Orig Sched: 032392 Els-To Stat: NY Order Dlr: 18030 Demo Date:
 Inv Prep: 030592 Orig Int St: 031692 Orig Els Dlr: 18028 Deliv Type: M
 Prod Date: 031292 Curr Int St: 031692 Els Dlr PAA: 10296 Sales Prd: 092032
 Els Date: 031292 Dirfin Ext: Warr Start: 032292 Cancel Sl:
 Memo Consign: P&C Ext: 041092 WarrS-Ind: Sale Status: G
 Orig Fltbus: 031292 Advert Ext: -Date- -Dealer-
 Curr Fltbus: 031292 Sleepn SS#: Shipped: 031292 88CF69
 T/Name: 9 Curr Stock: 031292 18A030
 Addr: State: NY 1st-Prior:
 City: CHERKTOWAGA N/A-Rcpt: 032392 2nd-Prior:
 Zip: Warr-Ins-Ind: 3rd-Prior:
 V.O.: 1 2 3 4 5 6 7 8
 1234567890123456789012345678901234567890123456789012345678901234
 M81NY 43 9623C1019 GA D P1 3P 2GL6L C P T18A030 0 AY2
 9 9 0 1 2 3 4 5 6
 567890123456789012345678901234567890123456789012345678901234567890
 AY H W1LNL5 9 B K A751A 9WP BU126
 Fl-Help F3-Exit F4-Primary Menu F5-Financial Screen F9-Screen 03

LPREL10

#92



4 MUST FILL THIS BOX

MINI-PAK Transmittal

3-8-99 3

Joe Name

Fareed Ansari

TELEPHONE 213-845-5577

FAX NO 621-8147

3/4/99 called and spoke to

3713 4458

Case # 2

1991-95 Town Car/Crown Vic/Grand Marquis Under hood Fire Questionnaire

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Customer Information

Model Year: 93 Make: TOWNCAR VIN# 1LL4S2W6F [REDACTED] License: Ariz and 78000

Do you still own the vehicle? NO If not, do you know where it is? TAKEN BY STATE FARM INSURANCE

Customer Name: Phone:

Address: NAPERVILLE, IL

Did a dealer inspect your vehicle? NO If yes, name of the dealer FAIR OAKS L-M

Was the vehicle involved in a natural disaster and as a result, destroyed? **NO**

If yes, where was the clean-up of the incident performed?

What is the repair history of the vehicle? WAS AT DETROITSHIP 10 DAYS
PRIOR TO FIRE. REPAIR INVOLVED POWER ANTENNA/
ELECTRICAL WORK (see attached copy of AHS claims
report).

Incident Info

Where did the fire start? Engine compartment? _____ Specific location/component? TOWARD WAPER RIGHT
CORNER NEAR FIRE WALL.

Was the vehicle:

Engine on? _____ Engine off? YES If off, how long was it off? 5 MINUTES
If on, how long was it on? _____

Moving? _____
 Period? _____ If parked, where was the vehicle parked? (street, garage or airport) _____

Did customer notice anything unusual prior to fire, such as:

Difficulty shifting out of park? **NO**

Speed control not working? NO

Brake warning lamp illuminated? NO

Battery not holding a charge? NO

Power blowing? NO

Stop loop imperative? NO

Other? _____

CONTACTED EAA
FOR INSPECTION:
3-11-99
4PM

SALE TO ALAN THOMAS

DATE CALLED: 3-10-99

3713 4459

Did you inspect the vehicle? BRIEFLY, She noticed the fire starting near fuse box

If yes, Did you find any of the following:

Any undetected relays show evidence of overheating? NO

Were the underhood fuse links blown? NO

Were there any fuses that were blown or show evidence of other damage? NO

What areas of the vehicle were damaged? ENTIRE FRONT END, VEHICLE WAS TOTALLED, PLUS LEFT FRONT TIRE

Was there any damage to any wiring in the area where you believe the fire was started?
SHE DOESN'T KNOW

Does the air suspension pump show evidence of overheating? NO

Was the vehicle equipped with any aftermarket components such as car alarm or remote start?
NONE

Was the vehicle repaired? NO When? _____ Where? _____

If the vehicle has not been repaired and was involved in an underhood fire or fire of unknown origin that involved the engine compartment, we would like to inspect it.

Would you allow a Ford representative to inspect your vehicle and if necessary, replace some parts?
CUSTOMER NO LONGER OWNS VEHICLE

Insurance agency: STATE FARM ; INVESTIGATIVE AGENT (CRASH UNIT)
JOHN KESSLER 630-406-5061
CLAIM # 139087166

For Investigators: Parts that we would like from vehicle:

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

EDS 8 module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay

Other suspect parts

STATE
FARM
HAS APPROVED
INSPECTION:

Insurance Agent must be present { VEHICLE LOCATED:
280 EAST SULLIVAN RD
AURORA IL 60505
630-896-5300

AGENCY ADDRESS:
JOHN KESSLER
185 NORTH RANDALL RD
BATAVIA, IL 60510
(630) 406-5061
(888) 209-4937
PIN # 28050

3713 4480

Cost Comments: WIPERS NOT SEATING CORRECTLY & NOISY AFTER SHUT OFF P/N Y N /
Tech Comments: REPLACE WIPER MOTOR EXACTLY & NOISY AFTER SHUT OFF P/N Y N / NW C 000YH N902B41M32A ESPCEFRASE G1 19960736D AJN11N 19960736D HJN11N

1LNLM82W6PY C/VB CM CFC CBR CB BA CDE C/VN 27-AUG-1992 31-AUG-1992 38429P USA 55 3A86 870100 E20Z 7852 A L72 D4 6
AWS Claim Key: 21638763 Trx Codes 0736D Labor Hrs: 5 Labor Cost: 32.48 Material Cost: 7.53 Total Cost: 40.01
Dir Cl-Sub Cl: 18533-0 Name: FAIR OAKS LINCOLN-MERCURY INC P/N 636-7594500 St IL Ctry Cd: USA Reg Cd: NA Reg Date: 07-FEB-1997 Doc #412
Cost Comments: CK TRANSMISSION LEAK
Tech Comments: CHECK FOR LEAKS REPLACED LEAKING TAIL SHAFT SEAL

1LNLM82W6PY C/VB CM CFC CBR CB BA CDE C/VN 27-AUG-1992 31-AUG-1992 38429P USA 55 3C84 870100 F5AZ 7A247 A P67 42 6
AWS Claim Key: 21638760 Trx Codes 0736D Labor Hrs: 1.5 Labor Cost: 116.93 Material Cost: 48.34 Total Cost: 175.47
Dir Cl-Sub Cl: 18533-0 Name: FAIR OAKS LINCOLN-MERCURY INC P/N 636-7594500 St IL Ctry Cd: USA Reg Cd: NA Reg Date: 07-FEB-1997 Doc #
Cost Comments: CHECK TRANS HARD SHIFT
Tech Comments: RAN 8508 TEST KORO PAIR KORO P116 REPLACED BAD TR SENSOR

1LNLM82W6PY C/VB CM CFC CBR CB BA CDE C/VN 27-AUG-1992 31-AUG-1992 38429P USA 55 3A85 870100 F4AZ 7A103 A 789 42 6
AWS Claim Key: 21748822 Trx Codes 0736D Labor Hrs: 9.2 Labor Cost: 397.63 Material Cost: 456.78 Total Cost: 1280.53
Dir Cl-Sub Cl: 18533-0 Name: FAIR OAKS LINCOLN-MERCURY INC P/N 636-7594500 St IL Ctry Cd: USA Reg Cd: NA Reg Date: 04-MAR-1997 Doc #413
Cost Comments: CK TRANS SLIPS EXCESSIVELY CK HISTORY
Tech Comments: ROADTESTED VERIFIED CONCERN PAN PRESSURE TEST REMOVED PAN FOR FLUID INSPECTION BURNED AND METAL IN PAN REMOVED TRANS OVERHOL-AU TRANS FLUSH CONVERTOR AND COOLER LINES ROADTESTED EVERYTHING OK NOW

1LNLM82W6PY C/VB CM CFC CBR CB BA CDE C/VN 27-AUG-1992 31-AUG-1992 38429P USA 56 7701 110501 * LMK359 * L25 42 6
AWS Claim Key: 21818891 Trx Codes 0736D Labor Hrs: 1.1 Labor Cost: 71.46 Material Cost: 65.27 Total Cost: 136.6
Dir Cl-Sub Cl: 18533-0 Name: FAIR OAKS LINCOLN-MERCURY INC P/N 636-7594500 St IL Ctry Cd: USA Reg Cd: NA Reg Date: 02-APR-1997 Doc #414
Cost Comments: L.S TURN SIGNAL & BRIGHT LITES B.O.F
Tech Comments: REPLACE MULTIFUNCTION SWITCH

1LNLM82W6PY C/VB CM CFC CBR CB BA CDE C/VN 27-AUG-1992 31-AUG-1992 38429P USA 61 7701 110501 FIVY 13K359 C W05 X2 7
AWS Claim Key: 22278262 Trx Codes SPW Labor Hrs: 1.1 Labor Cost: 73.81 Material Cost: 49.83 Total Cost: 123.65
Dir Cl-Sub Cl: 18533-0 Name: FAIR OAKS LINCOLN-MERCURY INC P/N 636-7594500 St IL Ctry Cd: USA Reg Cd: NA Reg Date: 13-AUG-1997 Doc #416
Cost Comments: CK HIGH BEAMS INCORP.CE AND ADJUST
Tech Comments: TEST AND REPLACE M.F. SWITCH

mileage: 70804

3713 4461

John Kessler

3/11/99

-he is checking
on removing parts approval

AURORA, IL

he has
many
Town Car
on his
lot

-release form?
-parts?

VEHICLE LOCATED:

280 East Sullivan Rd
Aurora IL 60505
(630) 896-5306

agent
must be present

John Kessler
185 North Randall Rd
Batavia, IL 60510
(630) 406-5061
PIN (888) 209-4937 - PIN 28050

Case # 5

1992-95 Town Car/Crown Vic/Grand Marquis Under hood Fire Questionnaire

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Customer Information

Model Year: 92 Make: GRAND MARQUIS VIN: 2MEBT5N6NA Mileage:

Do you still own the vehicle? NO If not, do you know where it is? STATE FARM INS.

Customer Name: Phone: NOT AVAILABLE

Address: NOT AVAILABLE

Did a dealer inspect your vehicle? NO If yes, name of the dealer DERMAIN L-M

Was the vehicle involved in a natural disaster and as a result, destroyed? NO

If yes, where was the clean-up of the incident performed?

What is the repair history of the vehicle?

See attached

Insurance Agency Information (if pertinent)

Insurance agency name: STATE FARM INSURANCE (DANIEL GREENE)

Insurance agent address: SADLER FACILITY (SAVING YD)

phone number: 941-656-7610

other: CLAIM # 593128346

DATE OF
FIRE

12-28-98

Incident Info

Where did the fire start? Engine compartment? Specific location/component?

Was the vehicle:

Engine on? Engine off? YES If off, how long was it off?

If on, how long was it on?

Moving?

Parked? YES If parked, where was the vehicle parked? (street, garage or airport)

Did customer notice anything unusual prior to fire, such as:

Difficulty shifting out of park?

Speed control not working?

Brake warning lamp illuminated?

Battery not holding a charge?

Fuses blowing?

Stop lamp inoperative?

Other: LOUD BANG, SOMETHING SHOULDERING UNDER HOOD

Did you inspect the vehicle? _____

If yes, Did you find any of the following:

Any underhood relays show evidence of overheating? YES

Were the underhood fuse links blown? _____

Were there any fuses that were blown or show evidence of other damage? _____

What areas of the vehicle were damaged? _____

Was there any damage to any wiring in the area where you believe the fire was started?

Does the air suspension pump show evidence of overheating? _____

Was the vehicle equipped with any aftermarket components such as car alarm or remote start?

Was the vehicle repaired? NO When? _____ Where? NOT APPLICABLE

If the vehicle has not been repaired and was involved in an underhood fire or fire of unknown origin that involved the engine compartment, we would like to inspect it.

Would you allow a Ford representative to inspect your vehicle and if necessary, replace some parts?
YES

For Inspectors: Parts that we would like from vehicles

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

EDIS 8 module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay

Other suspect parts

updated 3/10/99

note to Dan Greene 5/27/97

CASE #
5

Questions to ask:

1. Was the fire underhood? YES
2. Was anyone injured in the fire? NO
3. Has the vehicle already been repaired since the fire? NO, TOTALLED
4. Is your insurance company handling this incident? (agency name and agent phone #) STATE FARM INS.
REP: DANIEL GREENE
Ph: 941-656-7610
CLAIM #: 592088345
5. Is the vehicle available for Ford inspection? YES
6. What is the exact date of the fire? 12-28-98
7. Was a fire report done? YES
8. Where is the vehicle now? STATE FARM'S STORAGE/SALVAGE → SADISCO FACILITY
9. What is the name of the Ford dealer involved, or the nearest dealer? DERMAIN LINCOLN-MERC
10. What is the VIN number, the make, model and year of the vehicle?
VEHICLE MILEAGE: 2MECMT5N6NX [REDACTED] 192 MERC.
GRAND MARQUIS
11. Customer's name, address and phone number?
Leland Lintz.

Dan Greene-State Farm- 3-3-99

Conversation with Dan Greene (State Farm) (3-3-99)

-both vehicles had similar fires

-he thinks this involved the ignition switch

-both vehicles had recently been driven (within the past 12 hours of the respective incidents)

-both vehicles had been parked when the fires occurred

-a loud bang noise was heard, after something was smoldering under the hood

NVMP510

NAVIS Vehicle Inquiry

03/03/99 10:51:28

-->
VEHICLE ID: 2MXX [REDACTED] VIN: 2MECM7SW6ND DIV: 3 Status: 800
Vehicle Line: CFP Convey Deliv: 032592 Orig P-Lvl: 213 Selling Dlr: 25B037
Order Recpt: 030492 ShipTo Stat: Curr P-Lvl: 213 Sale Date: 063092
Orig Sched: 031692 Rls-To Stat: FL Order Dlr: 25037 Demo Date:
Inv Prep: 031192 Orig Int St: 031992 Orig Rls Dlr: 25037 Deliv Type: L
Prod Date: 031792 Curr Int St: 031992 Rls Dlr P&A: 11619 Sales Prd: 092071
Rls Date: 031792 Dirfin Ext: 042592 Warr Start: 063092 Cancel Sl: 063092
Memo Consgn: PaC Ext: 042592 WarrS-Ind: Sale Status: G
Orig Plthbus: 031792 Advert Ext: 042592 -Data- -Dealer-
Curr Plthbus: 031792 Slspen SS#: 0218 Shipped: 031892
T/Name: 9 Curr Stock: 031792 25B037
Addr: [REDACTED] State: FL 1st-Prior:
City: FT LAUDERDALE W/A-Recpt: 071392 2nd-Prior:
Zip: [REDACTED] Warr-Ins-Ind: 3rd-Prior:
V.O.: 1 2 3 4 5 6 7 8
12345234567890123456789012345678901234567890123456789012345678901234
M75NXY 44 A2 16C7820 1 4C D P1 J3P8Q7 KH 3 25B037 1 DD
8 9 0 1 2 3 4 5 6
567890123456789012345678901234567890123456789012345678901234567890
GH3H 3 2 W2MEC6 0 2 172A 9WP S
F1-Help F3-Exit F4-Primary Menu F5-Financial Screen F9-Screen #3

LPREL10

*Case #5**Customer*

Standard Claims List For Model Year 1992

2MECMT5W20	CHP	CM	CFA	CAJ	CB	AW	CDE	CVN	17-MAR-1992	30-JUN-1992	325837	USA	24	5V81	860381	F3VY	1125	A	N27	14	271
AWB Claim Key:	2789276	Trx Code:	EM	Labr Hrs:	3	Labr Cost:	41.31	Material Cost:	109.15	Total Cost:	150.46										
Wt CS-Sub Cde	11619-P	Name:	PORT MYERS	Lincoln-Mercury Inc	Ph:	941-4332300	St:	FL	City Cde:	USA	Reg Cde:	NA	Repr	13-JUN-1994	Doc	840					
Cost Comments:	BRAKES PULSATE WHEN STOPPING- WARE																				
Tech Comments:	FRONT ROTORS WARPED DISC BRAKE ROTOR- FRONT																				
2MECMT5W20	CHP	CM	CFA	CAJ	CB	AW	CDE	CVN	17-MAR-1992	30-JUN-1992	325837	USA	31	2B64	890783	F3PZ	12299	C	D36	46	289
AWB Claim Key:	2767500	Trx Code:	SW	Labr Hrs:	1.1	Labr Cost:	56.8	Material Cost:	60.48	Total Cost:	117.28										
Wt CS-Sub Cde	11619-P	Name:	PORT MYERS	Lincoln-Mercury Inc	Ph:	941-4332300	St:	FL	City Cde:	USA	Reg Cde:	NA	Repr	19-DEC-1994	Doc	80823					
Cost Comments:	ENGINE HAS A SEVERE MISF. ADVISE>																				
Tech Comments:	PLUG WIRE IS BURNED OUT IGNITION SYSTEM - HEADLIGHTS>																				

Any comments? You can contact

webmaster@aww.ford.com

WAITING FOR
CALL FROM
DAN CREEVE

left
msg
3/11/99

3/12/99
-nothing
to inspect
-vehicles were
used for parts

Sunshine Auto / own vehicles
(owns both vehicles)
305-884-3727

3/12/99
- 3:12 P.M. done

3713 4470

Case # 6

1992-95 Town Car/Crown Vic/Grand Marquis Under hood Fire Questionnaire

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Customer Information

Model Year: 92 Make: Town Car VIN: 1LNLM82W7N1 Mileage: 125,000

Do you still own the vehicle? Yes If not, do you know where it is? _____

Customer Name: _____ Phone: _____

Address: _____ Beaumont, TX _____

Did a dealer inspect your vehicle? Yes If yes, name of the dealer Mike Smith L-M Kinsel L-M Beaumont

Was the vehicle involved in a natural disaster and as a result, destroyed? NO

If yes, where was the clean-up of the incident performed? N/A

What is the repair history of the vehicle? at 75,000 miles, transmission was rebuilt - clutches were burnt (Solenoid?)

Insurance Agency Information (if pertinent)

Insurance agency name: Farmers Insurance
Insurance agent address: George Ritchman
phone number: _____
other: _____

Fire occurred @
6:20 pm
12-6-98

Incident Info

Where did the fire start? Engine compartment? Yes Specific location/component? electrical/wire harness, brake booster, master cylinder

Was the vehicle:

Engine on? _____ Engine off? _____ If off, how long was it off? 2 1/2 - 3 hrs only drove 10 miles that day

Moving? _____

Parked? Yes If parked, where was the vehicle parked? (street, garage or carport) garage

Did customer notice anything unusual prior to fire, such as:

Difficulty shifting out of park? _____
Speed control not working? YES
Brake warning lamp illuminated? _____
Battery not holding a charge? _____
Fuses blowing? _____
Stop lamp inoperative? _____
Other? _____

* Vehicle is being repaired at Kinsel L-M (taken list of Jo)

* Insurance Co does not want to cover more than 1/2 cost

Did you inspect the vehicle? _____

If yes, Did you find any of the following:

Any underhood relays show evidence of overheating? NO

Were the underhood fuse links blown? NO

Were there any fuses that were blown or show evidence of other damage? NO

What areas of the vehicle were damaged? engine, wire harnesses, cruise control

Was there any damage to any wiring in the area where you believe the fire was started?

Yes

Does the air suspension pump show evidence of overheating? NO

Was the vehicle equipped with any aftermarket components such as car alarm or remote start?

NO

Was the vehicle repaired? NO When? _____ Where? at dealership

If the vehicle has not been repaired and was involved in an underhood fire or fire of unknown origin that involved the engine compartment, we would like to inspect it.

Would you allow a Ford representative to inspect your vehicle and if necessary, replace some parts?

Yes

For Inspectors: Parts that we would like from vehicles

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

EDIS 2 module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay

Other suspect parts

updated 3/10/99

DEALER: 152084 KINSEL FORD INC
Address:
City: BEAUMONT
State/Prov: TX ZIP/Postal: 77704
Country: USA Trained: Y
Dlr Phone: 409 838 6611
Svc Phone: 409 838 6612
Svc Hours: 7:00 AM TO 6:00 PM
Directions:

P&A Code: 04413
Sales Region: 52 DALLAS
Sales Zone: M
PCSD Region: 52 DALLAS
Market: H2
Market Area:

**** BODYSHOP PHONE****

A

C POSITION	Employee Name
DEALER/PARTNER	KINSEL JR., JOE B
FINANCE & INSUR MANAGER	SPARKS, ANDREW
GENERAL MANAGER	MCFARLAND, DICK
PARTS MANAGER	MAXWELL, BILLY
SALES MANAGER	DRIVER, MIKE
SERVICE MANAGER	THORNTON, GARY L

F1-Help F2-IssueList
NO MORE RECORDS AVAILABLE

F7-Prev

F8-Next

F11-Menu

F12-Return

LPREL10

3/10/99

called dealer, spoke to SINGER / BILL MODSETTE

Vehicle came in 12-30

- Ticket closed 2-16 (cust declined work)

- Bill Modisette will call back w/ more info

3/11/99

- Vehicle is no longer at Kinsel Ford Inc.

- According to RO, it appears vehicle was picked up by customer on 2-16

SFCHADMA

Action Detail

03/04/99 10:23:41

VIN: 1LNLM82W7NY697561 Year: 1992 Model: TOWN CAR
 Owner Status: SUBSEQUENT WSD: 05/21/92
 Name: MR EDGAR REDBAUX Hm Ph: (409)842-4347
 Trmt: Case: 556522678 Day Ph: (409)839-4433
 Symptom Desc: FIRE/SMOKE VISIBLE FLAME UNDERHOOD
 Reason Desc: LEGAL - REFER TO INSURANCE COMPANY
 Dealer: MIKE SMITH LINCOLN-MERCURY
 Issue Type: 02 INFORMATION Issue Status: C CLOSED
 Comm Type: PH PHONE Odometer Reading: 120000 MI
 Analyst: AMATO ANTOINETTA AMATO Document Number:
 Action Date: 12/07/98 Action Data: Action Time: 11:15:56 EST
 Origin Desc: GENERAL CAC
 Action Desc: NO ACTION REQUIRED; INFORMATION ONLY
 Comments: CUSTOMER SAYS: ***FIRE*** -THE VEH CAUGHT O
 N FIRE, COMES FROM THE CELENOID-UNDER THE HOOD-BELEVES IT HA
 S TO DO WITH THE PRESSURE SENSOR FOR THE ABS -CUST SAYS TH
 IS HAPPENED DEC 6, 1998 AT 6:20PM -NO FIRE DEPT CONTACT AS
 CUST ABLE TO PUT OUT THE FIRE, -INSURANCE CO. NOT YET CONT
 ACTED PER CUSTOMER, DEALER SAYS: NONE CAC ADVISED: - TH
 F1-Help F2-AddAction F4-PrevAction F5-NextAction F6-ActionData
 F9-PrevComments F10-NextComments F11-Menu F12-Return F13-ESP
 MORE COMMENTS AVAILABLE

LPRKL10

(#27 in spreadsheet)

Call immediately!

3/4/99
 called and
 spoke to son
 call again
 3/5/99

called customer
 3-5 busy
 called
 5-8 N/A
 called
 3-10-99
 reached him
 (best time call: eve)
 3/11/99 called - no answer

3713 4474

need to
contact
Mr. Redieux
again!

Where is
the vehicle?

need to
call PM.

Case #7

1992-95 Town Car/Crown Vic/Grand Marquis Under hood Fire Questionnaire

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Customer Information

Model Year: 92 Make: TOWN CAR VIN: 1LNLH6ZWHNY Mileage: 48,000
 Do you still own the vehicle? NO If not, do you know where it is? INSURANCE COMPANY
 Customer Name: [REDACTED] Phone: [REDACTED]
 Address: [REDACTED] Merritt Island, FL [REDACTED]
 Did a dealer inspect your vehicle? NO If yes, name of the dealer ISLAND L-M
 Was the vehicle involved in a natural disaster and as a result, destroyed? NO
 If yes, where was the clean-up of the incident performed? ---
 What is the repair history of the vehicle? ---
NO

Insurance Agency Information (If pertinent)

Insurance agency name: Nationwide Insurance
 Insurance agent address: Mr. Filichia
 Phone number: 407-453-3480
 Other: claim # Courtney Penny, Merritt Island, FL
 Incident info: home 7709 HO271921 claims dept # 1800 421-3535
auto 7709H 611222 Kelly Van Vliet Rep 888-281-4671
 Where did the fire start? Engine compartment? Yes Specific location/component? -very hard to tell

Incident occurred
2-15-98

Was the vehicle:
 Engine on? --- Engine off? Yes If off, how long was it off? 15-20 minutes
 - If on, how long was it on? ---

Moving? ---
 Parked? --- If parked, where was the vehicle parked? (street, garage or carport) garage

Did customer notice anything unusual prior to fire, such as:

Difficulty shifting out of park? NO
 Speed control not working? NO
 Brake warning lamp illuminated? NO
 Battery not holding a charge? NO
 Fuses blowing? NO
 Stop lamp inoperative? NO
 Other? --- (Smoke right before fire)

- insurance only covered a few damages
 - Vehicle blew up
 - giant hole in hood.

Did you inspect the vehicle? Yes

If yes, Did you find any of the following:

Any underhood relays show evidence of overheat? not sure

Were the underhood fuse links blown? not sure - vehicle was charred

Were there any fuses that were blown or show evidence of other damage? not sure

What areas of the vehicle were damaged? ENTIRE VEHICLE (plus entire garage)
BURNED UP. was ruined)

Was there any damage to any wiring in the area where you believe the fire was started?
not sure

Does the air suspension pump show evidence of overheating? not sure

Was the vehicle equipped with any aftermarket components such as car alarm or remote start?
NO

Was the vehicle repaired? no When? - Where? -

If the vehicle has not been repaired and was involved in an underhood fire or fire of unknown origin that involved the engine compartment, we would like to inspect it.

Would you allow a Ford representative to inspect your vehicle and if necessary, replace some parts?

I need to contact insurance co.

For inspection Parts that we would like from vehicle

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

EDMS II module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay

Other suspect parts

updated 5/16/99

NVNP510

NAVIS Vehicle Inquiry

03/04/99 10:02:06

==>
VEHICLE ID: 1LN7000000 (WVFPBSSSS) VIN: 1LNLM82W4NY DIVT 3 Status: 600
Vehicle Line: CVB Convy Deliv: 120491 Orig P-Lvl: 213 Selling Dlr: 25C023
Order Recpt: 111491 ShipTo Stat: Curr P-Lvl: 213 Sale Date:
Orig Sched: 112591 Rls-To Stat: FL Order Dlr: 25023 Demo Date:
Inv Prep: 111891 Orig Int St: 112791 Orig Rls Dlr: 25023 Deliv Type:
Prod Date: 112591 Curr Int St: 112791 Rls Dlr P&A: 11643 Sales Prd:
Rls Date: 112691 Dirfin Ext: 122591 Warr Start: 122191 Cancel Sl: 120193
Memo Congn: P&C Ext: 122591 Warrs-Ind: Sale Status: B
Orig Pltbus: 112691 Advert Ext: 122591 -Data- -Dealer-
Curr Pltbus: 112691 Slapan SS@:
T/Name:
Addr: State:
City: N/A-Kept:
Zip: Warr-Ins-Ind:
V.O.: 1 2 3 4 5 6 7 8
1234567890123456789012345678901234567890123456789012345678901234
M82NY 4L 2 25L0087 EL 8 P14 3P 4 2 L6L A P 25C023 4 YZ
8 9 0 1 2 3 4 5 6
567890123456789012345678901234567890123456789012345678901234567890
DU H WILNL4 6 D 755A59WP
Fl-Help F3-Exit F4-Primary Menu F5-Financial Screen F9-Screen #3

LPREL10

#9 spreadsheet
onFile
2/15/98
2/27/98

Merritt Island, FL

Case #7

3713 4478

CASE # 8

1992-95 Town Car/Crown Vic/Grand Marquis Under hood Fire Questionnaire

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Customer Information

Model Year: 92 Make: Town Car VIN: 1LNLM81W5N4 Mileage: 70-75,000 miles

Do you still own the vehicle? NO If not, do you know where it is? INSURANCE CO.

Customer Name: [REDACTED] Phone: [REDACTED]

Address: [REDACTED] Somerset, KY [REDACTED]

Did a dealer inspect your vehicle? NO If yes, name of the dealer: ACTON-BLAKELY FORD

Was the vehicle involved in a natural disaster and as a result, destroyed? NO

If yes, where was the clean-up of the incident performed? [REDACTED]

What is the repair history of the vehicle? TRANSMISSION WAS REBUILT
about 1 year prior to fire

Insurance Agency Information (if different)

Insurance agency name: KY FARM BUREAU INSURANCE
Insurance agent address: 150 GENE HURT RD
phone number: 606-679-2360
other: [REDACTED]

claims office
679-4327
Joe Lake

Incident Info

Where did the fire start? Engine compartment? YES Specific location/component? difficult to tell -
large black cloud under hood -
then huge burst of flame.

Was the vehicle:

Engine on? [REDACTED] Engine off? YES If off, how long was it off? 15-30 minutes
- If on, how long was it on? [REDACTED]

Moving? [REDACTED]

Parked? YES If parked, where was the vehicle parked? (street, garage or curbside) parking lot

Did customer notice anything unusual prior to fire, such as:

Difficulty shifting out of park? NO

Speed control not working? NO

Brake warning lamp (illuminated)? NO

Battery not holding a charge? NO

Fuses blowing? NO

Shop lamp inoperative? NO

Other? [REDACTED]

hood area
was all
burnt

Did you inspect the vehicle? _____

If yes, Did you find any of the following:

Any underhood relays show evidence of overheating? NO

Were the underhood fuse links blown? NO

Were there any fuses that were blown or show evidence of other damage? NO

What areas of the vehicle were damaged? Not Sure

Was there any damage to any wiring in the area where you believe the fire was started?
Not Sure

Does the air suspension pump show evidence of overheating? Not Sure

Was the vehicle equipped with any aftermarket components such as car alarm or remote start?
NO

Was the vehicle repaired? Not Sure When? _____ Where? _____

If the vehicle has not been repaired and was involved in an underhood fire or fire of unknown origin that involved the engine compartment, we would like to inspect it.

Would you allow a Ford representative to inspect your vehicle and if necessary, replace some parts?
Yes (insurance agency approval obtained)

For Inspectors: Parts that we would like from vehicle:

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

BDIS 8 module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay

Other suspect parts

updated 3/10/99

NVNP510

NAVIS Vehicle Inquiry

03/04/99 11:30:49

```

==>
VEHICLE ID: 11NY (WYFANRHS) VIN: 11NLM81W5NY DWT 3 Status: 800
Vehicle Line: CVB Convey Deliv: 072792 Orig P-Lvl: 218 Selling Dlr: 25C707
Order Recpt: 040692 ShipTo Stat: Curr P-Lvl: 218 Sale Date: 073192
Orig Sched: 071392 Rls-To Stat: IL Order Dlr: 25707 Demo Date:
Inv Prep: 062592 Orig Int St: 071792 Orig Rls Dlr: 25707 Deliv Type: M
Prod Date: 071692 Curr Int St: 071792 Rls Dlr P&A: 11658 Sales Prd: 092073
Rls Date: 071692 Dirfin Ext: Warr Start: 073192 Cancel Sl:
Memo Consga: PaC Ext: 082592 WarrS-Ind: Sale Status: G
Orig Plthub: 071692 Advert Ext: -Data- -Dealer-
Curr Plthub: 071692 Slapan SS#: Shipped: 071692 88J446
T/Name: g Curr Stock: 071692 25C707
Addr: State: FL 1st-Prior:
City: ORLANDO W/A-Nopt: 073092 2nd-Prior:
Zip: Warr-Ins-Ind: 3rd-Prior:
V.O.: 1 2 3 4 5 6 7 8
12345234567890123456789012345678901234567890123456789012345678901234
MS1NY 43 5613G4089 6D D P1 3P 2GL6L C H J25C707 2 AYZ
8 9 0 1 2 3 4 5 6
567890123456789012345678901234567890123456789012345678901234567890
BB H WILNLS 2 B 2 A751A WP BU007
F1-Help F3-Exit F4-Primary Menu F5-Financial Screen F9-Screen #3

```

LPREL10

#25

Incident
9-29-95



92 TOWN CAR

- Called 3/10/99
- no answer
reached
customer 3/10/99 PM

3713 4481

case #8 Kentucky Farm Bureau Ins.

Case #8 [REDACTED] (customer)

- conversation of 3-11-99 with Joe Lake (claims office)
- the vehicle has not been repaired
- the vehicle was a total loss
- the fire resulted in damage to two other vehicles that were parked nearby when the fire occurred
- there is a lawsuit filed against both the customer and the insurance agency by the parties that suffered damage as a result of the fire
- KY Farm Bureau Insurance Agency attorney's name is Adams and Adams phone number 606-68-4916 — *call AGENCY*
- Ford Motor Company must discuss this with attorney to determine whether permission for inspection will be granted.

*get
correct
phone #*

*- need to call
insurance
- get Attorney phone #
- send note to
Way Logel*

CASE # 4

1992-95 Town Car/Crown Vic/Grand Marquis Under hood Fire Questionnaire

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Customer Information

Model Year: 92 Make: Town Car VIN: 1LPLMSJW5N7 Mileage: _____

Do you still own the vehicle? _____ If not, do you know where it is? no, insurance has it

Customer Name: _____ Phone: _____

Address: _____ Silsbee, TX _____

Did a dealer inspect your vehicle? no If yes, name of the dealer _____

Was the vehicle involved in a natural disaster and as a result, destroyed? no
If yes, where was the clean-up of the incident performed? _____

What is the repair history of the vehicle? no

Insurance Agency Information (if pertinent)

Insurance agency name: Kay Holbyworth
Insurance agent address: 110 H-96 S Silsbee, TX 77656
phone number: 409-981-0868
claim number: _____

Doc White
Claims Dept
Brazosport, TX
409-981-1800
7110763567

Incident Info

Date of Loss: Nov 27, 1998

Where did the fire start? Engine compartment? no Specific location/component?
front left

Was the vehicle:

Engine on? _____ Engine off? ✓ If off, how long was it off? 24 hrs
If on, how long was it on? _____

Moving? _____

Parked? ✓ If parked, where was the vehicle parked? (street, garage or carport) carport

Did customer notice anything unusual prior to fire, such as:

Difficulty shifting out of park? no

Speed control not working? no

Brake warning lamp illuminated? no

Battery not holding a charge? no

Fuses blowing? no

Stop lamp inoperative? no

Other? none

Did you inspect the vehicle? _____

If yes, Did you find any of the following:

Any underhood relays show evidence of overheating? no

Were the underhood fuse links blown? no

Were there any fuses that were blown or show evidence of other damage? no

What areas of the vehicle were damaged? Fender well, wiring, hood

Was there any damage to any wiring in the area where you believe the fire was started?

yes

Does the air suspension pump show evidence of overheating? no

Was the vehicle equipped with any aftermarket components such as car alarm or remote start?

no

Was the vehicle repaired? no When? _____ Where? _____

If the vehicle has not been repaired and was involved in an underhood fire or fire of unknown origin that involved the engine compartment, we would like to inspect it.

Would you allow a Ford representative to inspect your vehicle and if necessary, replace some parts?

yes

For Inspection: Parts that we would like from vehicles:

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

EDIS 4 module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay

Other suspect parts

updated 2/11/99

NVA 3

NAVIS Vehicle Inquiry

03/04/99 11:57:46

VEHICLE ID: 11NY (WNYP88888) VIN: 1LNLM83W5NY DIV: 3 Status: 800
 Vehicle Line: CVR Convy Deliv: 071392 Orig P-Lvl: 218 Selling Dir: 67B162
 Order Recpt: 052592 ShipTo Stat: Curr P-Lvl: 218 Sale Date: 091492
 Orig Sched: 061592 Rls-To Stat: TX Order Dir: 67162 Demo Date:
 Inv Prep: 061292 Orig Int St: 062792 Orig Rls Dir: 67162 Deliv Type: 0
 Prod Date: 061892 Curr Int St: 062792 Rls Dir P&A: 11492 Sales Prd: 092092
 Rls Date: 062692 Dirfin Ext: 072592 Warr Start: 091492 Cancel Sl:
 Memo Consign: 061992 P&C Ext: 072592 Warrs-Ind: Sale Status: G
 Orig Pltbus: 061992 Advert Ext: 072592 -Date- -Dealer-
 Curr Pltbus: 062692 Slapen S&S: 9304 Shipped: 062692
 T/Warrs: 2 Curr Stock: 062692 67B162
 Addr: State: TX 1st-Prior: 061992 67162
 City: AUSTIN N/A-Rcpt: 091792 2nd-Prior:
 Zip: Warr-Ins-Ind: 3rd-Prior:
 V.O.I. 2 3 4 5 6 7 8
 12345234567890123456789012345678901234567890123456789012345678901234
 M83NY 4L 2 15F0345 PE E 8 PLJ 3P854 2 L6L 7 67B162 2 1MD
 567890123456789012345678901234567890123456789012345678901234567890
 FB 5 H WILML5 1 F 760A 9WP
 F1=Help F2=Exit F4=Primary Menu F5=Financial Screen F9=Screen #3

LPREL10

*12

Incident
11-1-98'92 Town
Cam

SILSBEE, TX

Survey taken
 by Lou Federico
 3/11/99.

Called
 3-10-99
 - no msg left

3713 4485

SFCHADMA

Action Detail

03/04/99 11:58:27

VIN: 11NLM83W5NY Year: 1992 Model: TOWN CAR
Owner Status: SUBSEQUENT WSD: 09/14/92
Name: Hm Ph: [REDACTED]
Trmt: Case: 1292553358 Day Ph: [REDACTED]
Symptom Desc:
Reason Desc: LEGAL - INSURANCE COMPANY SETTLEMENT
Dealer:
Issue Type: 02 INFORMATION Issue Status: C CLOSED
Comm Type: PH PHONE Odometer Reading: 56000 MI
Analyst: SALEXA12 STACEY ALEXANDER Document Number:
Action Date: 11/27/98 Action Data: Action Time: 10:21:32 EST
Origin Desc: US CONCERN CASE BASE
Action Desc: ADVISE CUST THAT YOUR INSURANCE COMPANY MAY SUBROGATE
Comments: CUSTOMER SAYS: VEHICLE BURNED UP IN DRIVENWAY, NO ONE WAS HURT;
CONTACTED INSURANCE COMPANY PER CUSTOMER, DEALER SAYS:
NONE CAC ADVISED: - REFER TO INSURANCE COMPANY (INSURANCE CO. HAS THE RIGHT TO SUBROGATE FORD) INFERENCE CASE ID:
22

F1=Help F2=AddAction F4=PrevAction F5=NextAction F6=ActionData
F9=PrevComments F10=NextComments F11=Menu F12=Return F13=ESP
NO MORE COMMENTS AVAILABLE

LPREL10

Case # 21

1992-95 Town Car/Crown Vic/Grand Marquis Under hood Fire Questionnaire

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Customer Information

Model Year: 92 Make: Town Car VIN#: _____ Mileage: 70

Do you still own the vehicle? No If not, do you know where it is? _____

Customer Name: _____ Phone: _____

Address: _____

Did a dealer inspect your vehicle? No If yes, name of the dealer _____

Was the vehicle involved in a natural disaster and as a result, destroyed? No

If yes, where was the clean-up of the incident performed? _____

What is the repair history of the vehicle? transmission, brake switch problem
went out

Insurance Agency Information (if pertinent)

Insurance agency name: Quincy Scott

Insurance agent address: Walden, ME

phone number: _____

claim number: _____

Incident Info

Date of Loss: best know

Where did the fire start? Engine compartment? _____ Specific location/component?
driver's passenger, under the hood - leak in gas line manifold

Was the vehicle:

Engine on? _____ Engine off? ☒ If off, how long was it off? 45 min

If on, how long was it on? _____

Moving? _____

Parked? ☒ If parked, where was the vehicle parked? (street, garage or airport) _____

Did customer notice anything unusual prior to fire, such as:

Difficulty shifting out of park? _____

Speed control not working? _____

Brake warning lamp illuminated? _____

Battery not holding a charge? _____

Fume blowing? _____

Stop lamp inoperative? _____

Other? None

Did you inspect the vehicle? yes

If yes, Did you find any of the following:

Any underhood relays show evidence of overheating? no

Were the underhood fuse links blown? no

Were there any fuses that were blown or show evidence of other damage? no

What areas of the vehicle were damaged? front all way to back inside & outside

Was there any damage to any wiring in the area where you believe the fire was started?

don't know

Does the air suspension pump show evidence of overheating? don't know

Was the vehicle equipped with any aftermarket components such as car alarm or remote start?

no

Was the vehicle repaired? was totaled When? _____ Where? _____

If the vehicle has not been repaired and was involved in an underhood fire or fire of unknown origin that involved the engine compartment, we would like to inspect it.

Would you allow a Ford representative to inspect your vehicle and if necessary, replace some parts?

vehicle not in possession anymore

For Inspectors: Parts that we would like from vehicles

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

EDIS 3 module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay

Other suspect parts

updated 3/11/99

SFCH2VMA

Vehicle List

03/11/99 17:29:25

==>

Name:

Address:

Address:

City: DALLAS

Zip/Postal: [REDACTED]

Home Phone: [REDACTED]

Day Phone:

State/Prov: TX

Country: USA

A	VIN/	Year	Model/	Sale Type/
C	Owner Status		Previous Owner	Open Issues
-	1LNLN81W4PY [REDACTED]	1993	TOWN CAR	Individual Rtl
	SUBSEQUENT			

F1=Help

F2=IssueList

F5=AddIssue

F7=Prev

F8=Next F9=ESP

F10=WarnHistory

F11=Menu

F12=Return

F13=Recall/ONP

F14=SpecialCoverage

NO MORE RECORDS AVAILABLE

LPREL10

#46
on
spread sheetDate of Incident
5-8-97

3-18-99 spoke with cust 6:20/11/99

3713 4489

NVMP510

NAVIS Vehicle Inquiry

03/11/99 17:28:47

```

=>
VEHICLE ID: 11NY (WVTPANNNNN) VIN: 11N1M81N8NY DIVT 3 Status: 800
Vehicle Line: CVB Convey Deliv: 042292 Orig F-Lvl: 218 Selling Dlr: 67B725
Order Recpt: 030992 ShipTo Stat: Curr F-Lvl: 218 Sale Date: 042192
Orig Sched: 033092 Els-To Stat: IL Order Dlr: 67725 Demo Date:
Inv Prep: 032692 Orig Int St: 040792 Orig Els Dlr: 67725 Deliv Type: M
Prod Date: 040292 Curr Int St: 040792 Els Dlr P&A: 11493 Sales Prd: 092042
Els Date: 040692 Dirfin Ext: Warr Start: 042192 Cancel Sl:
Memo Conseg: PAC Ext: 051092 Warrs-Ind: Sale Status: G
Orig Pltbus: 040692 Advert Ext: -Date- -Dealer-
Curr Pltbus: 040692 Elapen SS#: Shipped: 040692 88R207
T/Name: 9 Curr Stock: 040692 67B725
Addr: State: TX 1st-Prior:
City: HOUSTON N/A-Recpt: 042092 2nd-Prior:
Zip: Warr-Ins-Ind: 3rd-Prior:
V.O.:1 2 3 4 5 6 7 8
12345234567890123456789012345678901234567890123456789012345678901234
MS1NY 43 5630C1298 1 9C D P1 3P 2GL6L C P J67B725 1 AYG
8 9 0 1 2 3 4 5 6
567890123456789012345678901234567890123456789012345678901234567890
BI H W11N18 0 B 2 A751A WP BU011
F1-Help F3-Exit F4-Primary Menu F5-Financial Screen F9-Screen #3
  
```

LPREL10

Case # 10

1992-95 Town Car/Crown Vic/Grand Marquis Under hood Fire Questionnaire

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Customer Information

Model Year: 92 Make: Town Car VIN: 1LNLM8W3N Mileage: 60,000

Do you still own the vehicle? no If not, do you know where it is? in storage by the Ins CO.

Customer Name: [redacted] Phone: [redacted]

Address: [redacted] Port S. Lucie

Did a dealer inspect your vehicle? no If yes, name of the dealer _____

Was the vehicle involved in a natural disaster and as a result, destroyed? no

If yes, where was the clean-up of the incident performed? _____

What is the repair history of the vehicle? only Routine Work

Insurance Agency Information (if pertinent)

Insurance agency name: State Farm
Insurance agent address: Ben + Mary Field 10610 South US Hwy 1 Port S Lucie
phone number: 385-4014 (561)
claim number: 59-8107-840

claim # 1: 8013 -
(561) 489-2800

Incident Info

Date of Loss: 12-30-97 House Clamett Do to the House. Fire spread from garage.

Where did the fire start? Engine compartment? _____ Specific location/component? under the hood over the LF tier

Was the vehicle:

Engine on? _____ Engine off? ☒ If off, how long was it off? 2 hours
If on, how long was it on? _____

Moving? _____

Parked? ☒ If parked, where was the vehicle parked? (street, garage or carport) garage

Did customer notice anything unusual prior to fire, such as:

Difficulty shifting out of park? _____

Speed control not working? _____

Brake warning lamp illuminated? _____

Battery not holding a charge? _____

Fuses blowing? _____

Stop lamp inoperative? _____

Other? NO problems with vehicle

Customer Just Drove 546 mi
Pr to issue - of within 2 hour's

Did you inspect the vehicle? total Burn Just a shell of the vehicle,

If yes, Did you find any of the following:

Any underhood relays show evidence of overheating? melted

Were the underhood fuse links blown? melted

Were there any fuses that were blown or show evidence of other damage? no

What areas of the vehicle were damaged? all

Was there any damage to any wiring in the area where you believe the fire was started?
no

Does the air suspension pump show evidence of overheating? no

Was the vehicle equipped with any aftermarket components such as car alarm or remote start?

Don't know total

Was the vehicle repaired? no When? _____ Where? _____

If the vehicle has not been repaired and was involved in an underhood fire or fire of unknown origin that involved the engine compartment, we would like to inspect it.

Would you allow a Ford representative to inspect your vehicle and if necessary, replace some parts?

For inspection: Parts that we would like from vehicles

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

EDIS 8 module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay

Other suspect parts

updated 3/11/99

NVNP510

NAVIS Vehicle Inquiry

03/04/99 12:19:22

VEHICLE ID: 1LNY (WVFPSEHSEH) VIN: 1LW1MS1W3NY Div: 3 Status: 800
 Vehicle Line: CVB Convy Deliv: 081292 Orig P-Lvl: 218 Selling Dlr: 25C160
 Order Reopt: 062392 ShipTo Stat: Curr P-Lvl: 218 Sale Date: 100992
 Orig Sched: 072792 Rls-To Stat: FL Order Dlr: 25160 Demo Date:
 Inv Prep: 072292 Orig Int St: 080192 Orig Rls Dlr: 25160 Deliv Type: 0
 Prod Date: 073192 Curr Int St: 080192 Rls Dlr PAA: 11608 Sales Prd: 092101
 Rls Date: 073192 Dlrfin Ext: 082592 Warr Start: 100992 Cancel S1:
 Memo Consign: P&C Ext: 082592 Warrs-Ind: Sale Status: G
 Orig Pltbus: 073192 Advert Ext: 082592 -Date- -Dealer-
 Curr Pltbus: 073192 Sleepn S28: 9236 Shipped: 073192
 T/Name: 1 Curr Stock: 073192 25C160
 Addr: State: FL 1st-Prior:
 City: STUART H/A-Reopt: 101392 2nd-Prior:
 Zip: Warr-Ins-Ind: 3rd-Prior:
 V.O.: 1 2 3 4 5 6 7 8
 1234567890123456789012345678901234567890123456789012345678901234
 MS1NY 4L 2 27G5015 WF 8 P14 3P 3 L6L P 25C160 2 Y2
 8 9 0 1 2 3 4 5 6
 567890123456789012345678901234567890123456789012345678901234567890
 BU H WILML3 5 B 751A59WP
 F1=Help F3=Exit F4=Primary Menu F5=Financial Screen F9=Screen #3

LPREL10

[REDACTED]
 Port St. Lucie FL [REDACTED]
 [REDACTED]

SURVEY TAKEN BY
 TAMMY BURBO
 called - 3-11-99

3713 4493

Case # 11

1992-95 Town Car/Crown Vic/Grand Marquis Under hood Fire Questionnaire

We are contacting you, because you reported smoke or fire in your vehicle. Ford is investigating your report and would like to ask you some questions about it. We hope everyone was ok...

Vehicle/Customer Information

Model Year: 92 Make: Town Car VIN: 3LNLM83W9NY Mileage: 67,694

Do you still own the vehicle? NO If not, do you know where it is? NO, sold to Salvage yard

Customer Name: [REDACTED] Phone: [REDACTED]

Address: [REDACTED]

Did a dealer inspect your vehicle? Yes If yes, name of the dealer Delta Chevy

Was the vehicle involved in a natural disaster and as a result, destroyed? no

If yes, where was the clean-up of the incident performed? no

What is the repair history of the vehicle? NO, second owner

Insurance Agency Information (If pertinent)

Insurance agency name: Farm Bureau Ins. Co.

Insurance agent address: [REDACTED]

phone number: 860-237-6344

claim number: 10642745

Incident Info

Date of Loss: April 30, 1998

Where did the fire start? Engine compartment? Yes Specific location/component? [REDACTED]

Was the vehicle:
Engine on? Engine off? ✓ If off, how long was it off? 7-10 min
If on, how long was it on?

Moving?
Parked? ✓ If parked, where was the vehicle parked? (street, garage or curpark) Parking lot

Did customer notice anything unusual prior to fire, such as:

Difficulty shifting out of park? no

Speed control not working? no

Brake warning lamp illuminated? no

Battery not holding a charge? no

Fuses blowing? no

Stop lamp inoperative? no

Other?

***UNABLE
TO LOCATE
VEHICLE -**

Customer sold
it to a Salvage
yard - but does
not have any info
about the facility

Did you inspect the vehicle? Yes

If yes, Did you find any of the following:

Any underhood relays show evidence of overheating? Yes

Were the underhood fuse links blown? no

Were there any fuses that were blown or show evidence of other damage? no

What areas of the vehicle were damaged? driver side front, windshield, Head inside Cab

Was there any damage to any wiring in the area where you believe the fire was started?

wire harness under hood drivers side

Does the air suspension pump show evidence of overheating? no

Was the vehicle equipped with any aftermarket components such as car alarm or remote start?

no

Was the vehicle repaired? no When? _____ Where? _____

If the vehicle has not been repaired and was involved in an underhood fire or fire of unknown origin that involved the engine compartment, we would like to inspect it.

Would you allow a Ford representative to inspect your vehicle and if necessary, replace some parts?

Yes

For Inspectors: Parts that we would like from vehicles

Brake pressure switch (preferably with wire pigtail/connector attached and still attached to prop valve)

Sample of brake fluid at prop valve (in sealed glass container)

Relay pack located on LH fender apron (with as much wiring as possible)

EDIS 8 module located on LH fender

Speed control module located on LH fender

Air suspension compressor located under air filter

Air suspension relay

Other suspect parts

updated 3/11/99

SFCHDMA

Issue Detail

03/04/99 12:22:33

VIN: 1LNLM83W9NY Year: 1992 Model: TOWN CAR
Owner Status: SUBSEQUENT WSD: 08/14/92 Mileage: 67694
Name: Hm Ph: [REDACTED]
Trmt: Case: 1487171248 Day Ph: [REDACTED]
Symptom: FIRE/SMOKE VISIBLE FLAME UNDERHOOD
Reason: LEGAL - REFER TO INSURANCE COMPANY
Dealer: TOM WIMBERLEY AUTO WORLD INC
Issue Type: 02 INFORMATION CAN Court: Legal Issue Type:
Issue Status: C CLOSED CAN Award: MORSI Contact: Y

A/C DATE Origin Description

x 05/04/98 CAC NO ACTION REQUIRED; INFORMATION ONLY
05/04/98 CACI38 ADVISE CUSTOMER TO CONTACT THEIR INSURANCE COMPANY FOR ASSIS

F1=Help F2=AddAction F4=ActionDetail F6=DealerInfo
F7=Prev F8=Next F9=ViewMORSII F11=Menu F12=Return
NO MORE RECORDS AVAILABLE LPREL10

#26

792 TOWN
CAR

Greenwood, MS

SFCHADMA

Action Detail

03/04/99 12:22:43

VIN: 1LNLM83W9NY Year: 1992 Model: TOWN CAR
Owner Status: SUBSEQUENT WSD: 08/14/92
Name: Hm Ph: [REDACTED]
Trmt: Case: 1487171248 Day Ph: [REDACTED]
Symptom Desc: FIRE/SMOKE VISIBLE FLAME UNDERHOOD
Reason Desc: LEGAL - REFER TO INSURANCE COMPANY
Dealer: TOM WIMBERLEY AUTO WORLD INC
Issue Type: 02 INFORMATION Issue Status: C CLOSED
Comm Type: PH PHONE Odometer Reading: 67694 MI
Analyst: YFERNAND YVONNE FERNANDEZ Document Number:
Action Date: 05/04/98 Action Data: Action Time: 13:30:49 EST
Origin Desc: GENERAL CAC
Action Desc: NO ACTION REQUIRED; INFORMATION ONLY
Comments: CUSTOMER SAYS: CUST'S VEHICLE CAUGHT ON FIRE ON APRIL 30,
1998 IN THE PARKING LOT OF THE GROCERY STORE. CUST WAS NOT
IN THE CAR. NO ONE WAS HURT. FIRE DEPARTMENT WAS CALLED TO
PUT FIRE OUT. FIRE MARSHALL SAID THAT IT WAS AN ELECTRICAL
FIRE IN WIRING HARNESS IN THE ENGINE COMPARTMENT. FIRE MARS
HALLS NAME IS TERRY RICKS FROM GREENWOOD FIRE DEPARTMENT. C

F1=Help F2=AddAction F4=PrevAction F5=NextAction F6=ActionData
F9=PrevComments F10=NextComments F11=Menu F12=Return F13=ESP
MORE COMMENTS AVAILABLE

LPREL10

SFCHADMA

Action Detail

03/04/99 12:23:06

==>

VIN: 1LWLM83W9N4 Year: 1992 Model: TOWN CAR
Owner Status: SUBSEQUENT WSD: 08/14/92
Name: [REDACTED] Em Ph: [REDACTED]
Trmt: Case: 1487171248 Day Ph: [REDACTED]
Symptom Desc: FIRE/SMOKE VISIBLE FLAME UNDERHOOD
Reason Desc: LEGAL - REFER TO INSURANCE COMPANY
Dealer: TOM WIMBERLEY AUTO WORLD INC
Issue Type: 02 INFORMATION Issue Status: C CLOSED
Comm Type: PH PHONE Odometer Reading: 67694 MI
Analyst: YFERNAND YVONNE FERNANDEZ Document Number:
Action Date: 05/04/98 Action Date: Action Time: 13:30:49 EST
Origin Desc: GENERAL CAC
Action Desc: NO ACTION REQUIRED, INFORMATION ONLY
Comments: HALLS NAME IS TERRY RICKS FROM GREENWOOD FIRE DEPARTMENT. C
AR IS AT DELTA CHEVERLOT IN GREENWOOD. CUST FRIENDS TOWED CA
R TO THIS VEHICLE. DAMAGE IS ONLY IN THE ENGINE AND TIRE BL
EW. THE INTERIOR OF THE CAR IS NOT TOUCHED. CUST WANTS CAR
REPAIRED. PER CUSTOMER, DEALER SAYS: CAC ADVISED: - TH
IS IS NOT A SITUATION THAT FMC IS ABLE TO ASSIST YOU WITH.

F1=Help F2=AddAction F4=PrevAction F5=NextAction F6=ActionData
F9=PrevComments F10=NextComments F11=Menu F12=Return F13=ESP
MORE COMMENTS AVAILABLE

LPREL10

3PCHADMA

Action Detail

03/04/99 12:23:20

==>

VIN: 1LNLM83W9NY Year: 1992 Model: TOWN CAR
Owner Status: SUBSEQUENT WSD: 08/14/92
Name: Hm Ph:
Trmt: Case: 1487171248 Day Ph:
Symptom Desc: FIRE/SMOKE VISIBLE FLAME UNDERHOOD
Reason Desc: LEGAL - REFER TO INSURANCE COMPANY
Dealer: TOM WIMBERLEY AUTO WORLD INC
Issue Type: 02 INFORMATION Issue Status: C CLOSED
Comm Type: PH PHONE Odometer Reading: 67694 MI
Analyst: YFERNAND YVONNE FERNANDEZ Document Number:
Action Date: 05/04/98 Action Data: Action Time: 13:30:49 EST
Origin Desc: GENERAL CAC
Action Desc: NO ACTION REQUIRED; INFORMATION ONLY
Comments: IS IS NOT A SITUATION THAT FMC IS ABLE TO ASSIST YOU WITH.
PLEASE CONTACT YOUR INSURANCE CARRIER FOR DIRECTIONS. INFERE
NCE CASE ID: 79

F1-Help F2-AddAction F4-PrevAction F5-NextAction F6-ActionData
F9-PrevComments F10-NextComments F11-Menu F12-Return F13-ESP
NO MORE COMMENTS AVAILABLE

LPREL10

NAVIS Vehicle Inquiry

Wings

```

VEHICLE ID: 1LN7 (WVWYK3B388) VIN: 1LNLM83W9NY Div: 3 Status: 800
Vehicle Line: CVB Convoy Deliv: 070692 Orig P-Lvl: 218 Selling Dir: 22A621
Order Recpt: 052192 ShipTo Stat: Curr P-Lvl: 218 Sale Date: 081492
Orig Sched: 061592 Rls-To Stat: MS Order Dlr: 22621 Demo Date:
Inv Prep: 061892 Orig Int St: 062792 Orig Rls Dlr: 22621 Deliv Type: 0
Prod Date: 062592 Curr Int St: 062792 Rls Dlr P&A: 12211 Sales Prd: 092082
Rls Date: 062692 Dirfin Ext: 072592 Warr Start: 081492 Cancel Sl:
Memo Consgn: P&C Ext: 072592 WarrS-Ind: Sale Status: G
Orig Plthum: 062692 Advert Ext: 072592 -Date- -Dealer-
Curr Plthum: 062692 Shipped: 062692
T/Name: 8946 Curr Stock: 062692 22A621
Addr: State: MS 1st-Prior:
City: JACKSON W/A-Mopt: 081892 2nd-Prior:
Zip: Warr-Ins-Ind: 3rd-Prior:
V.O.: 1 2 3 4 5 6 7 8
123452345678901234567890123456789012345678901234567890123456789012345678901234
M83NY 45 2 15F1131 LE E P1J 3P 4 2 L6L A 22A621 2 MD
8 9 0 1 2 3 4 5 6
5678901234567890123456789012345678901234567890123456789012345678901234567890
FB 5 H W1LNLS 2 F 760A WP
Fl-Help F3-Exit F4=Primary Menu F5=Financial Screen F9=Screen #3

```

LPREL10

NVMP510

NAVIS Vehicle Inquiry Case # 03/04/99 12:38:44

VEHICLE ID: 11NY (WV1P888888) VIN: 1LNLM81W9NY DIV: 3 Status: 800
 Vehicle Line: CVB Convy Deliv: 070392 Orig F-Lvl: 218 Selling Dlr: 67B725
 Order Recpt: 040192 ShipTo Stat: Curr F-Lvl: 218 Sale Date: 071192
 Orig Sched: 061592 Rls-To Stat: IL Order Dlr: 67725 Demo Date:
 Inv Prep: 051892 Orig Int St: 062792 Orig Rls Dlr: 67725 Deliv Type: M
 Prod Date: 062592 Curr Int St: 062792 Rls Dlr P&A: 11493 Sales Prd: 092071
 Rls Date: 062692 Dirfin Ext: Warr Start: 071192 Cancel S1:
 Memo Consign: P&C Ext: 072592 Warr#-Ind: Sale Status: G
 Orig Pltbus: 062692 Advert Ext: -Date- -Dealer-
 Curr Pltbus: 062692 Slespr S&S: Shipped: 062692 88R240
 T/Name: 9 Curr Stock: 062692 67B725
 Addr: State: TX 1st-Prior:
 City: GRAPEVINE N/A-Rept: 071292 2nd-Prior:
 Zip: Warr-Ins-Ind: 3rd-Prior:
 V.O.: 1 2 3 4 5 6 7 8
 12345234567890123456789012345678901234567890123456789012345678901234
 M81NY 43 5615F1913 1D D P1 3P 2GL6L C P J67B725 2 AY2
 8 9 0 1 2 3 4 5 6
 567890123456789012345678901234567890123456789012345678901234567890
 BT H WILNL9 2 B 2 A751A WP BU002
 F1-Help F3-Exit F4-Primary Menu F5-Financial Screen F9-Screen 93

LPREL10

38

[REDACTED]

Westlake, LA

'92
Towncar

[REDACTED]

- Unable to locate
Customer
- Phone # non-
published.

THOMMY BURRO

Not LISTED Phone AD.
3-11-99 # unpublished:

3713 4501